



# Incident History Database IHDB

SAR Controllers Training 2013  
19 – 21 March 2013

Beth Creamer  
Science Systems and Applications, Inc.  
Senior USMCC Controller





---

# What is the IHDB?



# Incident History Database (IHDB)

---

- New accounts need to come through:
  - For AFRCC/AKRCC
    - Dan Conley, AFRCC SAR Duty Officer
      - Danny.Conley@tyndall.af.mil
  - For USCG
    - CDR Mark Turner, SARSAT Liaison Officer
      - Mark.W.Turner@uscg.mil
- Passwords can be reset by the USMCC Controller



# Why did that beacon activate?

---

- Data Entries
  - Checked for consistency
  - Reported to NOAA Daily, Weekly, Quarterly and Annually
  - A significant part of annual report to Cospas-Sarsat
  - Used by USCG and Air Force for Reporting
  - Used in research continuously
    - Beacon reliability – Reported to Beacon Manufacturer's Workshop
    - Repeat Offenders data
    - Many, many, more

# Parts of Record

## View Record #330902

### Primary/Defining Data

Site Number 59425  
Beacon/Site ID 2DCE72056CFFBFF  
Time First Detected 2013-02-21 23:16:00.000  
Record Status Completed

Frequency Type 406 MHz  
Site Status (when closed) Composite  
SRRs Sent Feedback Report PACAREA AFRCC  
SRR Name (when site closed) AFRCC [366S]

### Feedback Information

#### USMCC Upward Site/Beacon ID Reference

If this incident is correlated with another, simply enter the master site number and click update

Case Number 1310873

Time Case Started 2013-02-21 23:19:00.000

General Location California

Actual Latitude (no data)

Actual Longitude (no data)

How Actual Location Estimated

#### Incident Outcome

Distress  Non-Distress  Ceased/Undetermined  Linked Site  
 (Unassigned)

#### Incident Type

Aviation  Maritime  Terrestrial  Other or Unknown

#### Was SARSAT Data used in the resolution of this case?

Yes - Only Notification  Yes - First Notification  Yes - Supporting Data  Not Involved  (Unassigned)

#### Number Rescued

Number In Distress

#### [Examples of Operational False Alerts](#)

Reason Activated False Alert - Beacon Mishandling: Usage

#### Activation Comment

Boat Hours

Cutter Hours

CAP Ground Hours

Helo Hours

Fixed Wing Hours

CAP Air Hours

#### Additional Remarks

PLB WAS LOCATED AND SILENCED BY REGISTERED OWNER BEACON WAS ACTIVATED DUE TO ACCIDENTAL ACTIVATION Result: NON-DISTRESS Location: PALO ALTO, CALIFORNIA Current beacon registration is incorrect. A POC for this beacon's registration (ED) can be reached at 210-710-8148.

**Additional Remarks** PLB WAS LOCATED AND SILENCED BY REGISTERED OWNER BEACON WAS ACTIVATED DUE TO ACCIDENTAL ACTIVATION Result: NON-DISTRESS Location: PALO ALTO, CALIFORNIA Current beacon registration is incorrect. A POC for this beacon's registration (ED ) can be reached at 210-710-8148.

### Beacon Information

**General Type** PLB  
**Protocol Type** PLB SERIAL (STANDARD)  
**Country Code** USA  
**Beacon Activation Type**  
**Location Protocol Beacon**  Yes  No

**Manufacturer**  
**Beacon Model**  
**Homing Device** 121.5 MHz  
**Beacon Registered**  Yes  No

### Site Data

**First Alert ALat** 33-30-29N  
**First Alert ALon** 140-10-41W  
**First Alert ASRR** PACAREA [366F]

**First Alert BLat** 37-25-59N  
**First Alert BLon** 122-09-25W  
**First Alert BSRR** AFRCC [366S]

**First Encoded Lat** 37-30-00N  
**First Encoded Lon** 122-15-00W  
**Time First Encoded** 2013-02-21 23:18:00.000  
**Time First Encoded U**  
**Encoded SRR** AFRCC [366S]

**First Composite Lat** 37-25-59N  
**First Composite Lon** 122-08-31W  
**Last Composite Lat** 37-25-59N  
**Last Composite Lon** 122-08-31W  
**Composite SRR** PACAREA [366F]

**Site Opened** 2013-02-21 23:18:00.000  
**First Composite Time** 2013-02-21 23:40:00.000

**Site Closed** 2013-02-22 02:11:00.000  
**Last Detected** 2013-02-21 23:36:00.000

**Frequency** 406.0367  
**Number of Passes** 4

**Time First Geo** 2013-02-21 23:16:00.000  
**Time First Leo** 2013-02-21 23:18:00.000

**Beacon Special Status** Normal

**Incident Data Last Updated** 2013-02-22 02:24:29.143

\*\*\*\*\* For NOAA System Managers and Data Managers Use Only \*\*\*\*\*

**Public Release Info**

PREV **DONE** NEXT

## View Record #329699

### Primary/Defining Data

**Site Number** 55263  
**Beacon/Site ID** 2DD42AC9BF81FE0  
**Time First Detected** 2013-01-01 17:15:00.000  
**Record Status** Completed

**Frequency Type** 406 MHz  
**Site Status (when closed)** Position Conflict  
**SRRs Sent Feedback Report** CGD01 CGD07 CGD05  
**SRR Name (when site closed)** CGD05 [386N]

### Feedback Information

#### USMCC Upward Site/Beacon ID Reference

If this incident is correlated with another, simply enter the master site number and click update

**Case Number** 623857

**Time Case Started** 2013-01-01 17:15:00.000

**General Location** South Carolina

**Actual Latitude** (no data)

**Actual Longitude** (no data)

**How Actual Location Estimated**

#### Incident Outcome

Distress   
  Non-Distress   
  Ceased/Undetermined   
  Linked Site  
 (Unassigned)

#### Incident Type

Aviation   
  Maritime   
  Terrestrial   
  Other or Unknown

#### Registration Information Usage

Not Used   
  Contributed to case resolution   
  Primary Means to resolve case   
  (Unassigned)

#### Was SARSAT Data used in the resolution of this case?

Yes - Only Notification   
  Yes - First Notification   
  Yes - Supporting Data   
  Not Involved   
  (Unassigned)

#### \*Registration Accuracy

##### Owner Information

Accurate   
  Not Accurate   
  Unverified

##### Emergency Contact Information

Accurate   
  Not Accurate   
  Unverified

##### Vessel/Aircraft Usage Information

Accurate   
  Not Accurate   
  Unverified

**Number Rescued** 0

**Number In Distress** 0



#### Examples of Operational False Alerts

**Reason Activated** False Alert - Beacon Mishandling: Usage

**Boat Hours** 0.0

**Cutter Hours** 0.0

**CAP Ground Hours** 0.0

#### Activation Comment

**Helo Hours** 0.0

**Fixed Wing Hours** 0.0

**CAP Air Hours** 0.0

#### Additional Remarks

D7CC received a 406MHZ EPIRB registered to the F/V CRYSTAL C with no positional information. D7CC contacted the registered owner who confirmed his F/V was safely moored at Little River Fish Camp. Then he stated he had just destroyed the beacon with a sledgehammer because he couldn't get it to deactivate after being removed from it's bracket. Beacon later composited with a 50/50 split with D7 in the buffer for the "A" solution, which plotted IVO where the beacon had been destroyed later compositing on shore. The registered owner was unable to confirm the beacon I.D. due the beacon being destroyed. D7 will monitored the site with no further updates and contacted the owner once more to attempt to confirm the beacon was the same. The owner then confirmed the beacon ID. Case closed.

## EXAMPLES OF OPERATIONAL FALSE ALERTS

### BEACON MISHANDLING

[False Alert - Mishandling - Installation](#)

[False Alert - Mishandling - Testing](#)

[False Alert - Mishandling - Usage](#)

[False Alert - Mishandling - Disposal](#)

### BEACON MALFUNCTION

[False Alert - Malfunction - Switch](#)

[False Alert - Malfunction - Water Intrusion](#)

[False Alert - Malfunction - Test](#)

[False Alert - Malfunction - Electronics](#)

### MOUNTING FAILURE

[False Alert - Mounting - Bracket](#)

[False Alert - Mounting - Release](#)

[False Alert - Mounting - Magnet](#)

### ENVIRONMENTAL CONDITIONS

[False Alert - Environmental Conditions](#)

### UNKNOWN

[False Alert - Reasons Unknown](#)

## BEACON MISHANDLING

### False Alert - Mishandling - Installation

- Exposed to sea action or ship's work, beacon activated by sea spray or wave, crewman bumped beacon, equipment struck beacon, beacon installed upside down, improperly placing beacon into bracket

### False Alert - Mishandling - Testing

- Failure to follow proper testing procedures, negligence, poor beacon testing instructions, aircraft in situ test, left beacon in "on" position too long. Inspection by authorised inspector: accidental activation during vessel equipment inspection.
- Repair by owner (usually unauthorised) or authorised facility: causing damage to beacon, activation during battery change, changing of hydrostatic release while servicing beacon.
- Improper removal from bracket: inspection, test, cleaning, or safe keeping without switching off.
- Beacon shipped to / by retailer, owner, repair facility (in transit): shipped while armed, improperly packed, improperly marked, rough handling.
- Maintenance of craft: mechanical, electronic, wash down, painting, winterization.
- Beacon stored improperly: stored while armed.

### False Alert - Mishandling - Usage

- Illegal activation: hoax, vandalism, theft.
- Accidental activation: owner or SAR authorities report accidental activation and no further information.
- Demonstration / test not co-ordinated with Cospas-Sarsat / SAR authorities: training, exercise, product demonstration using on position instead of test.

### False Alert - Mishandling - Disposal

- Beacon sold with craft for scrap, discarded as trash, abandoned.

## BEACON MALFUNCTION

### False Alert - Malfunction - Switch

- Faulty activation switch, i.e., gravity activated, magnetic, mercury, or crash.
- Hard landing, excessive craft vibration.

### False Alert - Malfunction - Water Intrusion

- Water leakage due to manufacturing defect, cracked casing, faulty seal.

## EXAMPLES OF OPERATIONAL FALSE ALERTS

### BEACON MISHANDLING

[False Alert - Mishandling - Installation](#)

[False Alert - Mishandling - Testing](#)

[False Alert - Mishandling - Usage](#)

[False Alert - Mishandling - Disposal](#)

### BEACON MALFUNCTION

[False Alert - Malfunction - Switch](#)

[False Alert - Malfunction - Water Intrusion](#)

[False Alert - Malfunction - Test](#)

[False Alert - Malfunction - Electronics](#)

### MOUNTING FAILURE

[False Alert - Mounting - Bracket](#)

[False Alert - Mounting - Release](#)

[False Alert - Mounting - Magnet](#)

### ENVIRONMENTAL CONDITIONS

[False Alert - Environmental Conditions](#)

### UNKNOWN

[False Alert – Reasons Unknown](#)

- Hard landing, excessive craft vibration.

#### **False Alert - Malfunction - Water Intrusion**

- Water leakage due to manufacturing defect, cracked casing, faulty seal.

#### **False Alert - Malfunction - Test**

- Transmitting distress signal while in test position
- Transmitted non-inverted frame sync while in test mode (406 MHz).

#### **False Alert - Malfunction - Electronics**

- Electronics malfunction
- Non-GPS electronics malfunction.

## **MOUNTING FAILURE**

#### **FalseAlert-Mounting-Bracket**

- Strap or bracket failure
- Strap failure, mounting bolts sheared, retainer pin broken, beacon fell out of bracket.

#### **FalseAlert-Mounting-Release**

- Hydrostatic release failure.

#### **FalseAlert-Mounting-Magnet**

- Faulty mounting magnet for externally mounted ELT
- Switch magnets not effective.

## **ENVIRONMENTAL CONDITIONS**

#### **False Alert - Environmental Conditions**

- Extreme weather conditions
- Hurricane / cyclone conditions, vessel knocked down, aircraft overturned, heavy seas, ice build-up.

## **UNKNOWN**

#### **False Alert – Reasons Unknown**

- (Confirmed Beacon Activations)
- No feedback received on why beacon activated
- Investigation into beacon activation cause was inconclusive



# IHDB False Alert Reason

---

- Beacon Mishandling
- Beacon Malfunction
- Mounting Failure
- Environmental Conditions
- Unknown



# IHDB False Alert Reason

---

- False Alert – Mishandling – Installation
  - Exposed to sea action or ship's work, equipment struck beacon, **improperly placing beacon in bracket**



# IHDB False Alert Reason

---

- Beacon Mishandling
  - False Alert – Mishandling – Installation
  - False Alert – Mishandling – Testing
    - Failure to follow proper testing procedures
    - Repair by owner or service center causing activation.
    - Improper removal from bracket while testing, cleaning.
    - Beacon shipped while armed and activated
    - Beacon stored improperly



# IHDB False Alert Reason

---

- Beacon Mishandling
  - False Alert – Mishandling – Installation
  - False Alert – Mishandling – Testing
  - False Alert – Usage
    - Illegal activation: hoax, vandalism, theft
    - Accidental activation: reported, NFI
    - Demonstrated / test not coordinated



# IHDB False Alert Reason

---

- Beacon Mishandling
  - False Alert – Mishandling – Installation
  - False Alert – Mishandling – Testing
  - False Alert – Mishandling – Usage
  - False Alert – Mishandling – Disposal
    - Beacon discarded as trash, abandoned



# IHDB False Alert Reason

---

- Beacon Malfunction
  - False Alert – Malfunction – Switch
    - Switch broken



# IHDB False Alert Reason

---

- Beacon Malfunction
  - False Alert – Malfunction – Switch
  - False Alert – Malfunction – Water Intrusion
    - Water leakage due to manufacturing defect, cracked casing, faulty seal.
    - **Not exterior of beacon getting wet**



# IHDB False Alert Reason

---

- Beacon Malfunction
  - False Alert – Malfunction – Switch
  - False Alert – Malfunction – Water Intrusion
  - False Alert – Malfunction – Test
    - Transmitted non-inverted frame
    - Transmitting distress signal while in test position



# IHDB False Alert Reason

---

- Beacon Malfunction
  - False Alert – Malfunction – Switch
  - False Alert – Malfunction – Water Intrusion
  - False Alert – Malfunction – Test
  - False Alert – Malfunction – Electronics
    - Electronics malfunction
    - Non-GPS electronics malfunction



# IHDB False Alert Reason

---

- Mounting Failure

67% Of False Alerts Mounting Failure



# IHDB False Alert Reason

---

- Mounting Failure
  - False Alert – Mounting – Bracket
    - Strap or bracket failure
    - Beacon fell out of bracket

\*\*Yarbrough study in 2008 found 67% Of False Alerts Mounting Failure



# IHDB False Alert Reason

---

- Mounting Failure
  - False Alert – Mounting – Bracket
  - False Alert – Mounting – Mounting Release
    - Hydrostatic release failure (?)

\*\*Yarbrough study in 2008 found 67% Of False Alerts Mounting Failure



# IHDB False Alert Reason

---

- Mounting Failure
  - False Alert – Mounting – Bracket
  - False Alert – Mounting – Mounting Release
  - False Alert – Mounting – Magnet
    - Switch magnet not effective or missing

\*\*Yarbrough study in 2008 found 67% Of False Alerts Mounting Failure



# IHDB False Alert Reason

---

- Environment Conditions
  - False Alert – environmental Conditions
    - Extreme Weather conditions
    - Hurricane / cyclone conditions, vsI knocked down, heavy seas, ice build-up



# False Alert ELT – environmental Conditions - YES





# False Alert EPIRB— environmental Conditions - NO





# IHDB False Alert Reason

---

- Unknown
  - False Alert – Reason Unknown
    - Confirmed Beacon False Alert
    - No feedback on why activated
    - Investigation in to beacon activation cause was inconclusive