

MSC Guidelines for Review of 30% open requirement for common spaces

Plan Review Guidance #: SOLAS-44

Effective Date	11/15/2002
Regulations	<ul style="list-style-type: none"><input type="checkbox"/> SOLAS 2001 Cite: II-2/9.2.2.3.2.2<input type="checkbox"/> SOLAS 1974 Cite: II-2/26.2
Disclaimer	<p>These guidelines were developed by the Marine Safety Center staff as an aid in the preparation and review of vessel plans and submissions. They were developed to supplement existing guidance. They are not intended to substitute or replace laws, regulations, or other official policy by the Coast Guard or the International Maritime Organization. The responsibility to demonstrate compliance with all applicable laws and regulations still rests with the plan submitter. The Coast Guard and the U.S. Department of Transportation expressly disclaim liability resulting from the use of this document.</p>
Contact Information	<p>If you have any questions or comments concerning this document, please contact the Marine Safety Center by e-mail or phone. Please refer to the Plan Review Guidance #: SOLAS-44.</p> <p>E-Mail: Customerservicemsc@uscg.msc.mil Phone: (202) 366-6480</p>
Regulation Text	<p>"...Smaller, enclosed rooms within a space that have less than 30% communicating openings to that space are considered separate spaces. The fire integrity of the boundary bulkheads and decks of such smaller rooms shall be prescribed in tables 9.1 and 9.2..."</p>
Guidance	<p>With respect to the 30% open determination for common spaces, the Coast Guard expects that windows, louvers, and ceiling area will not be considered as contributing to the 30% open requirement.</p>
Background	<p>We frequently come across multiple spaces that are considered common to one another. While SOLAS is clear that the boundary between these areas should be at least 30% open to be considered common, it is unclear on what methods are acceptable to achieve the level of openness (communicating openings).</p>