



Commanding Officer  
National Strike Force  
Coordination Center

1461 N. Road St. (US 17N)  
Elizabeth City, NC 27909  
Staff Symbol:  
Phone: (252) 331-6000  
FAX: (252) 331-6012

16452

Dear Oil Spill Industry Representative:

During our recent OSRO Workshop, an error was found in Boom Table 2A of the April 4, 2000 proposed OSRO Guidelines. Please insert enclosure (1) in place of that table.

Also, remember that all comments on the draft OSRO Guidelines must reach the Docket Management Facility on or before May 19, 2000. Electronic versions of the proposed Guidelines are available for review at the following web sites:

[www.uscg.mil/hq/g-m/gmhome.htm](http://www.uscg.mil/hq/g-m/gmhome.htm)

[www.uscg.mil/hq/nsfcc/nsfweb/index](http://www.uscg.mil/hq/nsfcc/nsfweb/index)

[www.uscg.mil/hq/vrp/vrpweb/index](http://www.uscg.mil/hq/vrp/vrpweb/index)

For questions concerning this or any related OSRO Guideline issues, contact Lieutenant Bob Rinelli or Lieutenant (Junior Grade) Allen Turner at the National Strike Force Coordination Center at (252) 331- 6000 extensions 3034 and 3041, respectfully.

Sincerely,

R. W. MUTH  
Acting

Encl: (1) Errata Sheet for Table 2A in the Proposed OSRO Classification Guidelines.