

Sector Ohio Valley Waterways Action Plan

Table of Contents

SECTOR OHIO VALLEY WATERWAYS ACTION PLAN.....	2
TABLE OF CONTENTS	2
1. GEOGRAPHIC DESCRIPTION	5
1.A. USCG SECTOR OHIO VALLEY – AREA OF RESPONSIBILITY	5
1. A.1. MTSR and Salvage Plan	5
1.A.2. Hydrologic and Meteorological Factors Affecting Waterways Management.....	6
2. PARTIES AND ROLES.....	8
2.A. GENERAL	8
2.A.1. Industry Groups & Representatives (WAPI, TRPRC, CORMIG, ICE, RIAC, LOMRC and TCIC).....	8
2.B. FEDERAL AGENCIES.....	11
2.B.1 United States Coast Guard (USCG).....	11
2.B.1.a. Safety Advisory	11
2.B.1.b. Safety Zone.....	11
2.B.1.c. Security Zone.....	12
2.B.1.d. Captain of the Port Order (COTP Order)	12
2.B.2. United States Army Corps of Engineers (USACE).....	12
2.B.3. Tennessee Valley Authority (TVA).....	12
3. COMMUNICATIONS:.....	13
3.A. OHIO RIVER COMMUNICATIONS PLAN.....	13
3.A.1. MSU Pittsburgh AOR Communications Plan	13
3.A.1.a. MSU Pittsburgh AOR Ice Communications.....	14
3.A.2. MSU Huntington AOR Communications Plan.....	16
3.A.3. Sector Ohio Valley (Louisville) AOR Communications Plan.....	19
3.A.4. MSU Paducah AOR Communications Plan	22
3.A.5. Ohio Valley Internet Information Communications Plan.....	26
3.B. MISSISSIPPI RIVER COMMUNICATIONS PLAN	27
3.B.1. Upper Mississippi River.....	27
3.B.1.a. Upper Mississippi River Towing Industry Communications Plan (RIAC).....	27
3.B.1.b. Upper Mississippi River Government Agency Communications Plan.....	28
3.B.1.c. Upper Mississippi River Internet Information Communications Plan.....	30
3.B.2. Lower Mississippi River.....	31
3.B.2.a. Lower Mississippi River Towing Industry Communications Plan (LOMRC).....	31
3.B.2.b. Lower Mississippi River Government Agency Communications Plan.....	32
3.B.2.c. Lower Mississippi River Internet Information Communications Plan.....	33
3.C. TENNESSEE RIVER COMMUNICATIONS PLAN	34
3.C.1. Tennessee River Towing Industry Communications Plan.....	34
3.C.2. Tennessee River Government Agencies Communications Plan.....	34
3.C.3. Tennessee River Internet Information Communications Plan.....	36
3.D. CUMBERLAND RIVER COMMUNICATIONS PLAN.....	37
3.D.2. Cumberland River Government Agencies Communications Plan.....	39
3.D.3. Cumberland River Internet Information Communications Plan.....	40

4. ACTION PLAN	41
4.A. OHIO RIVER ACTION PLAN	42
4.A.1. Emsworth Lock and Dam High Water Operations	42
4.A.2. Dashields Lock and Dam High Water Operations	44
4.A.3. Montgomery Lock and Dam High Water Operations	46
4.A.4. New Cumberland Lock and Dam High Water Operations	48
4.A.5. Pike Island Lock and Dam High Water Operations	50
4.A.6. Hannibal Lock and Dam High Water Operations	52
4.A.7. Willow island Lock and Dam High Water Operations	54
4.A.7.a. Parkersburg-Belpre Highway Bridge High Water Operations	56
4.A.8. Belleville Lock and Dam High Water Operations	58
4.A.9. Racine Lock and Dam High Water Operations	60
4.A.10. Robert C. Byrd Lock and Dam High Water Operations	62
4.A.11. Greenup Lock and Dam High Water Operations	64
4.A.12. Meldahl Lock and Dam High Water Operations	66
4.A.13. Markland Lock and Dam High Water Operations	68
4.A.14. McAlpine Lock and Dam High/Low Water Operations	70
4.A.15. Cannelton Lock and Dam High Water Operations	72
4.A.16. Newburgh Lock and Dam High Water Operations	74
4.A.17. J. T. Myers Lock and Dam High Water Operations	76
4.A.18. Smithland Lock and Dam High Water Operations	78
4.A.19. Smithland Lock and Dam Low Water Operations	79
4.A.20. Lock & Dam 52 Low Water Operations	82
4.A.21. Lock & Dam 53 Low Water Operations	84
4.A.22. Irvin Cobb Bridge Operations	86
4.A.23. I-24 Bridge	86
4.A.24. I.C. Railroad Bridge & Route 60/62 Bridge	87
4.A.25. Grand Chain & Post Creek Vicinity	89
4.A.26. American Bar & Mound City Bar Vicinity Low Water Operations	91
4.B. MISSISSIPPI RIVER ACTION PLAN	93
4.B.1. Chester Highway Bridge High Water / High Current Operations	93
4.B.2. Grays Point & Thebes Railroad Bridge High Water / High Current Operations	95
4.B.3. Route 60 / 62 Bridge High Water / High Current Operations	97
4.B.4. Cairo Point Vicinity Low Water Operations	99
4.C. TENNESSEE RIVER ACTION PLAN	101
4.C.1. I-24 / 62 / 641 Bridge High Water / High Current Operations	101
4.C.2. Kentucky Lock & Dam Low Water Operations	103
4.C.3. Kentucky Lock & Dam High Water Operations	105
4.C.4. The Gorge High Water Operations	107
4.D. CUMBERLAND RIVER ACTION PLAN	109
4.D.1. Barkley Lock & Dam Low Water Operations	109
4.D.2. Barkley Lock & Dam High Water Operations	111
4.E. ALLEGHENY RIVER ACTION PLAN	113
4.E.1. Lock 4 Low Water Operations	113
4.E.2. Lock 7 High Water Operations	115
4.F. MONONGAHELA RIVER ACTION PLAN	117
4.F.1. Braddock Lock and Dam High Water Operations	117
4.F.2. Lock and Dam 4 High/Low Water Operations	119
4.F.3. Maxwell Lock and Dam High Water Operations	121
4.F.4. Grays Landing Lock and Dam High Water Operations	123
4.F.5. Point Marion Lock and Dam High Water Operations	125
4.G. KANAWHA RIVER ACTION PLAN	127
4.G.1. Winfield Lock and Dam High Water Operations	127
4.G.2. Marmet Lock and Dam High Water Operations	129
4.G.3. London Lock and Dam High Water Operations	131
4.H. GREEN RIVER ACTION PLAN	

4.I. ICE CONDITIONS: ALL ZONES	133
5. DRIFT REMOVAL PROCEDURES	140
5.A. HUNTINGTON DISTRICT DRIFT REMOVAL PROCEDURES	140
5.A.1. Willow Island Locks and Dam	140
5.A.2. Belleville Locks and Dam	140
5.A.3. Racine Locks and Dam	140
5.A.4. Robert C. Byrd Locks and Dam	141
5.A.5. Greenup Locks and Dam	141
5.A.6. Meldahl Locks and Dam	141
5.A.7. London Locks and Dam - (Kanawha River)	141
5.A.8. Marmet Locks and Dam - (Kanawha River)	141
5.A.9. Winfield Locks and Dam - (Kanawha River)	142
5.B. LOUISVILLE DISTRICT DRIFT REMOVAL PROCEDURES	142
5.B.1. Markland Lock	142
5.B.2. McAlpine Lock	142
5.B.3. Cannelton Lock	142
5.B.4. Newburgh Lock	143
5.B.5. John T. Myers Lock	143
5.B.6. Smithland Lock	143
6. RISK ASSESSMENT	144
6.A. CASUALTY HISTORY BY LOCATION	144
Monongahela River	144
Allegheny River	144
Ohio River	144
Upper Mississippi River	144
Lower Mississippi River	145
Tennessee River	145
Cumberland River	145
6.B. WATERWAY ANALYSIS	146
6.B.1. Tool Legend	146
6.B.2. Risk Factors	146
6.B.2.a. Monongahela River	146
6.B.2.b. Allegheny River	146
6.B.2.c. Ohio River	147
6.B.2.d. Mississippi River	147
6.B.2.e. Tennessee River	148
6.B.2.f. Cumberland River	149

1. Geographic Description

1.A. USCG Sector Ohio Valley – Area of Responsibility

Sector Ohio Valley is comprised of all of Kentucky and West Virginia; in Missouri: Perry, Cape Girardeau, Scott, Mississippi and New Madrid Counties; in Tennessee: that portion of Lake County north and west of a line drawn from the Mississippi River at latitude 36° 20' N and longitude 89° 32' 30" W due east to Highway 78, thence northeast along Highway 78 to the Kentucky/Tennessee state line, and all other counties except Shelby, Tipton, Lauderdale, Dyer and Obion Counties; in Alabama: Colbert, Lawrence, Morgan, Marshall, Lauderdale, Limestone, Madison, and Jackson Counties; that portion of Pennsylvania south of latitude 41° 00' N and west of longitude 79° 00' W; those parts of Indiana and Ohio south of latitude 41°00'N; in Illinois: Jackson, Williamson, Saline, Gallatin, Union, Johnson, Pope, Hardin, Alexander, Pulaski and Massac Counties, and in Randolph County, that part of the Upper Mississippi River below mile 109.9, including both banks; that part of the Lower Mississippi River above mile 869.0.

CG Marine Safety Unit Pittsburgh – Area of Responsibility	
Ohio River	MM 00.0 - MM 127.2
Monongahela River	MM 00.0 – MM 128.7
Allegheny River	MM 00.0 – MM 72.0
CG Marine Safety Unit Huntington – Area of Responsibility	
Ohio River	MM 127.2 – MM 401.3
Kanawha River	MM 00.0 – MM 97.0
Big Sandy River	MM 00.0 – MM 26.8
Elk River	MM 00.0 – MM 190.0
Muskingum River	MM 00.0 – MM 112.5
Little Kanawha River	MM 00.0 – MM 122.0
Sector Ohio Valley (Louisville) – Area of Responsibility	
Ohio River	MM 531.5 – MM 867.4
Green River	MM 00.0 – MM 199
Kentucky River	MM 00.0 – 258.6
Wabash River	MM 00.0 – MM 585.0
White River	MM 00.0 – MM 51.6
Rough River	MM 00.0 – MM 29.0
Cumberland River	MM 385.6 – MM 694.2
CG Marine Safety Detachment Cincinnati – Area of Responsibility	
Ohio River	MM 401.3 – MM 531.5
Licking River	MM 00.0 – MM 3.0
Miami River	MM 00.0 – MM 117.6
CG Marine Safety Unit Paducah – Area of Responsibility	
Ohio River	MM 867.4 – MM 981.0
Upper Mississippi River	MM 000.0 – MM 109.9
Lower Mississippi River	MM 869.0 – MM 953.8
Tennessee River	MM 000.0 – MM 080.0
Cumberland River	MM 000.0 – MM 080.0
CG Marine Safety Detachment Nashville – Area of Responsibility	
Tennessee River	MM 080.0 – MM 652.2
Cumberland River	MM 080.0 – MM 385.6
Tennessee – Tombigbee Waterway	MM 412.0 – MM 450.5

1. A.1. MTSR and Salvage Plan

In the event of river closures, salvage of vessels, or other events that negatively impact the marine transportation system, please reference the Sector Ohio Valley MTSR and Salvage Plans.

1.A.2. Hydrologic and Meteorological Factors Affecting Waterways Management

General: The Ohio River and its tributaries form a complex system spread out over millions of square miles. In order to predict changes in conditions in this system, waterway managers must constantly monitor a number of hydrologic and meteorological factors. These include water flow, soil moisture, snow cover, precipitation, temperature, weather patterns and most importantly geography. Effective waterways managers must constantly monitor these factors and forecast river conditions in order to ensure they are adequately prepared to deal with a regional transportation emergency.

Numerous variables affect how much water is in the system at any given time. Listed below are some of the key variables:

Base Flow The amount of water flow (measured in cubic feet per second (CFS)) along a section of river (usually measured at a dam). The USACE has established an average flow rate for each section of river. Average rates are based on flows consistent with normal weather patterns. A comparison of actual flow against the base flow is an indicator of increased or decreased water levels. The flow rate does not provide an indication of the duration of increased/decreased flows. Base flows and flow rate information are available from the USACE.

Soil Moisture The amount of moisture concentrated in the soil. High soil moisture content means a large percentage of new precipitation will not be absorbed into the soil. This will result in increased runoff and a corresponding increase in water levels. Soil moisture averages and current levels are available from the U. S. Geological Survey (USGS) and state water/soil conservation agencies.

Precipitation The amount of rain/sleet, etc. This becomes runoff and impacts water levels in the river systems. The amount and duration of precipitation are equally important factors. Precipitation averages and totals can be obtained from the USGS, the National Oceanic and atmospheric Association (NOAA), the National Weather Service (NWS) and State agencies.

Snow Cover Snow cover is the buildup of snow that will melt and enter the water table and/or turn into runoff. Increase in snow cover will result in a corresponding increase in runoff and spring water levels. Information on snow cover can be obtained via NOAA, NWS and State weather services.

Temperatures Average fall and winter temperatures determine the depth of frost, the amount of water entering the soil and the amount and duration of river ice. Below normal temperatures in the fall and winter increase the depth of frost, allowing less water to enter the soil during periods of precipitation, increasing the amount of runoff. This situation may also cause an increase in ice and subsequent problems due to ice dams or gorges, and difficulties with the lock and dam system. Above normal temperatures in the spring increases the amount of runoff from snow melt. Temperature information is available from USGS, NOAA, NWS and State agencies.

Geography Terrain The physical characteristics of the river bend and shoreline. These characteristics impact river currents and the rate of change in water levels. Steep banks, levees, revetments, narrow channels, rock bottoms, adjacent flood plains and wetlands are just a few of the factors that determine how the river will rise or fall. In addition, geography has an effect on ice buildup, the effect of flooding, the time and complexity of maintenance and dredging and the effectiveness of traffic control measures.

River Slope

Rivers slope downstream toward their mouths. Slope is the change in elevation of the river, expressed as a ratio of the change in elevation between reference points and the number of miles between reference points. A working knowledge of slope is one of the best tools to quickly determine river conditions and the duration of low/high water events. As flow rates from the upper dams increase, the slope will increase as the upper end of the river in the vicinity of the upper dam increases in depth. If the increased flow rates remain constant, water levels downstream will rise and be sustained. As upper river water flow decreases, the river slope will decrease and water levels will crest sequentially down the river. The term for this decrease in flow and subsequent decrease in slope is called "leveling." Once the crest has passed through the system, and flow rates become more consistent, water levels and slope will return to normal.

"Leveling" also occurs when low water conditions prevail in the system. As the dams reduce flow in order to maintain their pools, less water becomes available downstream. As each successive dam reduces flow to maintain the nine foot channel, short term low water is caused in the next pool downstream until that dam holds enough water to maintain its required level. When dams are only able to maintain minimum pool or unable to maintain a minimum channel depth due to lack of sufficient water or loss of pool, traffic management may have to be initiated.

Weather Pattern Changes

Changes in weather patterns impact the river system by themselves and in conjunction with the factors listed above. One of the best known examples of this is the abnormal pattern that contributed significantly to the Great Flood of 1993. In this case, a wet-weather pattern persisted over the upper mid-west for over six months. This was caused by a weather front convergence zone which generated frequent and prolonged thunderstorms. In addition to the excessive rain, the area experienced an early snow melt, increasing spring runoff.

2. Parties and Roles

2.A. General

USACE POSITION	DUTIES AND RESPONSIBILITIES	EQUALS	USCG POSITION	DUTIES AND RESPONSIBILITIES
Head Lock operator	Coordinate Traffic, L&D Operations, Maintains Pool		MSU Prevention/Response Department Heads	Manages daily waterways management and casualty operations
REPORTS TO:				
Lock Masters	Oversees supervision and maintenance of project L&D		MSU CO/XO	Manages and supervises MSU daily operations
REPORTS TO:				
Assistant Operations Manager	Maintenance and oversight of District L&D projects		Deputy Sector Commander	Oversees Sector operations and management
REPORTS TO:				
Operations Manager	Planning and Control of District L&D Projects		Sector Ohio Valley Sector Commander	Senior Officer in Charge.

The successful management of any river crisis is dependent on the cooperation of the waterway system participants. This includes agencies of the federal, state and local governments, industry groups, and the general public (See 2.A.1. below for listing of industry groups by AOR), this chapter identifies the key organizations in these areas, outlines their authority and responsibilities, and explains their roles during a river crisis. They groups serve a vital role in serving as a liaison between industry and federal agencies. These groups address waterways conditions for the Allegheny, Monongahela, Ohio, Upper Mississippi, Lower Mississippi, Tennessee and Cumberland Rivers.

This plan should be used in conjunction with existing plans. Its purpose is to pull together information from existing plans and identify critical problem areas based on federal agency experience, industry experience, and statistical analysis.

***** In addition to this plan, reference the Tennessee River Waterway Management Plan and the Cumberland River Waterway Management Plan.**

[Tennessee River Waterway Management Plan](#)

[Cumberland River Waterway Management Plan](#)

2.A.1. Industry Groups & Representatives (WAPI, TRPRC, CORMIG, ICE, RIAC, LOMRC and TCIC)

2.A.1.a. MSU Pittsburgh AOR

2.A.1.a. 1. Waterways Association of Pittsburgh (WAPI) is an industry based association which represents the maritime industry in navigation safety, waterway infrastructure, commercial vessel regulation and maritime labor issues in the Pittsburgh AOR. Various committees of the association review matters relating to vessel safety, navigation safety, maritime industry regulatory issues and waterway infrastructure.

The Three Rivers Pollution Response Council Inc., (TRPRC) is a mutual aid organization representing a partnership between industry, U.S. Coast Guard and EPA Region III, dedicated to the prevention of oil and hazardous substances entering the inland waterways. The Council assists members with the over all aspects of response planning, drilling, and training.

2.A.1.b.MSU Huntington AOR

2.A.1.b.1. Huntington District Waterway Association (HDWA) is a regional association of commercial river users whose boundaries coincide with the Army Corps of Engineers Huntington District boundaries. The boundary extends on the Ohio River from Hannibal L/D to Meldahl L/D and includes the Kanawha and Big Sandy Rivers. Five different associations comprised of The Huntington District Waterways Advisory Committee, The Navigational Subcommittee, the Big Sandy Improvement Committee, The Tri-State Fleeting Association, and The Kanawha River Improvement Committee came together to form the HDWA. The group acts as a representative for industries operating on the Ohio River in the Army Corps of Engineers Huntington District. The HDWA is coordinated by a volunteer chairman from industry.

2.A.1.c. SOHV Louisville AOR

2.A.1.c.1. Central Ohio River Marine Industry Group (CORMIG) is a committee of the central Ohio River Towing companies, Coast Guard and Army Corps Representatives formed to address navigation problems during significant changes in river conditions such as extreme low water and high water events. The committee has evolved to address all issues concerning Central Ohio River navigation and is the major liaison between the towing industry, the Coast Guard, and Army Corps of Engineers for river conditions stretching from Huntington, WV to Cairo, IL. CORMIG is coordinated by a volunteer chairman from industry..

2.A.1.d. MSU Paducah AOR

2.A.1.d.1. The Ohio River Ice Committee (ICE) MSU Paducah AOR is an ad hoc committee of the Ohio River towing companies formed to address navigation problems during the major ice event of 1977 – 1978 on the Ohio River. Subsequent to this crisis, the committee has evolved to address all issues concerning Ohio River navigation, especially issues related to river conditions in the Lower Ohio River Valley area, and is the major liaison between the towing industry, the Coast Guard, and the Army Corps of Engineers. The Ice Committee also addresses river conditions impacting the Tennessee River and the Cumberland River. The Ice Committee is coordinated by a volunteer chairman from industry.

2.A.1.d.2. The River Industry Action Committee (RIAC) MSU Paducah AOR is a committee of the Upper Mississippi River and the lower Ohio River towing companies formed to address navigation problems during significant changes in river conditions such as extreme low water and high water events. The committee has evolved to address all issues concerning the Upper Mississippi River and lower Ohio River navigation and is the major liaison between the towing industry, the Coast Guard, and the Army Corps of Engineers for river conditions between St. Louis, MS and Cairo, IL. RIAC is coordinated by a volunteer chairman from industry.

2.A.1.d.3. Lower Mississippi River Committee (LOMRC) MSU Paducah AOR is a committee of the Lower Mississippi River and the lower Ohio River towing companies formed to address navigation problems during significant changes in river conditions such as extreme low water and high water events. The committee has evolved to address all issues concerning the Lower Mississippi River and lower Ohio River navigation and is the major liaison between the towing industry, the Coast Guard, and the Army Corps of Engineers for river conditions between Cairo, IL and Memphis, TN. LOMRC is coordinated by a volunteer chairman from industry.

2.A.1.d.4. The Tennessee and Cumberland River Industry Committee (TCIC) MSD Nashville and MSU Paducah AOR serves as the primary committee for communicating among the towing companies operating on the Tennessee and Cumberland River within the Coast Guard Marine Safety Detachment Nashville and Marine Safety Unit Paducah Area of Responsibility. The TCIC Committee Chairman serves as the primary point of contact for relaying information, coordinating meetings, and setting up conference calls between all federal agencies and the towing industry. The primary purpose of the TCIC Committee is to address all issues concerning Tennessee and Cumberland River navigation and to act as the major liaison between the towing industry, the Coast Guard, the Tennessee Valley Authority and the Army Corps of Engineers throughout the Tennessee and Cumberland River Valley.

2.A.2 Industry Points of Contact

AREAS ADDRESSED	COMPANY	MAIN POC	INDUSTRY GROUP	CONTACT INFO
Ohio River Allegheny River Monongahela River	Contact information available in password protected version			
Ohio River Allegheny River Monongahela River				
Ohio River Kanawha River				
Ohio River Green River				
Ohio River				
Upper Mississippi River				
Lower Mississippi River				
Tennessee River				
Cumberland River				

2.B. Federal Agencies

The United States Code (USC) provides regulatory authority for establishing and authorizing work or structures constructed within the navigable waterways and provides regulations for maintaining navigation throughout U.S. territorial waters. Included as part of a national waterway system are numerous rivers, lakes and streams that comprise the inland waterway system. Navigation on these “navigable waters of the United States” is regulated primarily by the USCG. The USACE provides technical advice to the USCG to enable that agency to properly evaluate and make decisions on navigation safety. The USACE is also responsible for authorizing waterway projects, evaluating and maintaining navigable channels, and directing emergency flood control operations (such as activation of spillways). The Tennessee Valley Authority (TVA) maintains jurisdiction on the Tennessee River and Cumberland River and monitors river conditions through flows discharged from locks and dams on these rivers, such as Kentucky Lock & Dam and Barkley Lock & Dam.

2.B.1 United States Coast Guard (USCG)

Title 14, USC, defines USCG roles and responsibilities in establishing and maintaining the safety of ports and waterways; 33 CFR Part 165.20 gives COTP’s and USCG District Commanders the authority to impose safety zones, security zones, and other restrictions to ensure the safe flow of navigation. Activities of the COTP’s are overseen by the Commander, Eighth Coast Guard District, in New Orleans, LA. Activities of the Marine Safety Unit Commanding Officers are overseen by the Commander, Sector Ohio Valley, in Louisville, KY.

2.B.1.a. Safety Advisory

The simplest form of intervention is a Navigation Safety Advisory. It relies on the voluntary compliance of industry to limit risk and prevent vessel casualties. USCG advisories are usually issued after consultation with the USACE and industry-user groups. They can be originated by the USCG or self imposed by industry, and disseminated as a USCG Broadcast Notice to Mariners (BNTM), posted on the USACE bulletin board, posted on the River Industry Bulletin Board (RIBB), sent via the industry facsimile, or any combination of these methods. The purpose is to advise the marine industry of the existence of hazardous conditions and provide recommendations for navigating safely. Advisories can also be used to notify the marine industry of the Captain of the Port’s (COTP’s) intention to take action with respect to developing navigation conditions. Advisories are important tools that provide marine interests time to adjust their operations to avoid future problems.

2.B.1.b. Safety Zone

During extreme high or low water conditions the risk of commercial vessel navigation can become increasingly hazardous to the environment, persons and property. These extreme cases may require the establishment of a safety zone by the COTP that imposes vessel-operating restrictions. Consultation and deliberation with the USACE and industry-user groups usually precede implementation of a safety zone by the USCG. A safety zone entails the control of a portion of the river, tributary, or harbor. This enables the USCG to control access and/or prescribe operating restrictions on vessels seeking to navigate in the area. This approach can be applied to limited or large geographical areas and may involve simple or complex restrictions, such as:

- Minimum horsepower requirements per barge
- Maximum draft limits
- Maximum tow sizes
- Specific tow configurations
- Length and breadth limits
- Safe speed zones, no-passing zones, or no-meeting zones
- Helper or towboat requirements
- Traffic separation schemes
- Reporting requirements
- Tank barge prohibitions or the exclusion of all vessels from the safety zone

The establishment of a safety zone may include active control of vessel traffic through an area or it may be conducted passively, relying on compliance to limit risk. Safety zones using passive control have been imposed on other waterways during periods of high or abnormally low water and when local construction or pollution response cleanup operations are impacted by passing traffic.

2.B.1.c. Security Zone

In some cases a security zone may be implemented to protect persons, property and the environment from actual or potential threats related to terrorism or destruction. These extreme cases may require the establishment of a security zone by the COTP that imposes restrictions on a vessel or a specific area of the river. Consultation and deliberation with the USACE, and industry-user groups usually precede implementation of a security zone by the USCG. A security zone entails the control of a portion of the river, tributary, or harbor. This enables the USCG to control access and/or prescribe restrictions on vessels and persons. This approach can be applied to limited or large geographical areas and may involve simple or complex restrictions. The establishment of a security zone may include active control of vessel traffic and intensive screening of persons entering through an area.

2.B.1.d. Captain of the Port Order (COTP Order)

Captain of the Port Orders are specific directions to an individual, facility, or vessel. They are detailed and exact in scope. Issued under the authority of the Ports and Waterways Safety Act, compliance with COTP Orders is required, and failure may result in civil or criminal penalty action. In general, COTP Orders will only be used when a terminal or vessel appears to be operating in an unsafe manner or to reduce damage to the environment or property.

2.B.2. United States Army Corps of Engineers (USACE)

Title 33 U.S.C., defines the USACE roles and responsibilities regarding development of, or change to, waterfront facilities, weirs, dams or dikes. Specifically, the USACE is authorized to review and approve all changes to hydrodynamic structures for the purposes of maintaining a navigable channel. In addition, the USACE is charged with conducting operations to maintain the physical nature of a navigable channel on particular waterways. Generally, the USACE has the responsibility to maintain a nine foot congressionally authorized project depth within the navigable channel on the Ohio River System. The USACE is also responsible for directing emergency flood control operations and collecting information on flood stages and damage.

2.B.3. Tennessee Valley Authority (TVA)

Under the TVA Act of 1933, as amended, 6 U.S.C. 831 – 831 dd (1994), TVA is authorized to construct and operate dams and reservoirs in the Tennessee River and its tributaries to promote navigation and to control destructive floods. Also under the TVA Act, TVA has broad responsibilities for the “development of the natural resources of the Tennessee River drainage basin and of such adjoining territory as may be related to or materially affected by the development for the general purpose fostering an orderly and proper, physical, economic, and social development of said areas. The broad responsibilities placed on the Tennessee Valley Authority relate to navigability, flood control, reforestation, marginal lands, and agricultural and industrial development of the whole Tennessee Valley.” Those responsibilities specifically include the construction and maintenance of the dams and reservoirs in the Tennessee River and its tributaries and providing a nine-foot channel in the river.

3. Communications:

3.A. Ohio River Communications Plan

3.A.1. MSU Pittsburgh AOR Communications Plan

If and when the Watch Phase occurs on the Ohio, Monongahela, or Allegheny Rivers, the WAPI will enact the “Waterways Association of Pittsburgh Calling Tree” seen below. In order to ensure that this calling tree remains accurate, annual audits will be conducted to ensure the accuracy of these calling trees and any changes should be immediately reported to the WAPI. In addition, when the trigger openings are met Coast Guard Marine Safety Unit (MSU) Pittsburgh will make notifications in accordance with Section 4 via Broadcast Notice to Mariners (BNM) through USCG Sector Ohio Valley Command Center.

ORGANIZATION	DESIGNATED CONTACT	PHONE NUMBERS	E-MAIL ADDRESS	WHEN CONTACTED
Waterways Association of Pittsburgh Navigation Committee	Contact information available in password protected version			

GOVERNMENT AGENCY	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
Coast Guard	Contact information available in password protected version			
USACE				

In addition, Coast Guard Sector Ohio Valley broadcasts river stages over VHF-FM radio channel 16. Scheduled broadcasts and river stages for the Ohio River and its tributaries are made at 11:00 a.m. EST. To obtain 24 hour information services, recorded messages on river gauges, predictions and weather forecasts with 7:00 a.m. and 1:00 p.m. updates, call these numbers:

Emsworth L/D – Ohio River	412-766-4555
Pike Island L/D – Ohio River	304-277-4646
Maxwell L/D – Monongahela River	724-785-3247
4 L/D – Allegheny River	724-224-0228

3.A.1.a. MSU Pittsburgh AOR Ice Communications

The U. S. Coast Guard Captain of the Port (COTP) Pittsburgh, in conjunction with the Waterways Association of Pittsburgh (WAPI), issues safety advisories when ice conditions pose a threat to the safe navigation of the Ohio, Monongahela and Allegheny rivers.

1. MSU Pittsburgh will coordinate a pre-seasonal Ice Committee Teleconference on or about the first week of December of each year. Pittsburgh Ice Committee members include the U. S. Coast Guard Captain of the Port Pittsburgh, The WAPI President and head of the Navigation Committee, designated representatives from the U. S. Army Corps of Engineers, Pittsburgh District, and National Weather Service.
2. Coordinate communications of waterway conditions from WAPI members during extended periods of freezing temperatures & river icing.
3. Issue Broadcast Notice to Mariners and SITREPS, as needed. An example broadcast and SITREP are listed below; previous message traffic and internal Coast Guard correspondence are located in the Waterways Action Plan\Ice Ops located in MSU Pittsburgh's shared electronic folder.
4. Coordinate scheduled Ice Committee Teleconferences, as needed.
5. Consider issuing navigation restrictions.
6. Over flights are generally performed by the U.S. Coast Guard aviation or U. S. Coast Guard Auxiliary assets, and will be requested through Sector Ohio Valley via CGMS message traffic. Additionally Pennsylvania State Police assets have been utilized. Contact information for Aviation Unit V Latrobe, PA Primary contact 724-520-3200, Alternate 724-8288; Aviation Unit VI Franklin, PA Primary 814-437-3424, Alternate 814-676-6596. Allegheny County Airport is the primary service facility available to aircraft, Primary Contact 412-469-6800, Radio frequencies Tower: 121.70MHZ, Services 129.95MHZ.

FM COGARD MSU PITTSBURGH PA
TO COMCOGARD SECTOR OHIO VALLEY LOUISVILLE KY
BT

UNCLAS

SUBJ: REQUEST BROADCAST NOTICE TO MARINERS BEGINNING *INSERT DATE*.

1. THE U. S. COAST GUARD CAPTAIN OF THE PORT (COTP) PITTSBURGH, IN CONJUNCTION WITH THE WATERWAYS ASSOCIATION OF PITTSBURGH, HAS ISSUED THIS SAFETY ADVISORY DUE TO ICE ACCUMULATIONS ON THE ALLEGHENY, MONONGAHELA AND OHIO RIVERS. IT IS IMPERATIVE THAT ALL NECESSARY ACTIONS BE TAKEN TO MITIGATE THE RISKS POSED BY THESE CONDITIONS AND THAT ALL MARINERS EXERCISE EXTREME CAUTION. FACILITY OPERATORS AND FLEETING AREA MANAGERS ARE REMINDED TO REVIEW THEIR FLEETING PROCEDURES ENSURING THE CONTINUOUS SURVEILLANCE OF FLEETING AREAS, ENSURE FLEETS ARE SECURED WITH AN ADEQUATE NUMBER OF LINES, THAT LINES ARE DOUBLED-UP AT THE HEAD OF THE FLEET, AND SECURING TOWBOAT ASSISTANCE IF NECESSARY.

BT

NNNN

FM COGARD MSU PITTSBURGH PA
TO CCGDEIGHT NEW ORLEANS LA//DP/DPW//
COGARD MSD CINCINNATI OH
COGARD MSU HUNTINGTON WV
USCGC OSAGE
COMCOGARD SECTOR OHIO VALLEY LOUISVILLE KY
INFO CDRUSAED PITTSBURGH PA
BT

UNCLAS //N03006//

SUBJ: SITREP ONE, ICE CONDITONS ON THE ALLEGHENY, MONONGAHELA, AND
OHIO RIVER.

A. OHIO RIVER VALLEY WATERWAYS MANAGEMENT PLAN.

1. SITUATION: THE MSU PITTSBURGH AOR HAS EXPERIENCED SEVERAL WEEKS OF SUB-FREEZING TEMPERATURES. AS A RESULT, ACCUMULATIONS OF ICE HAVE FORMED ON ALL RIVERS WITHIN THE ZONE. NAVIGABLE CHANNELS REMAIN OPEN TO VESSEL TRAFFIC, WITH THE EXCEPTION OF THE UPPER REACHES *OF THE XXXXXX RIVER BEYOND LD #X*. WEATHER FORECASTS FOR THE AREA INDICATE A *HIGH/LOW* PROBABILITY OF *SNOW/FREEZING RAIN* OVER THE NEXT 48 HOURS WITH TEMPERATURES EXPECTED TO *RISE TO/FALL TO/STABILIZE BETWEEN XX-XX* DEGREES FARENHEIT, *INCREASING/DECREASING* THE LIKELIHOOD OF NEW ICE FORMATION OR BUILD-UP.

2. ACTION TAKEN:

INSERT DTG: MSU PITTSBURGH IS HOSTING A TELECONFERENCE WITH THE OHIO RIVER VALLEY ICE COMMITTEE WHICH INCLUDES MEMBERS FROM: US ARMY CORPS OF ENGINEERS, NATIONAL WEATHER SERVICE, CG MSU HUNTINGTON, CG SECTOR OHIO VALLEY, CGC OSAGE, AND LOCAL INDUSTRY TO ASSESS CURRENT OPERATING CONDITIONS.

LIST RESTRICTIONS

3. FUTURE PLANS:

A. ICE COMMITTEE TELECONFERENCE SCHEDULED FOR *INSERT DTG*.

B. CGAUX OVERFLIGHT OF AOR SCHEDULED FOR *INSERT DTG*.

C. MSU PITTSBURGH WILL CONTINUE TO MONITOR SITUATION WITH INDUSTRY STAKEHOLDERS AND INITIATE OVERFLIGHTS AS NECESSARY. COTP PITTSBURGH WILL CONSIDER INPUT PROVIDED BY ALL INVOLVED AND APPLY VESSEL RESTRICTIONS, AS NEEDED, BASED UPON CHANGING CONDITIONS WITHIN THE MSU PITTSBURGH AOR.

BT

NNNN

3.A.2. MSU Huntington AOR Communications Plan

COMPANY / ORGANIZATION	DESIGNATED CONTACT	PHONE	EMAIL	WHEN CONTACTED
Action Petroleum Terminals			Contact information available in password protected version	
AEP Gavin Plant				
AEP John Amos Plant				
AEP River Operations				
American Styrenics Marietta				
Docks Creek				
Asphalt Materials Plant				
Baker Oil Company				
Bayer Crop Science				
BP Sciotoville				
Century Lubricants (Fuchs)				
Ceredo Liquids (KRT)				
Crouse Corp.				
Degussa Carbon Black				
Dominion Transmission-Bens Runs				
Dow Chemical Charleston				
Dow Chemical Charleston				
Dow Hanging Rock				
DuPont Chemicals Belle				
DuPont Washington Works				
Ergon trucking				
Gate City River Transportation				
Go-Mart Inc. Amandaville Terminal				
Kirby Institute Barge Fleeting				
Kirby Institute Barge Fleeting				
Kokosing Materials				
Kraton Polymers				
Kanawha River Terminals				
M & G Polymers				
Madison Coal & Supply				

Madison Coal & Supply			Contact information available in password protected version	
Marathon Petroleum (HDWA President)				
Mark West Energy Appalachia, LLC				
McGinnis, Inc.				
McGinnis, Inc.				
Merdie Boggs & Sons, Inc.				
Middleport Terminal- Shelly Liquid				
MPC Charleston				
MPC Inc. - Harbor Dispatch				
MPC Kenova Terminal				
MPC Kenova Terminal				
MPC Kenova Terminal				
MPC Marietta				
MPC Refinery – Marathon Oil Company				
Marathon Oil Company				
MPC Repair Terminal				
N&S Railroad				
Neale Fleeting				
Nova Chemicals(Caretaker Status)				
Ohio Oil Gathering Corp.				
Ohio River Sanitation Commission				
O-Kan Marine Repair				
R&D Associates				
Sabic Innovative Plastics				
Safety-Kleen Systems, Inc.				
Saint Mary's Refining				
Sunoco Chemical				

GOVERNMENT AGENCIES	DESIGNATED CONTACT	PHONE	EMAIL	WHEN CONTACTED
USCG MSU Huntington Duty Officer			Contact information available in password protected version	
USCG MSU Huntington Commanding Officer				
USCG MSU Huntington Prevention Department				
WV Dept of Natural Resources				
USACE, Huntington District				
USACE, Huntington District				
National Weather Service, Charleston, WV				
OH Dept of Natural Resources				

3.A.3. Sector Ohio Valley (Louisville) AOR Communications Plan

COMPANY/ ORGANIZATION	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
American Commercial Barge Lines			Contact information available in password protected version	
American Electric Power (AEP)				
Argosy Casino and Hotel				
Arrow Terminals LP NAS Dock				
Azstar Casino				
Sazerac North America				
BB Riverboats				
Beckjord Power Station				
Belle of Louisville				
Belterra Casino and Resort				
BP Oil Pipeline Company				
BP Products North America				
Marathon Petroleum				
CF Industries Inc.				
Chevron USA				
Cincinnati Bulk Terminal				
Citgo Petroleum Corp				
Clark Maritime Center				
Consolidated Grain and Barge				
Countrymark Cooperative				
Crouse Corp.				
Dart Polymers Inc.				
Dow Corning				
Evansville Marine Service				
Fall City Towing				

Five M Transportation			Contact information available in password protected version	
General Electric Plastics				
Grand Victoria Casino & Resort				
Countrymark Henderson Terminal				
Momentum Specialty Chemicals				
Indiana Port Commission				
IN-KY Electric				
Kinder Morgan				
Kirby Corporation				
Lanxess Corp.				
Liquid Transfer Terminal				
MAP/LLC Mt. Vernon				
MAP/LLC Clarksville/Louisville				
MAP/LLC Evansville				
Marathon Ashland Asphalt				
Marathon Ashland Co.				
Marathon Ashland Covington				
Marathon Ashland Petro				
Miles River Terminal				
Mosaic Phosphates				
Mt. Vernon Barge Service				
Mulzer Crushed Stone, Inc.				
Ohio Valley Marine Service				
Owensboro Grain Company				
Owensboro Grain Edible Oils				
Peter Cremer				
Queen City Terminals				
The Dow Chemical Co.				
Agrium				

Agrium US			Contact information available in password protected version	
Southern States				
Westway				
Southwind Maritime Center				
Tanco Clark Maritime LLC				
Thornton Transportation				
Transmontaigne Evansville				
Transmontaigne Henderson				
Transmontaigne Kentuckiana				
Transmontaigne Louisville				
Transmontaigne Owensboro				
Transmontaigne Cincinnati				
Wooten's River Service				
Yager Materials, Inc.				

3.A.4. MSU Paducah AOR Communications Plan

COMPANY / ORGANIZATION	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
River Marine Enterprises			Contact information available in password protected version	
Ingram Barge Co.				
Tennessee Valley Towing				
Marquette Transportation				
Kirby Inland Marine				
AEP Memco				
Crouse Corporation				
United Barge Line				
ARTCO				
American Commercial Barge Line (ACBL)				
Excell Marine				

Marathon Ashland			Contact information available in password protected version	
Magnolia Marine				
Florida Marine				
Inland Marine				
Luhr Brothers, Inc.				
Seaman's Church Institute				

GOVERNMENT AGENCY	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
U.S. Coast Guard			Contact information available in password protected version	
Sector Ohio Valley				
Sector Command				
U.S. Coast Guard Sector Ohio Valley Buoy Tenders				
U.S. Coast Guard MSU Paducah				
U.S. Army Corps of Engineers Louisville District Office				
U.S. Army Corps of Engineers Louisville District Office				
U.S. Army Corps of Engineers Louisville District Office				
U.S. Army Corps of Engineers Smithland Lock and Dam				

U.S. Army Corps of Engineers Lock and Dam 52			Contact information available in password protected version	
U.S. Army Corps of Engineers Lock and Dam 52				
U.S. Army Corps of Engineers Lock and Dam 53				
U.S. Army Corps of Engineers Cairo, IL GAUGE Reading				
U.S. Army Corps of Engineers Nashville District (Tennessee Locks / Cumberland Locks and Dams)				
Tennessee Valley Authority (Tennessee Locks and Dams)				
U.S. Army Corps of Engineers Paducah, Kentucky Flood Protection Project Levee Manager				
U.S. Army Corps of Engineers Brookport, Illinois Flood Protection Project Levee Manager				
U.S. Army Corps of Engineers Golconda, Illinois Flood Protection Project Levee Manager				
U.S. Army Corps of Engineers Rosiclare, Illinois Flood Protection Project Levee Manager				
U.S. Army Corps of Engineers Sturgis, Kentucky Flood Protection Project Levee Manager				
U.S. Army Corps of Engineers Shawneetown, Illinois Flood Protection Project				

3.A.5. Ohio Valley Internet Information Communications Plan

INTERNET SITE PURPOSE	ADDRESS
River Industry Bulletin Board (R.I.B.B.)	http://www.ribb.com/index.php
National Response Center (NRC) – Report Pollution / Terrorist Activity	http://www.nrc.uscg.mil/nrchp.html
Ohio River Lock & Dam Vessel Queues	http://www.ribb.com/riverstatus/river_locks.php
Kentucky / Barkley Lock & Dam Information	http://explorekentuckylake.com/weather.htm
National Weather Service (NWS) – River Forecasts	http://www.srh.noaa.gov/lmrfc/?n=lmrfc-mississippiandohioriverforecast
U.S. Army Corps of Engineers – River Gauges	http://www.lrd-wc.usace.army.mil/text/navrpti.txt
U.S. Army Corps of Engineers – River Navigation Charts	http://www.lrl.usace.army.mil/optm/default.asp?mycategory=41
Tennessee Valley Authority (TVA) – TNR / CMR	http://www.tva.gov/river/lakeinfo/index.htm
Tennessee Valley Authority (TVA) – Barkley L&D Flows	http://lakeinfo.tva.gov/htbin/lakeinfo?site=BAH&DataType=All&submit=View+info
Tennessee Valley Authority (TVA) – Kentucky L&D Flows	http://lakeinfo.tva.gov/htbin/lakeinfo?site=KYH&DataType=All&submit=View+info
The River School – River Training & Orientation	http://www.riverschool.com/
Incident Command System (ICS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
National Incident Management System (NIMS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
U.S. Coast Guard Port Security Directorate (MTSA Info)	https://homeport.uscg.mil/mycg/portal/ep/channelView.do?channelId=-24885&channelPage=%2Fep%2Fchannel%2Fdefault.jsp&pageTypeId=13489
U.S. Coast Guard – Eighth District Site – New Orleans, LA	Sector New Orleans Homeport Link
U.S. Coast Guard – Sector Ohio Valley – Louisville, KY	Sector Ohio Valley Homeport Link
U.S. Coast Guard – Sector Upper Miss. River - St. Louis, MS	Sector Upper Mississippi River Homeport Link
U.S. Coast Guard - Marine Safety Unit – Paducah, KY	MSU Paducah Via Sector Ohio Valley Homeport
U.S. Coast Guard - Marine Safety Unit – Huntington, WV	MSU Huntington Via Sector Ohio Valley Homeport
U.S. Coast Guard – Sector Lower Mississippi River – Memphis, TN	Sector Lower Miss. River Homeport Link

3.B. Mississippi River Communications Plan

3.B.1. Upper Mississippi River

The River Industry Action Committee (RIAC) is a committee of the Upper Mississippi River and the lower Ohio River towing companies, formed to address navigation problems during significant changes in river conditions such as extreme low water and high water events. The committee has evolved to address all issues concerning the Upper Mississippi River and lower Ohio River navigation and is the major liaison between the towing industry, the Coast Guard, and the Army Corps of Engineers for river conditions between St. Louis, MO and Cairo, IL. RIAC is coordinated by a volunteer chairman from industry.

3.B.1.a. Upper Mississippi River Towing Industry Communications Plan (RIAC)

COMPANY / ORGANIZATION	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
American Commercial Barge Line (ACBL)			Contact information available in password protected version	
River Marine Enterprises				
Ingram Barge Co.				
Tennessee Valley Towing				
Marquette Transportation				
Kirby Inland Marine				
AEP Memco				
Crouse Corporation				
United Barge Line				
ARTCO				

Luhr Brothers, Inc.				
---------------------	--	--	--	--

3.B.1.b. Upper Mississippi River Government Agency Communications Plan

GOVERNMENT AGENCY	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
U.S. Coast Guard			Contact information available in password protected version	
Sector Ohio Valley				
Sector Command				
U.S. Coast Guard Sector Ohio Valley Buoy Tenders				
U.S. Coast Guard MSU Paducah				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers St. Louis District Office				
U.S. Army Corps of Engineers Louisville District Office				

U.S. Army Corps of Engineers Louisville District Office				
U.S. Army Corps of Engineers Cairo, IL GAUGE Reading				
Cape Girardeau, MO City Planner Flood Protection Project Levee Manager				
U.S. Army Corps of Engineers Memphis District Birds Point Protection Project Levee Manager				

3.B.1.c. Upper Mississippi River Internet Information Communications Plan

INTERNET SITE PURPOSE	ADDRESS
River Industry Bulletin Board (R.I.B.B.)	http://www.ribb.com/index.php
National Response Center (NRC) – Report Pollution / Terrorist Activity	http://www.nrc.uscg.mil/nrchp.html
Ohio River Lock & Dam Vessel Queues	http://www.ribb.com/riverstatus/river_locks.php
National Weather Service (NWS) – River Forecasts	http://www.riverwatch.noaa.gov/u_mississippi.shtml
U.S. Army Corps of Engineers – River Gauges	http://mvs-wc.mvs.usace.army.mil/trans/gages.html
U.S. Army Corps of Engineers – River Navigation Charts	http://www.mvs.usace.army.mil/navigation1/chartsmaps.html
The River School – River Training & Orientation	http://www.riverschool.com/
Incident Command System (ICS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslst.asp
National Incident Management System (NIMS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslst.asp
U.S. Coast Guard Port Security Directorate (MTSA Info)	https://homeport.uscg.mil/mycg/portal/ep/channelView.do?channelId=-24885&channelPage=%2Fep%2Fchannel%2Fdefault.jsp&pageTypeId=13489
U.S. Coast Guard – Eighth District Site – New Orleans, LA	Sector New Orleans Homeport Link
U.S. Coast Guard – Sector Ohio Valley – Louisville, KY	Sector Ohio Valley Homeport Link
U.S. Coast Guard – Sector Upper Miss. River - St. Louis, MS	Sector Upper Mississippi River Homeport Link
U.S. Coast Guard - Marine Safety Unit – Paducah, KY	MSU Paducah Via Sector Ohio Valley Homeport
U.S. Coast Guard – Sector Lower Mississippi River – Memphis, TN	Sector Lower Miss. River Homeport Link
U.S. Army Corps of Engineers - Hydro Survey Data:	http://www.mvs.usace.army.mil/navigation1/surveys.html
U.S. Army Corps of Engineers - Navigation Information Connection:	http://www2.mvr.usace.army.mil/nic2/default.cfm
U.S. Army Corps of Engineers - Weekly Navigation Status Reports:	http://www.mvs.usace.army.mil/navigation1/status%20reports.html

3.B.2. Lower Mississippi River

Lower Mississippi River Committee (LOMRC) is a committee of the Lower Mississippi River and the lower Ohio River towing companies, formed to address navigation problems during significant changes in river conditions such as extreme low water and high water events. The committee has evolved to address all issues concerning the Lower Mississippi River and lower Ohio River navigation and is the major liaison between the towing industry, the Coast Guard, and the Army Corps of Engineers for river conditions between Cairo, IL and Memphis, TN. LOMRC is coordinated by a volunteer chairman from industry.

3.B.2.a. Lower Mississippi River Towing Industry Communications Plan (LOMRC)

COMPANY / ORGANIZATION	DESIGNATED CONTACT	OFFICE PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
Ingram Barge Co.			Contact information available in password protected version	
AEP Memco				
Marquette Transportation				
Kirby Inland Marine				
United Barge Line				
ARTCO				
American Commercial Barge Line (ACBL)				
Luhr Brothers, Inc.				
Alter Barge Line				
Canal Barge Line				
Magnolia Marine				
Ergon Marine				

Florida Marine				
----------------	--	--	--	--

3.B.2.b. Lower Mississippi River Government Agency Communications Plan

GOVERNMENT AGENCY	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
U.S. Coast Guard Sector Ohio Valley Sector Command			Contact information available in password protected version	
U.S. Coast Guard Sector Ohio Valley Buoy Tenders				
U.S. Coast Guard MSU Paducah				
U.S. Army Corps of Engineers Cairo, IL GAUGE Reading				
U.S. Army Corps of Engineers Nashville District				

3.B.2.c. Lower Mississippi River Internet Information Communications Plan

INTERNET SITE PURPOSE	ADDRESS
River Industry Bulletin Board (R.I.B.B.)	http://www.ribb.com/index.php
National Response Center (NRC) – Report Pollution / Terrorist Activity	http://www.nrc.uscg.mil/nrchp.html
Ohio River Lock & Dam Vessel Queues	http://www.ribb.com/riverstatus/river_locks.php
National Weather Service (NWS) – River Forecasts	http://www.srh.noaa.gov/lmrfc/?n=lmrfc-mississippiandohioriverforecast
U.S. Army Corps of Engineers – River Gauges	http://www.lrd-wc.usace.army.mil/text/navrpti.txt
U.S. Army Corps of Engineers – River Navigation Charts	http://www.mvs.usace.army.mil/navigation1/chartsmaps.html
The River School – River Training & Orientation	http://www.riverschool.com/
Incident Command System (ICS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
National Incident Management System (NIMS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
U.S. Coast Guard Port Security Directorate (MTSA Info)	https://homeport.uscg.mil/mycg/portal/ep/channelView.do?channelId=-24885&channelPage=%2Fep%2Fchannel%2Fdefault.jsp&pageTypeId=13489
U.S. Coast Guard – Eighth District Site – New Orleans, LA	Sector New Orleans Homeport Link
U.S. Coast Guard – Sector Ohio Valley – Louisville, KY	Sector Ohio Valley Homeport Link
U.S. Coast Guard – Sector Upper Miss. River - St. Louis, MS	Sector Upper Mississippi River Homeport Link
U.S. Coast Guard - Marine Safety Unit – Paducah, KY	MSU Paducah Via Sector Ohio Valley Homeport
U.S. Coast Guard – Sector Lower Mississippi River – Memphis, TN	Sector Lower Miss. River Homeport Link

3.C. Tennessee River Communications Plan

The Tennessee and Cumberland River Industry Committee (TCIC) MSD Nashville and MSU Paducah AOR serves as the primary committee for communicating among the towing companies operating on the Tennessee and Cumberland River within the Coast Guard Marine Safety Detachment Nashville and Marine Safety Unit Paducah Area of Responsibility. The TCIC Committee Chairman serves as the primary point of contact for relaying information, coordinating meetings, and setting up conference calls between all federal agencies and the towing industry. The primary purpose of the TCIC Committee is to address all issues concerning Tennessee and Cumberland River navigation and to act as the major liaison between the towing industry, the Coast Guard, the Tennessee Valley Authority and the Army Corps of Engineers throughout the Tennessee and Cumberland River Valley.

3.C.1. Tennessee River Towing Industry Communications Plan

COMPANY / ORGANIZATION	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
Tennessee and Cumberland River Industry Committee (TCIC)			Contact information available in password protected version	
Ingram Barge Co.				
Tennessee Valley Towing (TVT)				
Hunter Marine				
Crouse Corporation				
American Commercial Barge Line (ACBL)				
Serodino				
Canal Barge Lines				
Magnolia Marine				

3.C.2. Tennessee River Government Agencies Communications Plan

GOVERNMENT AGENCY	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
U.S. Coast Guard Sector Ohio Valley Sector Command				
U.S. Coast Guard Sector Ohio Valley				

Buoy Tenders				
U.S. Coast Guard MSU Paducah			Contact information available in password protected version	
U.S. Coast Guard MSD Nashville				
U.S. Army Corps of Engineers Louisville District Office				
U.S. Army Corps of Engineers Nashville District				
U.S. Army Corps of Engineers Louisville District Smithland Lock and Dam				
U.S. Army Corps of Engineers Louisville District Area Lockmaster LD52/53/Olmsted				
U.S. Army Corps of Engineers Louisville District LD 52				
U.S. Army Corps of Engineers Louisville District LD 53				
U.S. Army Corps of Engineers Nashville District (Tennessee Locks / Cumberland Locks and Dams)				
Tennessee Valley Authority (Tennessee Locks and Dams)				

3.C.3. Tennessee River Internet Information Communications Plan

INTERNET SITE PURPOSE	ADDRESS
River Industry Bulletin Board (R.I.B.B.)	http://www.ribb.com/index.php
National Response Center (NRC) – Report Pollution / Terrorist Activity	http://www.nrc.uscg.mil/nrchp.html
Ohio River Lock & Dam Vessel Queues	http://www.ribb.com/riverstatus/river_locks.php
Kentucky / Barkley Lock & Dam Information	http://explorekentuckylake.com/weather.htm
National Weather Service (NWS) – River Forecasts	http://www.srh.noaa.gov/lmrfc/forecast/rva.shtml
U.S. Army Corps of Engineers – River GAUGES	http://www.lrd-wc.usace.army.mil/text/navrpti.txt
U.S. Army Corps of Engineers – River Navigation Charts	http://www.lrl.usace.army.mil/
Tennessee Valley Authority (TVA) – TNR / CMR	http://www.tva.gov/river/lakeinfo/index.htm
Tennessee Valley Authority (TVA) – Barkley L&D Flows	http://lakeinfo.tva.gov/htbin/lakeinfo?site=BAH&DataType=All&submit=View+info
Tennessee Valley Authority (TVA) – Kentucky L&D Flows	http://lakeinfo.tva.gov/htbin/lakeinfo?site=KYH&DataType=All&submit=View+info
The River School – River Training & Orientation	http://www.riverschool.com/
Incident Command System (ICS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
National Incident Management System (NIMS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
U.S. Coast Guard Port Security Directorate (MTSA Info)	https://homeport.uscg.mil/mycg/portal/ep/channelView.do?channelId=-24885&channelPage=%2Fep%2Fchannel%2Fdefault.jsp&pageTypeId=13489
U.S. Coast Guard – Eighth District Site – New Orleans, LA	Sector New Orleans Homeport Link
U.S. Coast Guard – Sector Ohio Valley – Louisville, KY	Sector Ohio Valley Homeport Link
U.S. Coast Guard - Marine Safety Unit – Paducah, KY	MSU Paducah Via Sector Ohio Valley Homeport

3.D. Cumberland River Communications Plan

The Tennessee and Cumberland River Industry Committee (TCIC) MSD Nashville and MSU Paducah AOR serves as the primary committee for communicating among the towing companies operating on the Tennessee and Cumberland River within the Coast Guard Marine Safety Detachment Nashville and Marine Safety Unit Paducah Area of Responsibility. The TCIC Committee Chairman serves as the primary point of contact for relaying information, coordinating meetings, and setting up conference calls between all federal agencies and the towing industry. The primary purpose of the TCIC Committee is to address all issues concerning Tennessee and Cumberland River navigation and to act as the major liaison between the towing industry, the Coast Guard, the Tennessee Valley Authority and the Army Corps of Engineers throughout the Tennessee and Cumberland River Valley.

3.D.1. Cumberland River Towing Industry Communications Plan

COMPANY / ORGANIZATION	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
Tennessee and Cumberland River Industry Committee (TCIC)			Contact information available in password protected version	
Ingram Barge Co.				
Tennessee Valley Towing (TVT)				
Hunter Marine				
Crouse Corporation				
American Commercial Barge Line (ACBL)				

Serodino			Contact information available in password protected version	
Canal Barge Lines				
Magnolia Marine				
Volunteer Barge & Transport, Inc.				

3.D.2. Cumberland River Government Agencies Communications Plan

GOVERNMENT AGENCY	DESIGNATED CONTACT	PHONE NUMBER	E-MAIL ADDRESS	WHEN CONTACTED
U.S. Coast Guard Sector Ohio Valley Sector Command			Contact information available in password protected version	
U.S. Coast Guard Sector Ohio Valley Buoy Tenders				
U.S. Coast Guard MSU Paducah				
U.S. Coast Guard MSD Nashville				
U.S. Army Corps of Engineers Louisville District Office				
U.S. Army Corps of Engineers Nashville District				
U.S. Army Corps of Engineers Louisville District Smithland Lock and Dam				
U.S. Army Corps of Engineers Louisville District Area Lockmaster LD52/53/Olmsted				
U.S. Army Corps of Engineers Louisville District Lock and Dam 52				
U.S. Army Corps of Engineers Louisville District Lock and Dam 53				
U.S. Army Corps of Engineers Nashville District (Tennessee Locks / Cumberland Locks and Dams)				
Tennessee Valley Authority (Tennessee Locks and Dams)				

3.D.3. Cumberland River Internet Information Communications Plan

INTERNET SITE PURPOSE	ADDRESS
River Industry Bulletin Board (R.I.B.B.)	http://www.ribb.com/index.php
National Response Center (NRC) – Report Pollution / Terrorist Activity	http://www.nrc.uscg.mil/nrchp.html
Ohio River Lock & Dam Vessel Queues	http://www.ribb.com/riverstatus/river_locks.php
Kentucky / Barkley Lock & Dam Information	http://explorekentuckylake.com/weather.htm
National Weather Service (NWS) – River Forecasts	http://water.weather.gov/ahps2/index.php?wfo=ohx
U.S. Army Corps of Engineers – River Gauges	http://www.lrd-wc.usace.army.mil/text/lourpti.txt
U.S. Army Corps of Engineers – River Navigation Charts	http://www.lrl.usace.army.mil/
Tennessee Valley Authority (TVA) – TNR / CMR	http://www.tva.gov/river/lakeinfo/index.htm
Tennessee Valley Authority (TVA) – Barkley L&D Flows	http://lakeinfo.tva.gov/htbin/lakeinfo?site=BAH&DataType=All&submit=View+info
Tennessee Valley Authority (TVA) – Kentucky L&D Flows	http://lakeinfo.tva.gov/htbin/lakeinfo?site=KYH&DataType=All&submit=View+info
The River School – River Training & Orientation	http://www.riverschool.com/
Incident Command System (ICS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
National Incident Management System (NIMS) Courses – Response Training	http://training.fema.gov/EMIWEB/IS/crslist.asp
U.S. Coast Guard Port Security Directorate (MTSA Info)	https://homeport.uscg.mil/mycg/portal/ep/channelView.do?channelId=-24885&channelPage=%2Fep%2Fchannel%2Fdefault.jsp&pageTypeId=13489
U.S. Coast Guard – Eighth District Site – New Orleans, LA	Sector New Orleans Homeport Link
U.S. Coast Guard – Sector Ohio Valley – Louisville, KY	Sector Ohio Valley Homeport Link
U.S. Coast Guard - Marine Safety Unit – Paducah, KY	MSU Paducah Via Sector Ohio Valley Homeport

4. Action Plan

Actions taken during waterways crisis span a wide range of controls and responses from all involved parties including industry and federal government agencies. In general, actions taken by industry will be intended to reduce marine casualties during low & high water situations. Some actions taken by industry during extreme low water conditions include reducing loads or lightering barges, which reduce vessel drafts. During high water conditions, industry may reduce tow sizes to allow more positive control over the tow to more effectively utilize towboat horsepower. The federal government, including the U.S. Coast Guard, U.S. Army Corps of Engineers, and the Tennessee Valley Authority, is also required to take specific and timely actions to aid in preventing marine casualties while facilitating commerce. Some of these actions include the USCG's issuance of Broadcast Notice to Mariners (BNM), establishment of Safety Zones, dredging operations by the USACE, and adjustment of flow rates from locks and dams by the Tennessee Valley Authority (TVA). The enclosed Safety Advisory and Safety Zone templates are recommended for use, but can be modified or combined to meet the needs of the situation.

4.A. Ohio River Action Plan

4.A.1. Emsworth Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>EMSWORTH LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 6.2</p> <p>FLOOD STAGE READING: 30' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 16' ON UG & 12' ON LG MAX. DAM OPENING 105' CEASE LOCKING 30' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH THE LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: SEVERE OUTDRAFT DURING HIGH WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	65' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	65'+DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	85'+ DAM OPENING	Rising & projected to continue rising rapidly	Extreme High Water/Extreme High Flow Conditions	Action	Continue monitoring river conditions. MSU Pittsburgh will submit a Safety Advisory request to the SCC. The SCC will initiate a Safety Advisory (Enc. 2) and cancel Safety Advisory (Enc. 1). Note: Double lockages restricted to a maximum of three barge lengths at 90' of dam opening and a maximum of two barge lengths between 90' – 94'. * No restrictions with helper boat.
	95'+ DAM OPENING	Rising & projected to continue rising rapidly	Extreme High Water/Extreme High Flow Conditions	Action	Continue monitoring river conditions, continue broadcasting Safety Advisories (Enc. 2). Note: Small lock chamber taken out of operation when dam openings exceed 95'. Double lockages restricted to a maximum of one barge length at and above 95' of dam opening. * No restrictions with helper boat.
	95'- DAM OPENING	Falling	High Water/ High Flow Conditions	Watch	Continue monitoring river conditions, continue broadcasting Safety Advisories (Enc. 2).
	85'- DAM OPENING	Falling	High Water/ High Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 2) when below 85' and initiating Safety Advisory (Enc. 1). Consider canceling Safety Advisory (Enc. 1) when below 65'. * Use template (Enc. 3) for BNM cancellations.

OHIO RIVER - EMSWORTH L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT EMSWORTH DAM MILE MARKER 6.2 OHIO RIVER. THE GATE OPENING AT EMSWORTH DAM READS GREATER THAN 65 FEET. FOR VESSELS TRANSITING THE OHIO RIVER, WHEN TRANSITING DOWNRIVER WITH THE INTENTION OF USING THE FRONT CHANNEL PAST BRUNOT ISLAND, MILE MARKER 1.5, KEEP TOWARDS THE RIGHT DESCENDING BANK WHILE ENTERING THE FRONT CHANNEL TO AVOID SEVERE SET TOWARDS THE ISLAND. WHEN TRANSITING UPRIVER WITH THE INTENTION OF USING THE BACK CHANNEL PAST BRUNOT ISLAND, MILE MARKER 3, EXERCISE CAUTION WHILE ENTERING THE BACK CHANNEL TO PREVENT BEING SET AGAINST THE LEFT DESCENDING BANK. EXERCISE CAUTION AND ENSURE VERTICAL CLEARANCE IS SUFFICIENT WHILE TRANSITING UNDER BRIDGES LOCATED BETWEEN MILE MARKERS 0 AND 3 ALLEGHENY RIVER AND BETWEEN MILE MARKERS 0 AND 9 MONONGAHELA RIVER.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT EMSWORTH DAM MILE MARKER 6.2 OHIO RIVER. THE GATE OPENING AT EMSWORTH DAM READS GREATER THAN 85 FEET. FOR VESSELS TRANSITING THE OHIO RIVER, WHEN TRANSITING DOWNRIVER WITH THE INTENTION OF USING THE FRONT CHANNEL PAST BRUNOT ISLAND, MILE MARKER 1.5, KEEP TOWARDS THE RIGHT DESCENDING BANK WHILE ENTERING THE FRONT CHANNEL TO AVOID SEVERE SET TOWARDS THE ISLAND. WHEN TRANSITING UPRIVER WITH THE INTENTION OF USING THE BACK CHANNEL PAST BRUNOT ISLAND, MILE MARKER 3, EXERCISE CAUTION WHILE ENTERING THE BACK CHANNEL TO PREVENT BEING SET AGAINST THE LEFT DESCENDING BANK. ENSURE VERTICAL CLEARANCE IS SUFFICIENT WHILE TRANSITING UNDER BRIDGES LOCATED BETWEEN MILE MARKERS 0 AND 3 ALLEGHENY RIVER AND BETWEEN MILE MARKERS 0 AND 9 MONONGAHELA RIVER. EXERCISE CAUTION WHILE TRANSITING IN THE AREA OF THE EMSWORTH AND DASHIELDS LOCK AND DAMS, MILE MARKERS 13.3 TO 15, DUE TO THE STRONG CURRENTS IN THE AREA. SOUTHBOUND TOW VESSELS ARE RECOMMENDED TO HAVE A HELPER BOAT PRESENT TO ASSIST WHEN EITHER, (1) PUSHING A TOW CONSISTING OF TWO BARGE LENGTHS OR GREATER WHEN AT LEAST ONE BARGE IS A TANK BARGE OR, (2) CONDUCTING A DOUBLE LOCKAGE THROUGH EMSWORTH, DASHIELDS, OR MONTGOMERY LOCKS.

HIGH WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM_____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.2. Dashields Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p align="center">DASHIELDS LOCK & DAM</p> <p align="center">OHIO RIVER MILE MARKER: 13.3</p> <p align="center">FLOOD STAGE READING: 23' UG</p> <p>OTHER USEFUL DATA: NORMAL POOL 12' ON UG & 12' ON LG CEASE LOCKING 23' UG</p> <p>TABLE USES UPPER AND LOWER GAUGE READINGS TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL ALLISIONS WITH THE LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: SEVERE OUTDRAFT DURING HIGH WATER. OUTDRAFT INCREASES AS RIVER RISES.</p> <p>CAUTIONARY NOTE 2: MARINERS ARE ALSO ADVISED TO CLOSELY MONITOR CONDITIONS AND DAM OPENINGS AT EMSWORTH LOCK AND DAM, WHILE TRANSITTING IN THE VICINITY OF DASHIELDS. UNEXPECTED INCREASES IN FLOW, CURRENT AND SEVERE OUTDRAFTS DURING HIGH WATER CONDITIONS, MAY BE ENCOUNTERED.</p> <p>USACE GAUGE READINGS REPORT</p>	20' UG	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	20'+ UG	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	24'+ UG	Rising & projected to continue rising rapidly	Extreme High Water/ Extreme High Flow Conditions	Action	Continue monitoring river conditions, continue broadcasting Safety Advisory (Enc. 1).
	24' - UG	Falling	High Water/ High Flow Conditions	Watch	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1). * Use template (Enc. 3) for BNM cancellations.
	20' - UG	Falling	Normal Operations/ Flow Conditions	Recovery	Locking operations normal.

OHIO RIVER - DASHEILDS L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT DASHIELDS DAM MILE MARKER 13.3 OHIO RIVER. THE UPPER GAUGE AT DASHIELDS DAM READS GREATER THAN 20 FEET. FLEETING FACILITIES ARE ADVISED TO (1) REVIEW AND ACT IN ACCORDANCE WITH THEIR WATERFRONT FLEET OPERATIONS GUIDE AND ANY COMPANY CONTINGENCY PLANS, (2) TO ASSIGN A PERSON TO BE IN CONTINUOUS SURVEILLANCE AND TO OBSERVE THE BARGES IN THE FLEETING FACILITY, (3) DOUBLE-UP LINES ON THE HEAD OF THE FLEET AND PROVIDE AN ADEQUATE NUMBER OF SPRING AND BREAST LINES BETWEEN THE DOCK AND THE BARGES IN THE FLEET, AND (4) REVIEW THEIR NEED TO SECURE TOWBOAT ASSISTANCE.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM_____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.3. Montgomery Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p align="center">MONTGOMERY LOCK & DAM</p> <p align="center">OHIO RIVER MILE MARKER: 31.7</p> <p align="center">FLOOD STAGE READING: 33' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 12' ON UG & 12' ON LG CEASE LOCKING 20' UG MAX. DAM OPENING 100'</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH THE LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: SEVERE OUTDRAFT DURING HIGH WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	40' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	40'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	65'+ DAM OPENING	Rising & projected to continue rising rapidly	Extreme High Water/ Extreme High Flow Conditions	Action	Continue monitoring river conditions. MSU Pittsburgh will submit a Safety Advisory request to the SCC. The SCC will initiate a Safety Advisory (Enc. 2) and cancel Safety Advisory (Enc. 1). When dam openings exceed 65', small lock chamber taken out of operations and no up bound double lockages without the assistance of a helper boat.
	65' - DAM OPENING	Falling	High Water/ High Flow Conditions	Watch	Continue monitoring river conditions, cancel Safety Advisory (Enc. 2) and initiate Safety Advisory (Enc. 1).
	40' - DAM OPENING	Falling	Normal Operations/ Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1). * Use template (Enc. 3) for BNM cancellations.

OHIO RIVER - MONTGOMERY L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT MONTGOMERY DAM, MILE MARKER 31.7, OHIO RIVER. THE GATE OPENING AT MONTGOMERY DAM IS GREATER THAN 40 FEET. EXERCISE CAUTION WHILE TRANSITING UNDER THE NEWELL HIGHWAY BRIDGE MILE MARKER 44.5 DUE TO THE STRONG SET AND CURRENTS IN THAT AREA. UPBOUND TOW VESSELS ARE ADVISED THAT WHEN PERFORMING A SET OVER OR KNOCK OUT THROUGH THE MONTGOMERY LOCKS, TO SECURE THE HEAD OF THEIR TOWS TO THE LOCK WALL USING THE CLOSEST PIN POSSIBLE BEFORE THE SET OVER OR KNOCK OUT IS INITIATED, AND ENSURE THAT TOWS ARE FULLY SECURED PRIOR TO LEAVING THE VICINITY OF THE LOCKS. DOWNBOUND TOW VESSELS PERFORMING A DOUBLE LOCKAGE ARE STRONGLY ADVISED TO HAVE A HELPER BOAT ASSIST THE TOWS IN KEEPING ALONGSIDE THE GUIDE WALL WHILE ENTERING THE LOCKS.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT MONTGOMERY DAM, MILE MARKER 31.7, OHIO RIVER. THE GATE OPENING AT MONTGOMERY DAM IS GREATER THAN 65 FEET. EXERCISE CAUTION WHILE TRANSITING UNDER THE NEWELL HIGHWAY BRIDGE, MILE MARKER 44.5, AND THE P.L.&E. RAILROAD BRIDGE, MILE MARKER 25.8, DUE TO THE STRONG SET AND CURRENTS IN THOSE AREAS. TOW VESSELS ARE RECOMMENDED TO HAVE A HELPER BOAT WHEN TRANSITING THROUGH THE MONTGOMERY LOCKS, IF THEY ARE PUSHING TWO BARGE LENGTHS OR GREATER. UPBOUND TOW VESSELS ARE ADVISED THAT WHEN PERFORMING A SET OVER OR KNOCK OUT THROUGH THE MONTGOMERY LOCKS, TO SECURE THE HEAD OF THEIR TOWS TO THE LOCK WALL USING THE CLOSEST PIN POSSIBLE BEFORE THE SET OVER OR KNOCK OUT IS INITIATED, AND ENSURE THAT TOWS ARE FULLY SECURED PRIOR TO LEAVING THE VICINITY OF THE LOCKS. DOWNBOUND TOW VESSELS PERFORMING A DOUBLE LOCKAGE ARE STRONGLY ADVISED TO HAVE A HELPER BOAT ASSIST THE TOWS IN KEEPING ALONGSIDE THE GUIDE WALL WHILE ENTERING THE LOCKS.

HIGHWATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM_____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.4. New Cumberland Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>NEW CUMBERLAND LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 54.4</p> <p>FLOOD STAGE READING: 37' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 12' ON UG & 12' ON LG CEASE LOCKING 37' LG MAX. DAM OPENING 143'</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH THE LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: OUTDRAFTS DURING HIGH WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	50' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	50'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	50'- DAM OPENING	Falling	Normal Operations/ Flow Conditions	Recovery	Continue monitoring river conditions, consider canceling Safety Advisory (Enc. 1). * Use template (Enc. 2) for BNM cancellations.

OHIO RIVER - NEW CUMBERLAND L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT NEW CUMBERLAND DAM, MILE MARKER 54.4, OHIO RIVER. THE GATE OPENING AT NEW CUMBERLAND DAM IS GREATER THAN 50 FEET. EXERCISE CAUTION WHILE TRANSITING PAST BROWNS ISLAND, MILE MARKERS 60.5 TO 64, DUE TO THE NARROW CHANNEL, ABUNDANCE OF FLEETING AREAS, AND FAST CURRENTS IN THAT AREA. EXERCISE CAUTION WHILE TRANSITING PAST CABLES EDDY, MILE MARKERS 64.5 TO 65.5, DUE TO THE NARROW CHANNEL AND SHARP BEND IN THAT AREA.

HIGH WATER Enclosure 2 (Example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.5. Pike Island Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>PIKE ISLAND LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 54.4</p> <p>FLOOD STAGE READING: 37' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 12' ON UG & 12' ON LG CEASE LOCKING 37' LG MAX. DAM OPENING 194'</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH THE LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: OUTDRAFTS DURING EXTREME HIGH WATER.</p> <p>CAUTIONARY NOTE 2: DURING LOW WATER, UPBOUND TOWS ARE REMINDED TO BE CAUTIOUS OF OUTDRAFTS TOWARDS THE RIVER WALL.</p> <p>USACE GAUGE READINGS REPORT</p>	50' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	50'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	50' - DAM OPENING	Falling	Normal Operations/ Flow Conditions	Recovery	Continue monitoring river conditions, consider canceling Safety Advisory (Enc. 1). * Use template (Enc. 2) for BNM cancellations

OHIO RIVER - PIKE ISLAND L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT PIKE ISLAND DAM, MILE MARKER 84.2, OHIO RIVER. THE GATE OPENING AT PIKE ISLAND DAM IS GREATER THAN 50 FEET. EXERCISE CAUTION WHILE TRANSITING UNDER THE I-470 BRIDGE, MILE MARKER 91.8, DUE TO THE STRONG SET TOWARDS THE LEFT DESCENDING BANK IN THAT AREA. EXERCISE CAUTION WHILE TRANSITING UNDER THE CSX RAILROAD BRIDGE, MILE MARKER 94.5, DUE TO ITS LIMITED HORIZONTAL CLEARANCE OF 320 FEET. IF PUSHING AHEAD, TOW VESSELS ARE RECOMMENDED TO HAVE A HELPER BOAT WHEN TRANSITING UNDER THE CSX RAILROAD BRIDGE TO ENSURE THEY MAINTAIN PROPER COURSE AND SPEED.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM_____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.6. Hannibal Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">HANNIBAL LOCK & DAM</p> <p style="text-align: center;">OHIO RIVER MILE MARKER: 126.4</p> <p style="text-align: center;">FLOOD STAGE READING: 35.0 LG.</p> <p>OTHER USEFUL DATA: MAX OPENING 172.8' GATES ALL OUT 32.0' CEASE LOCKING 37.0' LG 17.0' UG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH HANNIBAL L&D TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH</p> <p>CAUTIONARY NOTE 2: WHEN MAKING A SOUTHBOUND APPROACH BE ALERT TO CURRENTS SETTING TOWARD THE ARRIVAL CELLS.</p> <p>CAUTIONARY NOTE 3: OUTDRAFTS MAY BE SEVERE WHEN GATE OPENING IS GREATER THAN 40'</p> <p>CAUTIONARY NOTE 4: 3000 CFS THROUGH THE HYDRO IS EQUAL TO 1' OF GATE OPENING</p> <p>USACE GAUGE READINGS REPORT</p>	< 40' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	40' + DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	100'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, and presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	100' - DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	40' - DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - HANNIBAL L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF HANNIBAL LOCK AND DAM, MILE MARKER 126.4, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.7. Willow island Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>WILLOW ISLAND LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 161.7</p> <p>FLOOD STAGE READING: 37' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 176' GATES ALL OUT 34.5' LG CEASE LOCKING 41.4' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH WILLOW ISLAND L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 150' OF GATE OPENING.</p> <p>GAUGE READINGS REPORT: USACE GAUGE READINGS REPORT</p>	<50' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	50'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	100'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	100'- DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	50'- DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - WILLOW ISLAND L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF WILLOW ISLAND LOCK AND DAM, MILE MARKER 161.7, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF WILLOW ISLAND LOCK AND DAM, MILE MARKER 161.7, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GAUGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.7.a. Parkersburg-Belpre Highway Bridge High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">Parkersburg-Belpre Highway Bridge B&O Rail Road Bridge Parkersburg Highway Bridge</p> <p style="text-align: center;">MILE MARKER:185-183</p> <p style="text-align: center;">Reference: WILLOW ISLAND LOCK & DAM</p> <p style="text-align: center;">FLOOD STAGE READING: 37' LG off of WILLOW ISLAND L&D</p> <p>OTHER USEFUL DATA Attained Willow Island L&D: MAX OPENING 176' GATES ALL OUT 33' LG CEASE LOCKING 33' LG</p> <p>THE TABLE USES DAM OPENING AT WILLIOW ISLAND L&D. THE POTENTIAL FOR VESSEL ALLISIONS WITH THESE BRIDGES TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS AND INCREASED DRAFTING TOWARD BRIDGE PIERS. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT MINIMUM SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: CONSIDER HORSEPOWER CAPABILITY, TOW SIZE, REGENCY THROUGH THE AREA, AND POTENTIAL EFFECTS OF STRONG CURRENTS WHILE NAVIGATING.</p> <p>CAUTIONARY NOTE 2: WHEN THE GATE OPENING AT WILLOW ISLAND L&D EXCEEDS 100' THE COAST GUARD, IN CONJUNCTION WITH THE HDWA, RECOMMENDS LOADED TOWS OF 800' OR GREATER CONSIDER TRANSITING MILES 183-185 OHIO RIVER DAYLIGHT HOURS ONLY.</p> <p>USACE GAUGE READINGS REPORT</p>	<50' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	50'+ DAM OPENING	Rising & projected to continue rising rapidly.	High Water/ High Flow Conditions	Watch	When Watch Phase conditions exist at Willow Island L/D the COTP will coordinate with industry to determine the need to initiate the calling tree and /or a phone conference between the CG, USACE, and HDWA. During this phone conference, topics that will be discussed are the water conditions, tow restrictions or assistance needed for navigating under the Parkersburg-Belpre Highway Bridge, B&O Rail Road Bridge and the Parkersburg Highway Bridge. All concerns and future actions should also be discussed. Future weather forecasts and river stages will be reviewed and river conditions will be assessed for future actions/considerations. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	100'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, US USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, presence of ice, weather conditions, and tow restrictions or assistance needed for navigating under the Parkersburg-Belpre Highway, B&O Rail Road Bridge and the Parkersburg Highway Bridge. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Cancel Safety Advisory (Enc. 1) and issue Safety Advisory (Enc. 2)
	100'- DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions/assistance as appropriate. Consider canceling Safety Advisory (Enc. 2) and issuing Safety Advisory (Enc. 1).
	50'- DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	When Recovery Phase conditions exist at Willow Island L/D, the CG, USACE and HDWA will coordinate to ensure a proper recovery and timely return to normal operations. Topics of discussion should be current and future river conditions, channel surveys if necessary, recovery/salvage of sunken barges, and discuss any changes necessary for future events. Consider canceling Safety Advisory (Enc. 1).

OHIO RIVER - PARKERSBURG-BELPRE HIGHWAY BRIDGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE BRIDGES AT PARKERSBURG, MILE MARKERS 183 TO 185, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, INCREASED DRAFTING TOWARD BRIDGE PIERS, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE BRIDGES AT PARKERSBURG, MILE MARKERS 183 TO 185, OHIO RIVER. THE GATE OPENING AT WILLOW ISLAND LOCK AND DAM, MILE MARKER 161.7, EXCEEDS 100 FEET. TOWS OF 800 FEET OR GREATER ARE RECOMMENDED TO TRANSIT MILE MARKERS 183 TO 185 DURING DAYLIGHT HOURS ONLY. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, INCREASED DRAFTING TOWARD BRIDGE PIERS, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 3 (example)

CANCEL BNM_____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.8. Belleville Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>BELLEVILLE LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 203.9</p> <p>FLOOD STAGE READING: 45' LG</p> <p>OTHER USEFUL DATA: MAX OPENING: 176' GATES ALL OUT 33' LG CEASE LOCKING 43.0' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH BELLEVILLE L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 150' OF GATE OPENING.</p> <p>USACE GAUGE READINGS REPORT</p>	60' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	60'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	90'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, and presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: Ohio River MM 209 – 211(long bottom bend) recommended one way traffic
	90'- DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	60' DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - BELLEVILLE L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF BELLEVILLE LOCK AND DAM, MILE MARKER 203.9, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF BELLEVILLE LOCK AND DAM, MILE MARKER 203.9, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GAUGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.9. Racine Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>RACINE LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 237</p> <p>FLOOD STAGE READING: 38' LG</p> <p>OTHER USEFUL DATA: MAX OPENING: 200' GATES ALL OUT: 34' LG CEASE LOCKING: 49.9' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH RACINE L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 180' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 3: MM 265 TO 267 (MOUTH OF THE KANAWHA RIVER) IS A HIGH TRAFFIC AREA</p> <p>USACE GAUGE READINGS REPORT</p>	<50' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	50'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	150' DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, and presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: MM 245 to 247 (sliding hill bend) recommended one way traffic.
	150'- DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	50'- DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - RACINE L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF RACINE LOCK AND DAM, MILE MARKER 237, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF RACINE LOCK AND DAM, MILE MARKER 237, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GAUGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.10. Robert C. Byrd Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p align="center">ROBERT C. BYRD LOCK & DAM</p> <p align="center">OHIO RIVER MILE MARKER: 279.2</p> <p align="center">FLOOD STAGE READING: 50' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 144' GATES ALL OUT 33.5' LG CEASE LOCKING 53' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH ROBERT C. BYRD L&D TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: EXERCISE CAUTION DEPARTING CANAL UPBOUND IN HIGH FLOW CONDITIONS; HEAD OF LOADED TOW MAY DIVE.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 130' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 3: MM 265 TO 267 (MOUTH OF THE KANAWHA RIVER) IS A HIGH TRAFFIC AREA</p> <p>CAUTIONARY NOTE 4: MM 304 TO 328 (HUNTINGTON CATLETTSBURG HARBOR) IS A HIGH TRAFFIC AREA</p> <p>USACE GAUGE READINGS REPORT</p>	<40' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	40'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	144'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, and presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	144'- DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	40'- DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - ROBERT C. BYRD L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF R. C. BYRD LOCK AND DAM, MILE MARKER 279.2, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF R. C. BYRD LOCK AND DAM, MILE MARKER 279.2, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GAUGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.11. Greenup Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">GREENUP LOCK & DAM</p> <p style="text-align: center;">OHIO RIVER MILE MARKER: 341.0</p> <p style="text-align: center;">FLOOD STAGE READING: 54' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 242' GATES ALL OUT 42' LG CEASE LOCKING 59' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH GREENUP L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 180' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 3: MM 304 TO 328 (HUNTINGTON CATLETTSBURG HARBOR) IS A HIGH TRAFFIC AREA</p> <p>USACE GAUGE READINGS REPORT</p>	<100' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	100'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	200'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, and presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	200' - DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	100' - DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - GREENUP L&D

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF GREENUP LOCK AND DAM, MILE MARKER 341, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF GREENUP LOCK AND DAM, MILE MARKER 341, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GAUGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.12. Meldahl Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">MELDAHL LOCK & DAM</p> <p style="text-align: center;">OHIO RIVER MILE MARKER: 436.2</p> <p style="text-align: center;">FLOOD STAGE READING: 51' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 360' GATES ALL OUT 41.6' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH MELDAHL L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE ENTERING SOUTHBOUND LOCK CHAMBER. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: OUTDRAFT IS SEVERE AT APPROXIMATELY 300' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 2: WHEN TRANSITING BETWEEN MM 462 AND MM 473 MARINERS SHOULD BE AWARE OF A HIGH CONCENTRATION OF PLEASURE CRAFTS DURING SUMMER MONTHS AND SPECIAL EVENTS.</p> <p>CAUTIONARY NOTE 3: RADIO COMMUNICATIONS ARE POOR BETWEEN MM 462 AND MM 473. MARINERS ARE ADVISED TO USE ALL AVAILABLE MEANS OF COMMUNICATION TO ENSURE SAFE TRANSIT.</p> <p>USACE GAUGE READINGS REPORT</p>	60' DAM OPENING	Rising	Normal Operations/ Flow Conditions **Note 1**		Locking operations normal.
	60'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	90'+ DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Consider implementation of Safety Zone (Enc. 2). Factors to evaluate include rate of rise, amount of drift, presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: RNA (Enc. 3) is initiated when the Cincinnati Gauge reads 45'.
	90' - DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Consider Safety Advisory, (Enc. 1) versus Safety Zone (Enc. 2).
	60' - DAM OPENING	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory. (Enc. 1)

OHIO RIVER - MELDAHL LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF MELDAHL LOCK AND DAM, MILE MARKER 436.2, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE FROM _____ TO _____ ON THE OHIO RIVER. ALL MARINERS ARE TO PROCEED WITH CAUTION AND REMAIN IN THE NAVIGABLE CHANNEL ON THE OHIO RIVER DUE TO INCREASING WATER LEVELS. ALL VESSELS ARE TO MONITOR RIVER CONDITIONS AND ENSURE ADEQUATE HORSEPOWER FOR VESSEL TRANSITS. REPORT ALL MARINE CASUALTIES TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

CINCINNATI REGULATED NAVIGATION AREA

DUE TO THE HIGH WATER LEVEL AT THE CINCINNATI GAUGE BEING 45 FEET OR GREATER, A REGULATED NAVIGATION AREA IS IN EFFECT IN THE CINCINNATI HARBOR FROM MI 466.0 TO 473.0. ENTRY INTO THIS ZONE BY ALL D/B VESSELS TOWING CARGOES REGULATED BY TITLE 46 CFR SUBCHAPTER D AND O WITH A TOW LENGTH EXCEEDING 600 FEET, EXCLUDING TOWBOAT, ARE PROHIBITED FROM 1/2 HOUR BEFORE SUNSET TO 1/2 HOUR AFTER SUNRISE. IAW THE PROVISIONS OUTLINED IN TITLE 33 CFR 165.821, THIS REGULATED NAVIGATION AREA WILL REMAIN IN EFFECT UNTIL THE CINCINNATI GAUGE DROPS BELOW 45 FEET. ALL MARINERS ARE URGED TO USE CAUTION WHEN TRANSITING THIS AREA.

4.A. Ohio River Action Plan

4.A.13. Markland Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">MARKLAND LOCK & DAM</p> <p style="text-align: center;">OHIO RIVER MILE MARKER: 531.5</p> <p style="text-align: center;">FLOOD STAGE READING: 16' UG</p> <p>OTHER USEFUL DATA: MAX OPENING 480' GATES ALL OUT 47' LG CEASE LOCKING 55' LG</p> <p>TABLE USES A COMBINATION OF DAM OPENING AND LOWER GAUGE READINGS. THE POTENTIAL FOR VESSEL ALLISIONS WITH MARKLAND L&D TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE OUTDRAFT WHILE ENTERING SOUTHBOUND LOCK CHAMBER. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DOWNBOUND MARINERS NEED TO BE AWARE OF POCKET AND PROTRUDING POINT THAT HAS A POTENTIAL TO SADDLEBAG THE TOW ON THE LEFT DESCENDING BANK AT MM 531.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 400' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 3: WHEN TRANSITING BETWEEN MM 462 AND MM 473 MARINERS SHOULD BE AWARE OF A HIGH CONCENTRATION OF PLEASURE CRAFTS DURING SUMMER MONTHS AND SPECIAL EVENTS.</p> <p>CAUTIONARY NOTE 4: RADIO COMMUNICATIONS ARE POOR BETWEEN MM 462 AND MM 473. MARINERS ARE ADVISED TO USE ALL AVAILABLE MEANS OF COMMUNICATION TO ENSURE SAFE TRANSIT</p> <p>USACE GAUGE READINGS REPORT</p>	80' DAM OPENING	Rising	Normal Operations/Flow Conditions	Watch	Locking operations normal.
	80'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/Increased Flow Conditions	Watch	Consider for up river high water conference calls. COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	280'+ DAM OPENING	Rising	Extreme High Water/Extreme High Flow Conditions	Action	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Consider implementation of Safety Zone (Enc. 2). Factors to evaluate include rate of rise, amount of drift, presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: RNA (Enc. 3) is initiated when the Cincinnati Gauge reads 45'.
	280' - DAM OPENING	Falling	High Water/Increased Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Consider Safety Advisory, (Enc. 1) versus Safety Zone (Enc. 2).
	80' - DAM OPENING	Falling	Normal Operations/Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1).

OHIO RIVER - MARKLAND LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF MARKLAND LOCK AND DAM, MILE MARKER 531.5, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE FOR MARKLAND L/D, OHIO RIVER MILE MARKER 526.5 TO 536.5. THE MARKLAND L/D IS NAVIGABLE UNDER THE FOLLOWING CONDITIONS: ALL DOWNBOUND VESSELS ARE RESTRICTED TO DAYLIGHT HOURS ONLY WHILE TRANSITING THROUGH THE MARKLAND L/D. MINIMUM HP PER LOADED BARGE IS 250 HP. TOWS COMPRISED OF CARGOES REGULATED BY TITLE 46 CFR SUBCHAPTER D AND O (KNOWN AS RED FLAG BARGES) AND/OR MORE THAN 6 BARGES LOADED WITH ANY PRODUCT, ARE RESTRICTED TO DAYLIGHT TRANSIT ONLY. THE MARKLAND L/D LOCK OPERATOR WILL ESTABLISH THE TRANSIT QUEUE. TOWS SHOULD NOTIFY THE LOCK OPERATOR WHEN APPROACHING MARKLAND L/D. A CARRIER MAY REQUEST AN EXCEPTION TO THE ABOVE. REQUESTS SHOULD BE MADE DURING NORMAL BUSINESS HOURS TO THE CAPTAIN OF THE PORT OHIO VALLEY AT 1-800-253-7465. THE CAPTAIN OF THE PORT MAY CONSULT WITH THE CENTRAL OHIO RIVER MARINE INDUSTRY GROUP (CORMIG) CHAIRMAN, BUT IT WILL BE THE CAPTAIN OF THE PORT WHO WILL MAKE A FINAL DETERMINATION ON EACH REQUEST. MARINERS ARE ADVISED THAT FAILURE TO FOLLOW THIS REGULATION MAY RESULT IN A CIVIL PENALTY.

HIGH WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

CINCINNATI REGULATED NAVIGATION AREA

DUE TO THE HIGH WATER LEVEL AT THE CINCINNATI GAUGE BEING 45 FEET OR GREATER, A REGULATED NAVIGATION AREA IS IN EFFECT IN THE CINCINNATI HARBOR FROM MI 466.0 TO 473.0. ENTRY INTO THIS ZONE BY ALL D/B VESSELS TOWING CARGOES REGULATED BY TITLE 46 CFR SUBCHAPTER D AND O WITH A TOW LENGTH EXCEEDING 600 FEET, EXCLUDING TOWBOAT, ARE PROHIBITED FROM 1/2 HOUR BEFORE SUNSET TO 1/2 HOUR AFTER SUNRISE. IAW THE PROVISIONS OUTLINED IN TITLE 33 CFR 165.821, THIS REGULATED NAVIGATION AREA WILL REMAIN IN EFFECT UNTIL THE CINCINNATI GAUGE DROPS BELOW 45 FEET. ALL MARINERS ARE URGED TO USE CAUTION WHEN TRANSITING THIS AREA.

4.A. Ohio River Action Plan

4.A.14. McAlpine Lock and Dam High/Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">MCALPINE LOCK & DAM</p> <p style="text-align: center;">OHIO RIVER MILE MARKER: 606.8</p> <p style="text-align: center;">FLOOD STAGE READING: 23' UG</p> <p>OTHER USEFUL DATA: MAX OPENING 113' GATES ALL OUT 28'-30' LG CEASE LOCKING 66' LG</p> <p>TABLE USES A COMBINATION OF DAM OPENING AND LOWER GAUGE READING. THE POTENTIAL FOR VESSEL ALLISIONS WITH MCALPINE L&D TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE OUTDRAFT WHILE ENTERING SOUTHBOUND PORTLAND CANAL. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: THE VANE DYKE AT THE ENTRANCE TO THE LOUISVILLE AND PORTLAND CANAL AT OHR MM 604.3 EXPERIENCES STRONG OUTDRAFTS ON THE UP STREAM END DURING HIGH FLOWS.</p> <p>CAUTIONARY NOTE 2: SEDIMENT SHOALING FROM MM 606 TO 609 RESTRICTS VESSEL TRAFFIC AT 10' ON THE LOWER GAUGE; VESSELS SHOULD USE CAUTION WHEN TRANSITING THIS AREA.</p> <p>USACE GAUGE READINGS REPORT</p>	60' DAM OPENING	Rising	Normal Operations/ Flow Conditions	Watch	Locking operations normal.
	60' + DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	100'+ DAM OPENING or 13' UG	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Factors to evaluate include rate of rise, amount of drift, and presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: Safety Zone (Enc. 2) is initiated when the McAlpine L&D reaches 13.0' UG (VTS Louisville activated).
	100'- DAM OPENING or < 13' UG	Falling	High Water/Increased Flow Conditions	Watch	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Consider Safety Advisory, (Enc. 1) and cancel Safety Zone (Enc. 2) once river levels fall below 13' UG.
	60'- DAM OPENING	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).
	9.0' LG >20' DAM OPENING	Falling	Normal Operations/ Normal Flow Conditions	Watch	Locking operations normal.
	8.9' – 8.5' LG	Falling	Low Water / Low Flow Conditions	Watch	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG; discuss draft and tow size recommendations under falling river conditions. COTP Ohio Valley issues Safety Advisory (Enc. 3).
	8.5'- LG	Falling	Extreme low Water/ Extreme low Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Consider Safety Zone (Enc. 4) verses Safety Advisory (Enc. 3). Mile marker 637-677 may warrant one-way traffic during low water conditions.
	8.5' + LG	Rising	Low Water/ Low Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 3).

OHIO RIVER - McALPINE LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF MCALPINE LOCK AND DAM, MILE MARKER 606.8, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE VESSEL TRAFFIC SYSTEM LOUISVILLE, KY WAS ACTIVATED ON **DD MMM YY**. THIS SYSTEM IS FROM MI 593.0 TO 606.8 AND WILL REMAIN IN EFFECT WHILE MCALPINE L/D UPPER GAUGE READS 13.0 FT AND ABOVE. OPERATING PROCEDURES AND INSTRUCTIONS TO MARINERS ARE DESCRIBED IN 33 CFR 161.

LOW WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

SHOALING HAS BEEN REPORTED IN THE VICINITY OF MILE MARKER _____ OHIO RIVER ON THE (LDB/RDB). ON **DD MMM YY** THE MCALPINE L/D GAUGE READING WAS _____ FT AND FALLING. VESSELS ARE ADVISED TO EXERCISE CAUTION WHEN TRANSITING THE MCALPINE L/D POOL AND REPORT ALL GROUNDINGS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 4 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE FROM MILE MARKER _____ TO _____ OHIO RIVER. ALL MARINERS ARE TO PROCEED WITH CAUTION AND REMAIN IN THE NAVIGABLE CHANNEL DUE TO DECREASING WATER LEVELS. ALL VESSELS MUST MONITOR CHANNEL DEPTHS AND ENSURE THAT ADEQUATE WATER EXISTS FOR THEIR VESSEL DRAFTS. VESSEL DRAFTS SHALL NOT EXCEED _____ FT. REPORT ALL GROUNDINGS TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.15. Cannelton Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">CANNELTON LOCK & DAM</p> <p style="text-align: center;">OHIO RIVER MILE MARKER: 720.7</p> <p style="text-align: center;">FLOOD STAGE READING: 42' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 420' GATES ALL OUT 34.5'-35.0' LG CEASE LOCKING 51' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH CANNELTON L&D TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE OUTDRAFT WHILE ENTERING SOUTHBOUND LOCK CHAMBER. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: OUTDRAFT IS SEVERE AT APPROXIMATELY 400' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 2: WHEN LEAVING THE LOCK NORTHBOUND WITH LOADED TOWS, MARINERS SHOULD BE AWARE OF AN AREA OF SLACK WATER FROM THE CHAMBERS TO A DIKE SEVERAL HUNDRED YARDS UPRIVER. MARINERS SHOULD CONSIDER REDUCING POWER IN ANTICIPATION OF INCREASED CURRENTS WHEN LEAVING SLACK WATER AS THEY PASS THE DIKE, TO PREVENT BREAKAWAYS OR DIVING.</p> <p>USACE GAUGE READINGS REPORT</p>	10' DAM OPENING	Rising	Normal Operations/Flow Conditions	Watch	Locking operations normal.
	100'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/Increased Flow Conditions	Watch	Consider for up river high water conference calls. COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	120'+ DAM OPENING	Rising	Extreme High Water/Extreme High Flow Conditions	Action	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Consider implementation of Safety Zone (Enc. 2). Factors to evaluate include rate of rise, amount of drift, presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	120' - DAM OPENING	Falling	High Water/Increased Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Consider Safety Advisory, (Enc. 1) verses Safety Zone (Enc. 2).
	100' - DAM OPENING	Falling	Normal Operations/Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

OHIO RIVER - CANNELTON LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF CANNELTON LOCK AND DAM, MILE MARKER 720.7, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE AT THE CANNELTON LOCK AND DAM, MILE MARKER 720.7, OHIO RIVER. THE CANNELTON LOCK AND DAM HAS CEASED LOCKING. HIGH WATER CONDITIONS AND VESSEL WAKES HAVE CAUSED DAMAGE TO SURROUNDING STRUCTURES. VESSEL TRANSITS ARE CEASED UNTIL WATER CONDITIONS SUBSIDE AND DAMAGE CAN BE PREVENTED.

4.A. Ohio River Action Plan

4.A.16. Newburgh Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>NEWBURGH LOCK & DAM</p> <p>OHIO RIVER MILE MARKER: 776.1</p> <p>FLOOD STAGE READING: 38' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 252' GATES ALL OUT 27.5'-28.0' LG CEASE LOCKING 47' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH NEWBURGH L&D TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE. VESSELS EXPERIENCE OUTDRAFT WHILE ENTERING SOUTHBOUND LOCK CHAMBER. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: THERE IS NOTICEABLE SHOALING DURING LOW WATER CONDITIONS FROM MM 723 TO MM 737.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE ON THE UPPER SIDE OF THE LOCK DUE TO HIGH FLOWS.</p> <p>USACE GAUGE READINGS REPORT</p>	60' DAM OPENING	Rising	Normal Operations/Flow Conditions	Watch	Locking operations normal.
	60'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/Increased Flow Conditions	Watch	Consider for up river high water conference calls. COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	100'+ DAM OPENING or 47' LG	Rising	Extreme High Water/Extreme High Flow Conditions	Action	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Once the LG reaches 47' LG implement Safety Zone (Enc. 2) advising mariners that the Newburgh L&D has ceased locking and the weir is navigable. Consider implementing the following restrictions: 250 HP minimum per loaded barge, daylight transits only for tows comprised of barges carrying cargoes regulated under Title 46 CFR Subchapter D & O and/or more than 6 barges loaded with any product, and/or a standby assist vessel of appropriate HP to provide assistance as needed. Factors to evaluate include rate of rise, amount of drift, presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: High/low water conditions may warrant one way traffic due to ATON changes from MM 791 to MM 795.
	100' - DAM OPENING or 47' LG	Falling	High Water/Increased Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Cancel Safety Zone (Enc. 2) Consider Safety Advisory (Enc. 1).
	60' - DAM OPENING	Falling	Normal Operations/Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory.

OHIO RIVER - NEWBURGH LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF NEWBURGH LOCK AND DAM, MILE MARKER 776.1, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ESTABLISHED A SAFETY ZONE AT THE NEWBURGH LOCK AND DAM, MILE MARKER 776.1, OHIO RIVER. THE NEWBURGH L/D HAS CEASED LOCKING. THE NEWBURGH WEIR IS NAVIGABLE AND MARINERS ARE URGED TO PROCEED WITH CAUTION ALONG THE KENTUCKY SHORELINE. REPORT ALL MARINE CASUALTIES TO THE U.S. COAST GUARD.

4.A. Ohio River Action Plan

4.A.17. J. T. Myers Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>J. T. MYERS LOCK & DAM OHIO RIVER MILE MARKER: 846 FLOOD STAGE READING: 37' LG</p> <p>OTHER USEFUL DATA: MAX OPENING 270' GATES ALL OUT 30' LG CEASE LOCKING 47' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH J. T. MYERS L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFTS WHILE ENTERING SOUTHBOUND LOCK CHAMBER. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: SHALLOW WATER OFTEN EXISTS BELOW THE LOCK FROM MM 847 TO MM 851 DUE TO OUTFLOW FROM THE WABASH RIVER</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE ON THE UPPER SIDE OF THE LOCK DUE TO HIGH FLOWS.</p> <p>USACE GAUGE READINGS REPORT</p>	100' DAM OPENING	Rising	Normal Operations/Flow Conditions	Watch	Locking operations normal.
	100'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/Increased Flow Conditions	Watch	Consider for up river high water conference calls. COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	150'+ DAM OPENING or 47' LG	Rising	Extreme High Water/Extreme High Flow Conditions	Action	COTP Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Once the LG reaches 47' LG implement Safety Zone (Enc. 2) advising mariners that the J. T. Myers L&D has ceased locking and the weir is navigable. Consider implementing the following restrictions: 250 HP minimum per loaded barge, daylight transits only for tows compromised of barges carrying cargoes regulated under Title 46 CFR Subchapter D & O and/or more than 6 barges loaded with any product, and/or a standby assist vessel of appropriate HP to provide assistance as needed. Additional factors to evaluate include rate of rise, amount of drift, presence of ice and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics. Note: High/low water conditions may warrant one way traffic due to ATON changes from MM 791 to MM 795.
	150'- DAM OPENING or <47' LG	Falling	High Water/Increased Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate. Cancel Safety Zone (Enc. 2), Consider Safety Advisory (Enc. 1).
	100'- DAM OPENING	Falling	Normal Operations/Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc 1).

OHIO RIVER – J. T. MYERS LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF J. T. MEYERS LOCK AND DAM, MILE MARKER 846, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SPECIAL LOCAL REGULATION FOR J. T. MYERS LOCK AND DAM, MILE MARKER 845, OHIO RIVER. THE J. T. MYERS LOCK AND DAM HAS CEASED LOCKING. THE J. T. MYERS WEIR IS NAVIGABLE UNDER THE FOLLOWING CONDITIONS: MINIMUM HORSE POWER PER LOADED BARGE IS 250 HP. TOWS COMPRISED OF BARGES CARRYING CARGOES REGULATED UNDER TITLE 46 CFR SUCHAPTER D AND O (KNOWN AS RED FLAG BARGES) AND/OR WITH MORE THAN 6 BARGES LOADED WITH ANY PRODUCT, ARE RESTRICTED TO DAYLIGHT TRANSIT ONLY. A STANDBY ASSIST BOAT WITH APPROPRIATE HORSE POWER IS ON SCENE TO PROVIDE ASSISTANCE AS NEEDED. AT FIRST LIGHT, NORTH BOUND TOWS WILL BE CLEARED FIRST, FOLLOWED BY SOUTHBOUND TOWS. THE J. T. MYERS LOCK OPERATOR WILL ESTABLISH THE TRANSIT QUEUE. TOWS SHOULD NOTIFY THE LOCK OPERATOR WHEN APPROACHING J. T. MYERS L/D. A CARRIER MAY REQUEST AN EXCEPTION TO THE ABOVE. REQUESTS SHOULD BE MADE DURING NORMAL BUSINESS HOURS TO THE CAPTAIN OF THE PORT AT 1-800-253-7465. THE CAPTAIN OF THE PORT MAY CONSULT WITH THE CENTRAL OHIO RIVER MARINE INDUSTRY GROUP (CORMIG) CHAIRMAN, BUT IT WILL BE THE CAPTAIN OF THE PORT WHO WILL MAKE A FINAL DETERMINATION ON EACH REQUEST. MARINERS ARE ADVISED THAT FAILURE TO FOLLOW THIS REGULATION MAY RESULT IN A CIVIL PENALTY.

4.A. Ohio River Action Plan

4.A.18. Smithland Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING UPPER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>SMITHLAND LOCK & DAM OHIO RIVER MILE MARKER: 918.5</p> <p>FLOOD STAGE READING: 20'0"</p> <p>OTHER USEFUL DATA: VESSEL ALLISIONS WITH SMITHLAND L&D TEND TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE ENTERING SOUTHBOUND LOCK CHAMBER. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS (LOCAL PRACTICE IS TO USE THE LAND CHAMBER DOWNBOUND)</p> <p>USACE GAUGE READINGS REPORT</p> <p>Lock #: 618-564-2315</p>	12'3"	Rising	Normal Operations	Watch	Locking Operations Normal.
	15'5"	Rising & projected to continue rising rapidly	High Water	Watch	Lockmaster contacts MSU Paducah. Notify ICE Committee. Consider ICE Committee Meeting with MSU Paducah and CGC CHIPPEWA. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	20'0"	Rising	Extreme High Water	Watch	Lockmaster contacts CG MSU Paducah. Hold ICE Committee conference call with MSU Paducah and CGC CHIPPEWA. Safety Advisory in effect.
	27'4"	Rising	Max Locking Ability	Action	Lockmaster contacts CG MSU Paducah. Smithland L&D ceases locking vessels. MSU Paducah will submit a BNM request to the Sector Command Center (SCC). The SCC will initiate a Safety Zone (Enc. 2). Hold ICE Committee conference call. Vessels will experience delays. Consider pre-identified lay-up areas in the event of river closure.
	29'0" & above	Rising	Potential Weir Navigation Weir elevation is 14 ft	Action	Lockmaster contacts CG MSU Paducah. Hold ICE Committee meeting to determine potential for weir navigation. If the weir is navigable MSU Paducah implements Safety Zone. Consider assist vessel on stand-by for up-bound traffic. Determine appropriate horsepower per tow restrictions and one way traffic patterns in order to navigate weir. Consider providing local Pilot knowledge of weir characteristics.
	29'0"	Falling	Potential Weir Navigation	Action	Lockmaster contacts CG MSU Paducah. Hold ICE Committee meeting to determine potential for weir navigation. Safety Zone in effect.
	27'4"	Falling	Resume Locking Ability	Recovery	Lockmaster contacts CG MSU Paducah. Smithland L&D resumes locking vessels. Notify ICE Committee. Sector Command Center cancels Safety Zone (Enc. 2) and re-issues Safety Advisory (Enc. 1).
	20'0"	Falling	Extreme High Water	Recovery	Safety Advisory in remains in effect
	12'5" - 15'5"	Falling	High Water	Recovery	Continue monitoring river condition and cancel Safety Advisory (Enc. 1).
	12'0"	Falling	Normal Operations	Watch	Locking Operations Normal.

4.A. Ohio River Action Plan

4.A.19. Smithland Lock and Dam Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>SMITHLAND LOCK & DAM</p> <p>OHIO RIVER MILE MARKERS: 918.5</p> <p>OTHER USEFUL DATA: TO DETERMINE NAVIGABILITY OVER MITER SILLS CONSULT LOCKMASTER. L&D 52 MAINTAINS AN AVERAGE LOWER GAUGE OF 12'4" AT SMITHLAND L&D. LOWER SIDE OF SMITHLAND L&D TO THE FOOT OF CUMBERLAND ISLAND IS ONE WAY TRAFFIC AT ALL TIMES.</p> <p>USACE GAUGE READINGS REPORT</p>	12'0" and above	Falling	Normal Operations	Watch	Lock Operations Normal.
	11'0"	Falling	Low Water	Watch	Lockmaster contacts CG MSU Paducah. Notify ICE Committee. Notify division USACE, TVA. Discuss draft and tow size recommendations under falling river conditions. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 3).
	10'5"	Falling	Extreme Low Water	Action	Lockmaster contacts CG MSU Paducah. Notify ICE Committee consider meeting. Discuss draft and tow size recommendations under falling river conditions. Safety Advisory in effect. Note: Vessels draft must have one foot of clearance over miter sills to enter and exit lock chamber.
	10'0"	Falling	Restrict Lock Operations	Action	Lockmaster contacts CG MSU Paducah. Hold ICE Committee Meeting with MSU Paducah and CGC CHIPPEWA. Smithland L&D considers ceasing locking vessels. Safety Advisory in effect.
	9'8" and below	Falling	Restrict Lock Operations	Action	Lockmaster contacts CG MSU Paducah. MSU Paducah will submit a Safety Zone request to the Sector Command Center (SCC) due to extreme low water between MM 918.5 – MM 934.0 OHR. . The SCC will initiate a Safety Zone (Enc. 4) and cancel Safety Advisory (Enc. 3). Vessels will experience delays.
	9'8" and below	Rising	Restrict Lock Operations	Recovery	Safety Zone in effect. Vessels will experience delays.
	10'0"	Rising	Resume Lock Operations	Recovery	Notify ICE Committee. Smithland L&D resumes locking vessels CG MSU Paducah cancels Safety Zone; re-issues Safety Advisory; indicate low water, exercise caution.
	10'5"	Rising	Extreme Low Water	Recovery	Lockmaster contacts CG MSU Paducah. Notify ICE Committee. Discuss draft and tow size recommendations under rising river conditions. Safety Advisory in effect.

	11'0"	Rising	Low Water	Watch	Lockmaster contacts CG MSU Paducah. SCC will cancel Safety Zone (Enc. 4) and re-issue Safety Advisory (Enc. 3).
	12'0" and above	Rising	Normal Operations	Watch	Lock Operations Normal.

OHIO RIVER – SMITHLAND LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF SMITHLAND LOCK AND DAM, MILE MARKER 918.5, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE OHIO RIVER FROM MILE MARKER 917 TO MILE MARKER 922 IN THE VICINITY OF SMITHLAND LOCK AND DAM. THIS SAFETY ZONE INCLUDES THE CLOSURE OF SMITHLAND LOCK AND DAM DUE TO HIGH WATER WITH THE UPPER GAUGE READING 29.0 FEET. NORTHBOUND VESSELS ARE PROHIBITED FROM NAVIGATION OVER THE WEIR PASS. SOUTHBOUND VESSELS WITH 9'0" DRAFT AND ADEQUATE HORSEPOWER ARE AUTHORIZED NAVIGATION OVER THE WEIR WITH AN ASSIST VESSEL IMMEDIATELY AVAILABLE IN CASE OF EMERGENCY.

LOW WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF SMITHLAND LOCK AND DAM. VESSELS DEPARTING THE LOCK AND DAM WHILE TRANSITING SOUTHBOUND ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE L/D 52 POOL. RIVER LEVELS IN THE VICINITY OF SMITHLAND LOCK AND DAM ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ARMY CORPS OF ENGINEERS GUARANTEES AN 9'0" CHANNEL. MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 4 (example)

Safety Marine Information Broadcast (Local Safety)

Low Water Safety Zone BNM to be developed by MSU Paducah on case by case basis.

4.A. Ohio River Action Plan

4.A.20. Lock & Dam 52 Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING UPPER & LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>LOCK & DAM 52</p> <p>OHIO RIVER MILE MARKERS: 939.0</p> <p>FLOOD STAGE READING: 37'0" REFERENCE GAUGE: L & D 52</p> <p>OTHER USEFUL DATA: ONE GAUGE READING EXISTS WHEN WICKETS ARE DOWN. WHEN WICKETS ARE RAISED THERE IS AN UPPER AND LOWER GAUGE READING. IDEAL POOL CONDITIONS FOR LOCK & DAM 52 WHEN WICKETS ARE RAISED: 18.6 ON THE UPPER GAUGE AND 10.0 OR GREATER ON THE LOWER GAUGE. NAVIGATION OVER THE BEAR TRAPS WILL BE CONSIDERED WHEN THE UPPER GAUGE REACHES 36.0. MINIMUM LOCKING ABILITY ON LOWER GAUGE IS 9.0.</p> <p>HARRAHS CASINO STOPS PASSENGER OPERATIONS WHEN L&D 52 GAUGE REACHES 51'0".</p> <p>USACE GAUGE READINGS REPORT</p>	U 15.6 & above	Falling	Normal Operations	Watch	Wicket dam is normally down. Vessels navigating the wicket pass. Vessels not required to use lock chamber.
	U 15.5 – 15.0	Falling	Low Water	Watch	Lockmaster contacts CG MSU Paducah. L&D 52 Lockmaster considers raising wickets. Vessels may experience delays during this stage. Notify ICE Committee. MSU Paducah will submit a BNM request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	U 14.9 L 10.0	Falling	Low Water	Watch	Wickets unable to maintain adequate pool. Lockmaster contacts CG MSU Paducah. Notify ICE Committee. Vessels exercise caution within buoyed areas within L&D 52 pool (MM 927 OHR). L&D 52 pool experiences draw down condition prior to pool regenerating resulting in low water in the tail end of the pool near Smithland L&D.
	U 14.7 and below L 9.0 and below	Falling	Extreme Low Water	Action	Wickets unable to maintain adequate pool. Lockmaster contacts CG MSU Paducah. CG MSU Paducah considers implementation of Safety Zone (Enc. 2) due to extreme low water. Emergency situation. Hold ICE Committee meeting with MSU Paducah and CGC CHIPPEWA. Vessels will experience delays. Lock chamber unable to accommodate commercial vessels. Note: Vessels draft must have one foot of clearance over miter sills to enter and exit lock chamber.
	U 15.5 L 10.0	Rising	Low Water	Action	MSU Paducah requests SCC cancel Safety Zone (Enc. 2) if implemented and issue Safety Advisory (Enc. 1) Notify ICE Committee. Resume locking of commercial vessels.
	U 15.6 L 12.0	Rising	Low Water	Recovery	Locking vessels. Mariners should consider potential out-drafts. CG MSU Paducah cancels low water Safety Advisory.
	U 18.6 L 15.0	Rising	Normal Operations	Recovery	Lockmaster considers lowering all wickets. Locking vessels.
	U 18.8	Rising	Normal Operations	Action	Lockmaster lowers wickets to maintain upper pool.
	U 19.1	Rising	Normal Operations	Recovery	Wicket dam is normally down. Vessels navigating the pass. Vessels not using lock chambers.

OHIO RIVER –LOCK AND DAM 52

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF LOCK AND DAM 52. VESSELS DEPARTING THE LOCK AND DAM WHILE TRANSITING SOUTHBOUND ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE L/D 52 POOL. RIVER LEVELS IN THE VICINITY OF LOCK AND DAM 52 ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ARMY CORPS OF ENGINEERS GUARANTEES A 9'0" CHANNEL. MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE OHIO RIVER FROM MILE MARKER _____ TO MILE MARKER _____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY THE U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT IN THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.A. Ohio River Action Plan

4.A.21. Lock & Dam 53 Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING UPPER & LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>LOCK & DAM 53 OHIO RIVER MILE MARKER: 963.0</p> <p>OTHER USEFUL DATA: ONE GAUGE READING EXISTS WHEN WICKETS ARE DOWN. WHEN WICKETS ARE RAISED THERE IS AN UPPER AND LOWER GAUGE READING. IDEAL POOL CONDITIONS FOR LOCK & DAM 53: 16.9 ON THE UPPER GAUGE AND 10.0 ON THE LOWER GAUGE. NAVIGATION OVER THE BEAR TRAPS WILL BE CONSIDERED WHEN THE UPPER GAUGE REACHES 32.0. MINIMUM LOCKING ABILITY ON LOWER GAUGE IS 4.0.</p> <p>USACE GAUGE READINGS REPORT</p>	U 16.0 & above	Falling	Normal Operations	Watch	Vessels navigating the pass.
	U 16.0 – 14.0	Falling	Normal Operations	Watch	Lockmaster contacts MSU Paducah. Lockmaster considers raising wickets. Notify ICE Committee. MSU Paducah will submit a BNM request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1). Consider resetting buoys. Discuss draft and tow size recommendations. Vessels may experience delays during this stage.
	U 13.6 L 10.0	Falling	Low Water	Watch	Wickets unable to maintain adequate pool. Lockmaster contacts MSU Paducah. Hold ICE Committee meeting. Vessels exercise caution within buoyed areas between L&D 53 to mouth of OHR.
	U 13.3 and below L 9.0 and below	Falling	Extreme Low Water	Action	Wickets unable to maintain adequate pool. MSU Paducah considers implementation of Safety Zone (Enc. 2) due to extreme low water. Cease locking of commercial vessels. Hold ICE Committee meeting with MSU Paducah and CGC CHIPPEWA. Note: Vessels draft must have one foot of clearance over miter sills to enter and exit lock chamber.
	U 13.4 L 9.0	Rising	Extreme Low Water	Action	Lockmaster contacts MSU Paducah. MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1) Lock chamber unable to accommodate commercial vessels.
	U 13.6 L 10.0	Rising	Low Water	Recovery	Locking vessels. Mariners should consider potential out drafts.
	U 16.9 L 11.0	Rising	Normal Operations	Recovery	Locking vessels.
	U 17.0 L 12.0	Rising	Normal Operations	Action	Lockmaster considers lowering some wickets to maintain upper pool. Locking vessels.
	U 17.2	Rising	Normal Operations	Recovery	Lockmaster contacts MSU Paducah. Lockmaster considers lowering all wickets. Vessels navigating the pass. Vessels not locking.

OHIO RIVER –LOCK AND DAM 53

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF LOCK AND DAM 53. VESSELS DEPARTING THE LOCK AND DAM WHILE TRANSITING SOUTHBOUND ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE L/D 53 POOL. RIVER LEVELS IN THE VICINITY OF LOCK AND DAM 53 ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ADVERTISED NAVIGABLE DRAFT IS 9'0". MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE OHIO RIVER FROM MILE MARKER ____ TO MILE MARKER ____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY THE U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.A. Ohio River Action Plan

4.A.22. Irvin Cobb Bridge Operations

CRITICAL AREA DESCRIPTION	TRIGGER	TREND	DESCRIPTION	PHASE	ACTION
IRVIN COBB BRIDGE OHIO RIVER MILE MARKERS: 937.4 OTHER USEFUL DATA: MARINERS SHOULD EXERCISE EXTREME CAUTION WHEN NAVIGATING THESE SPANS AND ENSURE ADEQUATE CLEARANCE OF VESSEL UNDER BRIDGE DURING HIGH WATER CONDITIONS	Locking at 52	Locking at 52	Normal Operations	Watch	Vessels normally run Illinois channel span when L&D 52 is locking.
	Not locking at 52	Not locking at 52	Normal Operations	Watch	Vessels normally run Kentucky channel span when L&D 52 is not locking

4.A. Ohio River Action Plan

4.A.23. I-24 Bridge

CRITICAL AREA DESCRIPTION	TRIGGER	TREND	DESCRIPTION	PHASE	ACTION
I-24 BRIDGE OHIO RIVER MILE MARKERS: 940.9 OTHER USEFUL DATA MARINERS SHOULD EXERCISE EXTREME CAUTION WHEN NAVIGATING THESE SPANS AND ENSURE ADEQUATE CLEARANCE OF VESSEL UNDER BRIDGE DURING HIGH: WATER CONDITIONS.	Locking at 52	Locking at 52	Normal Operations	Watch	Vessels normally run Illinois channel span when L&D 52 is locking. Vertical clearance is 20' less on Illinois span and may not be adequate to transit high water conditions.
	Not locking at 52	Not locking at 52	Normal Operations	Watch	Vessels normally run Kentucky channel span when L&D 52 is not locking

4.A. Ohio River Action Plan

4.A.24. I.C. Railroad Bridge & Route 60/62 Bridge

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	TRIGGER CURRENT	DESCRIPTION	PHASE	ACTION
<p>I.C. RAILROAD BRIDGE AND ROUTE 60 / 62 BRIDGE</p> <p>OHIO RIVER MILE MARKERS: 977.7 980.4</p> <p>FLOOD STAGE READING: 40'0"</p> <p>REFERENCE GAUGE: CAIRO & L & D 53</p> <p>OTHER USEFUL DATA: THIS CHART USES THE CAIRO GAUGE AND THE LOCK AND DAM 53 GAUGE. THE L&D 53 GAUGE CAN BE COMPARED TO THE CAIRO GAUGE TO DETERMINE HAZARDOUS CONDITIONS / FLOWS. SIMILAR CONDITIONS EXIST FOR THE CAIRO HIGHWAY BRIDGE AT MM 980.4 FOR VESSELS TRANSITING DOWNBOUND. UNDER THESE CONDITIONS MARINERS SHOULD NAVIGATE WITH CAUTION. HIGH CONSEQUENCE COLLISIONS MAY OCCUR IN THIS AREA UNDER HIGH WATER AND HIGH CURRENT CONDITIONS RESULTING IN MARINE CASUALTIES AND VESSEL SINKINGS. HARRAHS CASINO STOPS PASSENGER OPERATIONS WHEN L&D 52 GAUGE REACHES 51'0".</p> <p>BIRDS POINT FLOOD PLAIN OFFICE: 901-544-3401 CAIRO GAUGE READING: PHONE #: 1-618 - 734 - 0577</p> <p>USACE GAUGE READINGS REPORT</p>	35'0" & below	Rising	3.0 mph	Normal Operations	Watch	Operations normal.
	35'0"	Rising & projected to continue rising rapidly	3.0 mph	High Current	Watch	MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1); be alert for swift currents, report unusual conditions to Coast Guard. Transit area with extreme caution. Notify ICE Committee.
	38'0"	Rising	4.0 mph	High Current	Watch	Safety Advisory in effect. Notify ICE Committee. Discuss horsepower and tow size recommendations. Consider use of assist vessel.
	40'0"	Rising	5.0 mph	Very High Current	Action	Safety Advisory in effect. Hold ICE Committee conference call with MSU Paducah and CGC CHIPPEWA. Consider transit of vessels based on horsepower, tow size, cargo, and visibility. Fleet managers secure fleeting areas.
	40'0" & above	Rising	5.0 mph	Very High Current	Action	Consider need for Safety Zone (Enc. 2). Hold ICE Committee Meeting. Consider transit of vessels based on horsepower, tow size, cargo, and visibility. Fleet managers secure fleeting areas. Note: At 49' on Cairo gauge, consult Birds Point Floodway Plan. At 56' on Cairo gauge, CG requested on scene.
	39'0"	Falling	4.0 mph	Very High Current	Recovery	MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1). Notify ICE Committee.
	38'0"	Falling	3.5 mph	Very High Current	Recovery	Safety Advisory in effect. Notify ICE Committee. Consider transit of vessels based on horsepower, tow size, cargo, and visibility.
	35'0"	Falling	3.0 mph	High Current	Recovery	Continue monitoring river conditions, cancel Safety Advisory (Enc. 1). Notify ICE Committee.
	35'0" & below	Falling	3.0 mph	Normal Operations	Recovery	Operations normal.

OHIO RIVER – I.C. RAILROAD BRIDGE AND ROUTE 60 / 62 BRIDGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE I.C. RAILROAD BRIDGE AND ROUTE 60 / 62 BRIDGE, OHIO RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING THIS AREA, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO HAS ESTABLISHED A SAFETY ZONE ON THE OHIO RIVER FROM MILE MARKER _____ TO MILE MARKER _____ IN THE VICINITY OF THE I.C. RAILROAD BRIDGE AND ROUTE 60 / 62 BRIDGE. NORTHBOUND VESSELS ARE PROHIBITED FROM NAVIGATION OVER THE LOCK AND DAM 53 WEIR PASS. SOUTHBOUND VESSELS WITH 9'0" DRAFT AND ADEQUATE HORSEPOWER ARE AUTHORIZED NAVIGATION OVER THE WEIR WITH AN ASSIST VESSEL IMMEDIATELY AVAILABLE IN CASE OF EMERGENCY.

4.A. Ohio River Action Plan

4.A.25. Grand Chain & Post Creek Vicinity

CRITICAL AREA DESCRIPTION	TRIGGER READING L&D 53 UPPER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>GRAND CHAIN & POST CREEK VICINITY</p> <p>OHIO RIVER MILE MARKERS: 959.0 – 962.0</p> <p>REFERENCE GAUGE: L & D 53</p> <p>NAVIGATION CHANNEL PROJECT DEPTH OR OTHER USEFUL DATA: THIS AREA EXPERIENCES EXCESSIVE SHOALING RESULTING IN VESSEL GROUNDINGS WITHIN THE CHANNEL. DURING LOW WATER OR WHEN ALL L&D 53 WICKETS ARE DOWN, GROUNDINGS MAY INCREASE SIGNIFICANTLY. VESSEL DRAFTS SHOULD BE CAREFULLY WATCHED WHEN TRANSITING THIS AREA. VESSELS MAY REQUIRE LIGHTERING DURING EXTENDED PERIODS OF LOW WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	16'0" and above	Falling	Normal Operations	Watch	Operations Normal. CG, Industry chairman, & USACE monitor L&D 53 GAUGE. Mariners report all missing Aids to Navigation to CG Sector Ohio Valley.
	15'0"	Falling	Low Water	Action	Notify ICE Committee. Discuss draft and tow size recommendations under falling river conditions. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1). Notify USACE discuss surveys and dredging. Notify CG Buoy Tender to survey & set buoys.
	14'8"	Falling	Low Water	Action	CG, Industry chairman, & USACE monitor L&D 53 GAUGE. Notify ICE Committee. Safety Advisory in effect. Notify USACE discuss surveys and dredging. Notify CG Buoy Tender to survey & set buoys.
	14'2"	Falling	Extreme Low Water	Action	Hold ICE Committee call with MSU Paducah and CGC CHIPPEWA. Discuss draft and tow size recommendations under falling river conditions. Safety Advisory in effect. CG Buoy Tender on scene. USACE plan potential dredging.
	13'8"	Falling	Extreme Low Water	Action	CG, Industry chairman, & USACE monitor L&D 53 GAUGE. Hold ICE Committee meeting. Identify specific critical low water areas. Review surveys. Safety Advisory in effect. Consider need for Safety Zone (Enc. 2).
	13'5" and below	Falling	Restrict Navigation	Action	CG MSU Paducah considers implementation of Safety Zone due to extreme low water. Vessels will experience delays.
	13'5" and below	Rising	Restrict Navigation	Recovery	Safety Zone in effect. Vessels will experience delays.
	13'8"	Rising	Extreme Low Water	Recovery	Notify ICE Committee. MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1) Discuss draft and tow size recommendations.
	14'2"	Rising	Extreme Low Water	Recovery	CG, Industry chairman, & USACE monitor L&D 53 GAUGE. Hold ICE Committee conference call. Discuss draft and tow size recommendations under rising river conditions. Safety Advisory in effect. USACE plan potential dredging.
	14'8"	Rising	Low Water	Recovery	Discuss draft and tow size recommendations. Safety Advisory in effect. Notify USACE discuss surveys and dredging.
	15'0"	Rising	Low Water	Recovery	Continue monitoring river conditions, cancel Safety Advisory (Enc. 1). CG Buoy Tender survey area for missing buoys.
	16'0" and above	Rising	Normal Operations	Recovery	Operations Normal.

OHIO RIVER – GRAND CHAIN & POST CREEK VICINITY

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE GRAND CHAIN AND POST CREEK VICINITY. VESSELS DEPARTING LOCK AND DAM 53 WHILE TRANSITING SOUTHBOUND ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE L/D 53 POOL. RIVER LEVELS IN THE VICINITY OF LOCK AND DAM 53 ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ARMY CORPS OF ENGINEERS GUARANTEES A 9'0" CHANNEL. MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE OHIO RIVER FROM MILE MARKER ____ TO MILE MARKER ____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT IN THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.A. Ohio River Action Plan

4.A.26. American Bar & Mound City Bar Vicinity Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING CAIRO GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>AMERICA BAR & MOUND CITY BAR VICINITY</p> <p>OHIO RIVER MILE MARKERS: 969.0 – 972.0 973.0 – 975.0</p> <p>REFERENCE GAUGE: CAIRO</p> <p>OTHER USEFUL DATA: THIS AREA EXPERIENCES EXCESSIVE SHOALING RESULTING IN VESSEL GROUNDINGS WITHIN THE CHANNEL. DURING LOW WATER OR WHEN ALL L&D 53 WICKETS ARE UP, GROUNDINGS MAY INCREASE IN THIS AREA. VESSEL DRAFTS SHOULD BE CAREFULLY WATCHED WHEN TRANSITING THIS AREA. VESSELS MAY REQUIRE LIGHTERING DURING EXTENDED PERIODS OF LOW WATER. HISTORICAL LOWS: 1988 – CAIRO GAUGE – 5’5” 1997 – CAIRO GAUGE – 6’8” 2005 – CAIRO GAUGE – 7’5” EMERGENCY CONDITIONS EXIST WHEN THE CAIRO GAUGE FALLS BELOW 9’0” FOR AN EXTENDED PERIOD OF TIME. CAIRO GAUGE READING: PHONE #: 1- 618 – 734 – 0577</p> <p>USACE GAUGE READINGS REPORT</p>	11’0” and above	Falling	Normal Operations	Watch	Operations Normal. CG, Industry chairman, & USACE monitor Cairo GAUGE. Mariners report all missing Aids to Navigation to CG Sector Ohio Valley.
	10’0”	Falling	Low Water	Watch	Notify MSU Paducah of Cairo GAUGE reading 10’0”. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1). Report missing Aids to Navigation to CG.
	9’5”	Falling	Low Water	Watch	CG, Industry chairman, & USACE monitor Cairo GAUGE. Notify ICE Committee. Discuss draft and tow size recommendations under falling river conditions. Safety Advisory in effect. Notify USACE discuss surveys and dredging. Notify CG Buoy Tender to survey & set buoys.
	9’0”	Falling	Extreme Low Water	Action	Hold ICE Committee conference call. Discuss draft and tow size recommendations under falling river conditions. Safety Advisory in effect. CG Buoy Tender on scene. USACE plan / begin dredging.
	8’8”	Falling	Extreme Low Water	Action	CG, Industry chairman, & USACE monitor Cairo GAUGE. Hold ICE Committee call with MSU Paducah and CGC CHIPPEWA. Identify specific critical low water areas. Review surveys. Safety Advisory in effect. Consider need for Safety Zone (Enc. 2). CG Buoy Tender on scene. USACE plan / begin dredging.
	8’3” and below	Falling	Restrict Navigation	Action	CG, Industry chairman, & USACE monitor Cairo GAUGE. CG MSU Paducah considers implementation of Safety Zone due to extreme low water. Vessels will experience delays. USACE continue dredging. CG Buoy Tender on-scene.
	8’3” and below	Rising	Restrict Navigation	Recovery	Safety Zone in effect. Vessels will experience delays.
	8’8”	Rising	Extreme Low Water	Recovery	MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1). Notify ICE Committee. CG Buoy Tender coordinates with USACE on scene to re-open channel and survey existing ATON. Discuss draft and tow size recommendations under rising river conditions.
	9’0”	Rising	Extreme Low Water	Recovery	CG, Industry chairman, & USACE monitor Cairo GAUGE. Hold ICE Committee conference call. Discuss draft and tow size recommendations under rising river conditions. Safety Advisory in effect.
	9’5”	Rising	Low Water	Recovery	Notify ICE Committee. Discuss draft and tow size recommendations. Safety Advisory in effect. Notify USACE discuss surveys and dredging.
	10’0”	Rising	Low Water	Recovery	CG, Industry chairman, & USACE monitor Cairo GAUGE. Cancel Safety Advisory (Enc. 1) CG Buoy Tender survey area for missing buoys.
	11’0” and above	Rising	Normal Operations	Recovery	Operations Normal. CG, Industry chairman, & USACE monitor Cairo GAUGE. Mariners report all missing Aids to Navigation to CG Sector Ohio Valley.

OHIO RIVER – AMERICA BAR & MOUND CITY BAR VICINITY

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF THE AMERICA BAR AND MOUND CITY BAR, OHIO RIVER. VESSELS TRANSITING IN THE CAIRO VICINITY ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE CAIRO VICINITY. RIVER LEVELS IN THE CAIRO VICINITY ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ADVERTISED NAVIGABLE DRAFT IS 9'0". MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE OHIO RIVER FROM MILE MARKER ____ TO MILE MARKER ____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY THE U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT IN THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.B. Mississippi River Action Plan

4.B.1. Chester Highway Bridge High Water / High Current Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING CHESTER GAUGE	TREND	TRIGGER CURRENT	DESCRIPTION	PHASE	ACTION
<p>CHESTER HIGHWAY BRIDGE</p> <p>UPPER MISSISSIPPI RIVER MILE MARKER: 109.9</p> <p>FLOOD STAGE READING: 29'0" REFERENCE GAUGE: CHESTER</p> <p>OTHER USEFUL DATA: DURING HIGH WATER CONDITIONS VESSELS MAY EXPERIENCE SET WHILE NAVIGATING CHANNEL SPAN OF THE CHESTER HIGHWAY BRIDGE. DURING HIGH CURRENT AND HIGH WATER MARINERS ARE ADVISED TO NAVIGATE THIS AREA AT SLOWEST SAFE SPEED AND EXERCISE EXTREME CAUTION DUE TO POTENTIAL OUTDRAFTS.</p> <p>CAPE GIRARDEAU FLOOD PLAIN OFFICE: 1-573-339-6351</p> <p>NOAA GAUGE READINGS REPORT</p>	20'0"	Rising	2.5 mph	Normal Operations	Watch	Operations Normal.
	22'5"	Rising and projected to rise rapidly	3.5 mph	High Water	Watch	MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1); indicate swift currents, report unusual conditions to Coast Guard. Transit area with extreme caution. Notify RIAC. Discuss voluntary horsepower and tow size recommendations.
	24'5"	Rising	4.0 mph	Extreme High Water	Action	Safety Advisory in effect. Consider RIAC phone conference call. Discuss industry actions. Consider use of assist vessel. Notify levee managers. Discuss levee concerns and future actions.
	27'0" & above	Rising	5.0 mph	Extreme High Water	Action	Safety Advisory in effect. Hold RIAC phone conference call. Notify levee managers. Discuss potential for a reducing tow sizes. Consider use of assist vessel.
	27'0"	Falling	5.0 mph	Extreme High Water	Action	Safety Advisory in effect. Continue potential for a Regulated Navigation Area restricting tow sizes. Consider use of assist vessel. Discuss levee concerns and future actions.
	24'5"	Falling	4.0 mph	Extreme High Water	Recovery	Safety Advisory in effect. Consider RIAC conference call. Discuss industry actions. Consider use of assist vessel. Discuss levee concerns and future actions.
	22'5"	Falling	3.5 mph	High Water	Recovery	Cancel Safety Advisory (Enc. 1). Notify RIAC.
	20'0"	Falling	2.5 mph	Normal Operations	Watch	Operations Normal.

UPPER MISSISSIPPI RIVER – CHESTER HIGHWAY BRIDGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE CHESTER HIGHWAY BRIDGE, MILE MARKER 109.9, UPPER MISSISSIPPI RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE WHEN NAVIGATING IN THIS AREA. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

4.B. Mississippi River Action Plan

4.B.2. Grays Point & Thebes Railroad Bridge High Water / High Current Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING CAPE GIRARDEAU GAUGE	TREND	TRIGGER CURRENT	DESCRIPTION	PHASE	ACTION
<p>GRAYS POINT & THEBES RAILROAD BRIDGE</p> <p>UPPER MISSISSIPPI RIVER MILE MARKER: 43.2</p> <p>FLOOD STAGE READING: 30'0" REFERENCE GAUGE: CAPE GIRARDEAU</p> <p>OTHER USEFUL DATA: VESSELS MAY EXPERIENCE SET WHILE NAVIGATING GRAYS POINT AND CHANNEL SPAN OF THE THEBES RAILROAD BRIDGE. DURING HIGH WATER MARINERS ARE ADVISED TO NAVIGATE THIS AREA AT SLOWEST SAFE SPEED AND EXERCISE EXTREME CAUTION DUE TO POTENTIAL OUTDRAFTS. CAPE GIRARDEAU FLOOD PLAIN OFFICE: 1-573-339-6351</p> <p>NOAA GAUGE READINGS REPORT</p>	12'0"	Rising	2.5 mph	Normal Operations	Watch	Operations Normal.
	20'0"	Rising & projected to continue rising rapidly	3.5 mph	High Water	Watch	MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1); indicate swift currents, report hazardous conditions to Coast Guard. Notify RIAC. Discuss fleeing areas.
	27'4"	Rising	4.0 mph	Extreme High Water	Action	Safety Advisory in effect. Consider RIAC phone conference call. Discuss industry actions. Discuss horsepower and tow size recommendations. Notify levee managers. Discuss levee concerns and future actions. Secure fleeing areas.
	29'0" & above	Rising	5.0 mph	Extreme High Water	Action	Safety Advisory in effect. Hold RIAC phone conference call. Discuss horsepower and tow size recommendations. Consider use of assist vessel. Notify levee managers. Secure fleeing areas. Contact Cape G. Flood Plain Office (1-573-339-6351).
	29'0"	Falling	5.0 mph	Extreme High Water	Action	Safety Advisory in effect. Discuss horsepower and tow size recommendations. Consider use of assist vessel. Secure fleeing areas. Discuss levee concerns and future actions.
	27'4"	Falling	4.0 mph	Extreme High Water	Recovery	Safety Advisory in effect. Consider RIAC phone conference call. Discuss industry actions. Discuss horsepower and tow size recommendations. Secure fleeing areas. Discuss levee concerns and future actions.
	20'0"	Falling	3.5 mph	High Water	Recovery	Cancel Safety Advisory (Enc. 1) Notify RIAC.
	12'0"	Falling	2.5 mph	Normal Operations	Watch	Operations Normal.

UPPER MISSISSIPPI RIVER – GRAYS POINT & THEBES RAILROAD BRIDGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF GRAYS POINT AND THEBES RAILROAD BRIDGE, MILE MARKER 43.2, UPPER MISSISSIPPI RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE WHEN NAVIGATING IN THIS AREA. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

4.B. Mississippi River Action Plan

4.B.3. Route 60 / 62 Bridge High Water / High Current Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING CAIRO GAUGE	TREND	TRIGGER CURRENT	DESCRIPTION	PHASE	ACTION
<p>ROUTE 60 / 62 BRIDGE</p> <p>UPPER MISSISSIPPI RIVER MILE MARKERS: 1.3</p> <p>FLOOD STAGE READING: 40'0" REFERENCE GAUGE: CAIRO</p> <p>OTHER USEFUL DATA: THE CAPE GIRARDEAU GAUGE CAN BE COMPARED TO THE CAIRO GAUGE TO DETERMINE HAZARDOUS CONDITIONS / FLOWS. SIMILAR CONDITIONS EXIST FOR THE LOWER OHIO RIVER BRIDGES FOR VESSELS TRANSITING DOWNBOUND. UNDER THESE CONDITIONS MARINERS SHOULD NAVIGATE AT SLOWEST SAFE SPEED. HIGH CONSEQUENCE ALLISIONS MAY OCCUR IN THIS AREA UNDER HIGH WATER CONDITIONS RESULTING IN HIGH CONSEQUENCE MARINE CASUALTIES AND VESSEL SINKINGS.</p> <p>BIRDS POINT FLOOD PLAIN OFFICE: 901-544-3401</p> <p>CAIRO GAUGE READING PHONE #: 1-618-734-0577</p> <p>NOAA GAUGE READINGS REPORT</p>	35'0" & below	Rising	3.0 mph	Normal Operations	Watch	Operations normal.
	35'0"	Rising & projected to continue rising rapidly	3.0 mph	High Current	Watch	MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1); indicate swift currents, report hazardous conditions to Coast Guard. Notify RIAC Committee.
	38'0"	Rising	3.5 mph	High Current	Watch	Safety Advisory in effect (Enc. 1). Fleet managers secure fleeing areas.
	39'0"	Rising	5.0 mph	Very High Current	Action	Safety Advisory in effect. Hold RIAC Committee conference call. Discuss horsepower and tow size recommendations. Consider use of assist vessel. Fleet managers secure fleeing areas.
	40'0" & above	Rising	5.0 mph	Very High Current	Action	CG MSU Paducah considers implementation of Safety Zone (Enc. 2) Hold RIAC Committee meeting. Consider coordination of vessel traffic on a vessel-by-vessel basis. Consider use of assist vessel. Vessels may experience delays. Fleet managers secure fleeing areas. Note: <u>At 49' on Cairo gauge, consult Birds Point Floodway Plan.</u> At 56' on Cairo gauge, CG requested on scene.
	39'0"	Falling	4.0 mph	Very High Current	Recovery	MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1); indicate swift currents, report hazardous conditions to Coast Guard. Notify RIAC Committee. Consider use of assist vessel.
	38'0"	Falling	3.5 mph	Very High Current	Recovery	Safety Advisory in effect. Notify RIAC Committee. Discuss horsepower and tow size recommendations.
	35'0"	Falling	3.0 mph	High Current	Recovery	Cancel Safety Advisory (Enc. 1). Notify RIAC Committee.
35'0" & below	Falling	3.0 mph	Normal Operations	Recovery	Operations normal.	

UPPER MISSISSIPPI RIVER – ROUTE 60 / 62 BRIDGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE ROUTE 60 / 62 BRIDGE, MILE MARKER 1.3, UPPER MISSISSIPPI RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE WHEN NAVIGATING IN THIS AREA. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U. S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE UPPER MISSISSIPPI RIVER FROM MILE MARKER _____ TO MILE MARKER _____ IN THE VICINITY OF THE ROUTE 60/62 BRIDGE. NORTHBOUND VESSELS ARE PROHIBITED FROM NAVIGATION OVER THE LOCK AND DAM 53 WEIR PASS. SOUTHBOUND VESSELS WITH 9'0" DRAFT AND ADEQUATE HORSEPOWER ARE AUTHORIZED NAVIGATION OVER THE WEIR WITH AN ASSIST VESSEL IMMEDIATELY AVAILABLE IN CASE OF EMERGENCY.

4.B. Mississippi River Action Plan
4.B.4. Cairo Point Vicinity Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING CAIRO GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>CAIRO POINT VICINITY</p> <p>UPPER MISSISSIPPI RIVER MILE MARKERS: 0.3</p> <p>REFERENCE GAUGE: CAIRO</p> <p>OTHER USEFUL DATA: THIS AREA EXPERIENCES EXCESSIVE SHOALING RESULTING IN VESSEL GROUNDINGS WITHIN THE CHANNEL TYPICALLY ALONG THE RIGHT DESCENDING BANK. DURING LOW WATER OR WHEN ALL L&D 53 WICKETS ARE UP, GROUNDINGS MAY INCREASE SIGNIFICANTLY. VESSEL DRAFTS SHOULD BE CAREFULLY WATCHED WHEN TRANSITING THIS AREA DURING LOW WATER CONDITIONS. MARINERS ARE ADVISED TO NAVIGATE THIS AREA WHILE ADHEREING TO THE CENTER OF THE CHANNEL DURING LOW WATER. HISTORICAL LOWS: 1988 – CAIRO GAUGE – 5’5” 1997 – CAIRO GAUGE – 6’8” 2005 – CAIRO GAUGE – 7’5” EMERGENCY CONDITIONS EXIST WHEN THE CAIRO GAUGE FALLS BELOW 9’0” FOR AN EXTENDED PERIOD OF TIME.</p> <p>CAIRO GAUGE READING PHONE #: 1- 618 – 734 – 0577</p> <p>NOAA GAUGE READINGS REPORT</p>	11’0” and above	Falling	Normal Operations	Watch	Operations Normal. CG, Industry chairman, & USACE monitor Cairo GAUGE. Mariners report all missing Aids to Navigation to CG Sector Ohio Valley.
	10’0”	Falling	Low Water	Watch	Notify MSU Paducah of Cairo GAUGE reading 10’0”. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1). Report missing Aids to Navigation to CG.
	9’5”	Falling	Low Water	Watch	Notify ICE Committee. Discuss draft and tow size recommendations under falling river conditions. Safety Advisory in effect. Notify USACE discuss surveys and dredging. Notify CG Buoy Tender to survey & set buoys.
	9’0”	Falling	Extreme Low Water	Action	CG, Industry chairman, & USACE monitor Cairo GAUGE. Hold ICE Committee conference call. Discuss draft and tow size recommendations under falling river conditions. Safety Advisory in effect. CG Buoy Tender on scene. USACE plan / begin dredging.
	8’8”	Falling	Extreme Low Water	Action	Consider ICE Committee meeting. Identify specific critical low water areas. USACE discuss surveys and dredging. Safety Advisory in effect. Consider need for Safety Zone (Enc. 2). CG Buoy Tender on scene. USACE plan / begin dredging.
	8’3” and below	Falling	Restrict Navigation	Action	CG, Industry chairman, & USACE monitor Cairo GAUGE. Hold ICE Committee meeting. MSU Paducah considers implementation of Safety Zone due to extreme low water. Vessels will experience delays. USACE continue dredging. CG Buoy Tender on-scene.
	8’3” and below	Rising	Restrict Navigation	Recovery	Safety Zone in effect. Vessels may experience delays.
	8’8”	Rising	Extreme Low Water	Recovery	Notify ICE Committee. MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1). CG Buoy Tender coordinates with USACE on scene to re-open channel and survey existing ATON.
	9’0”	Rising	Extreme Low Water	Recovery	CG, Industry chairman, & USACE monitor Cairo GAUGE. Hold ICE Committee conference call. Discuss draft and tow size recommendations under rising river conditions. Safety Advisory in effect.
	9’5”	Rising	Low Water	Recovery	Notify ICE Committee. Discuss draft and tow size recommendations. Safety Advisory in effect. Notify USACE discuss surveys and dredging.
	10’0”	Rising	Low Water	Recovery	CG, Industry chairman, & USACE monitor Cairo GAUGE. Cancel Safety Advisory (Enc. 1). Notify ICE Committee. CG Buoy Tender survey area for missing buoys.
	11’0” and above	Rising	Normal Operations	Recovery	Operations Normal. CG, Industry chairman, & USACE monitor Cairo GAUGE. Mariners report all missing Aids to Navigation to CG Sector Ohio Valley.

UPPER MISSISSIPPI RIVER – CAIRO POINT

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF CAIRO POINT. VESSELS TRANSITING IN THE VICINITY OF CAIRO ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE CAIRO AREA. RIVER LEVELS IN THE CAIRO AREA ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ADVERTISED NAVIGABLE DRAFT IS 9'0". MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE MISSISSIPPI RIVER FROM MILE MARKER _____ TO MILE MARKER _____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY THE U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT IN THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.C. Tennessee River Action Plan

4.C.1. I-24 / 62 / 641 Bridge High Water / High Current Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING KENTUCKY L&D FLOW RATE	TREND	TRIGGER CURRENT	DESCRIPTION	PHASE	ACTION
<p>I-24 BRIDGE & 62 / 641 BRIDGE</p> <p>TENNESSEE RIVER MILE MARKER: 21.1, 22.4</p> <p>FLOOD STAGE READING: 200 CFS REFERENCE GAUGE: KENTUCKY LOCK & DAM GIVEN IN THOUSANDS OF (CFS).</p> <p>OTHER USEFUL DATA: TABLE USES FLOW THROUGH CURRENTS ESTIMATED BY KENTUCKY LOCK & DAM. CFS RATES CAN BE USED TO DETERMINE HAZARDOUS CONDITIONS / FLOWS. UNDER THESE CONDITIONS MARINERS SHOULD NAVIGATE AT SLOWEST SAFE SPEED. AREA MAY CONTAIN HIGH CURRENT CAUSING VESSELS TO EXPERIENCE UNEXPECTED SET RESULTING IN ADVERSE CONSEQUENCE.</p> <p>USACE GAUGE READINGS REPORT</p>	140 CFS and below	Rising	4.0 mph	Normal Operations	Watch	Operations Normal. TVA, CG, Industry chairman, & USACE monitor CFS rates.
	160 CFS	Rising & projected to continue rising rapidly	4.2 mph	Normal Operations	Watch	Notify ICE Committee and TCIC.
	180 CFS	Rising	4.4 mph	Strong Current	Watch	Lockmaster contacts MSU Paducah. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). SCC will initiate Safety Advisory (Enc. 1).
	200 CFS	Rising	4.6 mph	Strong Current	Watch	Safety Advisory in effect. Notify ICE Committee and TCIC. Discuss horsepower and tow size recommendations.
	220 CFS	Rising	4.8 mph	Extreme Strong Current	Action	Safety Advisory in effect. Hold ICE Committee and TCIC conference call. Consider need for assist vessel on stand-by when reaching 220 CFS.
	240 CFS and above	Rising	5.0 mph or greater	Extreme Strong Current	Action	Lockmaster contacts CG MSU Paducah. Safety Advisory in effect. Consider ICE Committee and TCIC meeting. Consider implementation of assist vessel.
	220 CFS	Falling	4.8 mph	Extreme Strong Current	Action	Safety Advisory in effect. Notify ICE Committee and TCIC. Consider need for assist vessel on stand-by when reaching 220 CFS.
	200 CFS	Falling	4.6 mph	Strong Current	Recovery	Safety Advisory in effect. Notify ICE Committee and TCIC. Discuss horsepower and tow size recommendations.
	180 CFS	Falling	4.4 mph	Strong Current	Recovery	Lockmaster contacts CG MSU Paducah. Cancel Safety Advisory (Enc. 1). Notify ICE Committee and TCIC.
	160 CFS	Falling	4.2 mph	Normal Operations	Recovery	Notify ICE Committee and TCIC.
140 CFS and below	Falling	4.0 mph	Normal Operations	Recovery	Operations Normal. TVA, CG, Industry chairman, & USACE monitor CFS rates.	

TENNESSEE RIVER – I-24 BRIDGE & 62 / 641 BRIDGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE I-24 BRIDGE AND THE 62 / 641 BRIDGE, TENNESSEE RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE WHEN NAVIGATING IN THIS AREA. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

4.C. Tennessee River Action Plan

4.C.2. Kentucky Lock & Dam Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>KENTUCKY LOCK & DAM</p> <p>TENNESSEE RIVER MILE MARKERS: 22.4</p> <p>REFERENCE GAUGE: KENTUCKY LOCK AND DAM LOWER GAUGE.</p> <p>OTHER USEFUL DATA: THIS CHART USES THE KENTUCKY LOCK AND DAM LOWER GAUGE. THE GAUGE IS GIVEN IN FEET ABOVE SEA LEVEL. TO DETERMINE DEPTH OVER MITER SILL ADD THE STAFF GAUGE READING + 289 FEET. 289 FEET = THE MITER SILL ELEVATION ABOVE SEA LEVEL. WHEN THE STAFF GAUGE REACHES 11 FEET VESSEL MAY BE RESTRICTED FROM ENTERING LOCK CHAMBER DUE TO LOW WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	302' & above 13ft	Falling	Normal Operations	Watch	Lock Operations Normal
	301' 12ft	Falling	Low Water	Watch	Lockmaster contacts MSU Paducah. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	300' 11ft	Falling	Low Water	Watch	Safety Advisory in effect. Notify ICE Committee and TCIC. Note: Vessels exercise caution at MM 17.0 TNR due to low water. When the staff gauge falls to or below 11' vessels may be restricted from entering the lock chamber based on draft and water level.
	299' 10ft	Falling	Extreme Low Water	Action	Safety Advisory in effect. Hold ICE Committee and TCIC conference call. Discuss draft and tow size recommendations. Limited locking ability based on vessel s draft. Note: At Kentucky lock & dam one foot of clearance over the miter sill is required for vessels to enter and exit lock chambers.
	298' 9ft	Falling	Restrict Lock Operations	Action	Lockmaster contacts CG MSU Paducah. Hold ICE Committee and TCIC meeting. Limited locking ability based on vessel s draft. Consider need for Safety Zone (Enc. 2) for lower TNR.
	297' and below 8ft	Falling	Restrict Lock Operations	Action	MSU Paducah considers implementation of Safety Zone between MM 00.0 – MM 22.4TNR.
	297' and below 8ft	Rising	Restrict Lock Operations	Recovery	Consider need for Safety Zone between MM 00.0 – MM 22.4TNR. Manage vessel traffic on a case-by-case basis.
	298' 9ft	Rising	Restrict Lock Operations	Recovery	Lockmaster contacts MSU Paducah. Notify ICE Committee and TCIC. Limited locking ability based on vessel s draft. Consider lifting Safety Zone for lower TNR; re-issue Safety Advisory.
	299' 10ft	Rising	Extreme Low Water	Recovery	Lockmaster contacts MSU Paducah. Notify ICE Committee and TCIC. Limited locking ability based on vessel s draft. MSU Paducah requests SCC cancel Safety Zone (Enc. 2), if implemented, and issue Safety Advisory (Enc. 1).
	300' 11ft	Rising	Extreme Low Water	Recovery	Safety Advisory in effect. Notify ICE Committee and TCIC. Vessels exercise caution MM 17.0 TNR.
	301' 12ft	Rising	Low Water	Recovery	Lockmaster contacts MSU Paducah. Cancel Safety Advisory (Enc. 1).
302' & above 13ft	Rising	Normal Operations	Watch	Lock Operations Normal.	

TENNESSEE RIVER – KENTUCKY LOCK & DAM

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF KENTUCKY LOCK AND DAM. VESSELS TRANSITING THE KENTUCKY LOCK AND DAM VICINITY ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE KENTUCKY LOCK AND DAM VICINITY. RIVER LEVELS IN THE KENTUCKY LOCK AND DAM VICINITY ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ADVERTISED NAVIGABLE DRAFT IS 9'0". MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE TENNESSEE RIVER FROM MILE MARKER _____ TO MILE MARKER _____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY THE U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT IN THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.C. Tennessee River Action Plan

4.C.3. Kentucky Lock & Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>KENTUCKY LOCK & DAM</p> <p>TENNESSEE RIVER MILE MARKER: 22.4</p> <p>FLOOD STAGE READING: REFERENCE GAUGE: KENTUCKY LOCK AND DAM LOWER GAUGE.</p> <p>OTHER USEFUL DATA: THIS CHART USES THE KENTUCKY LOCK AND DAM LOWER GAUGE. THE GAUGE IS GIVEN IN FEET ABOVE SEA LEVEL. ADD THE ACTUAL STAFF GAUGE READING + 289 FEET TO DETERMINE THE GAUGE READING. MONITOR TVA FLOW RATES. REFERENCE PADUCAH GAUGE (335) & KENTUCKY LOCK & DAM LOWER GAUGE (334).</p> <p>USACE GAUGE READINGS REPORT</p>	302' 13ft	Rising	Normal Operations	Watch	Locking Operations Normal.
	335'	Rising & projected to continue rising rapidly	High Water	Watch	Lockmaster contacts MSU Paducah. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	340'	Rising	High Water	Action	Safety Advisory in effect. Consider ICE Committee and TCIC conference call.
	341' 1ft height of guard wall remaining.	Rising	Extreme High Water	Action	Lockmaster contacts MSU Paducah. Safety Advisory in effect. Hold ICE Committee and TCIC conference call. Consider assist vessel on stand-by for up-bound. 1ft height of guide wall remaining.
	342' Top of guard wall submerged	Rising	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. Kentucky L&D may cease locking vessels. Hold ICE Committee and TCIC meeting. Consider assist vessel on stand-by for up-bound. MSU Paducah considers implementation of Safety Zone (Enc. 2). Vessels will experience delays.
	342' & above	Rising	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. Kentucky L&D ceases locking vessels. Hold ICE Committee and TCIC meeting. MSU Paducah requests SCC initiate Safety Zone (Enc. 2) and cancel Safety Advisory (Enc. 1). USACE may buoy guide wall. Note: When the upper gauge reaches 374 feet Kentucky L&D closes due to debris in gate gears.
	342' Top of guard wall submerged	Falling	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. Kentucky L&D ceases locking vessels. CG MSU Paducah considers cancellation of Safety Zone.
	341' 1ft height of guard wall remaining.	Falling	Resume Locking Ability	Recovery	Lockmaster contacts MSU Paducah. Kentucky L&D resumes locking vessels. Hold ICE Committee Meeting. SCC cancels Safety Zone (Enc 2); if implemented and re-issues Safety Advisory (Enc 1); indicate high water, report hazardous conditions to Coast Guard.
	340'	Falling	Extreme High Water	Recovery	Lockmaster contacts MSU Paducah. Safety Advisory in effect.
	335'	Falling	High Water	Recovery	Lockmaster contacts MSU Paducah. Cancel Safety Advisory (Enc. 1).
302' 13ft	Falling	High Water	Recovery	Locking Operations Normal.	

TENNESSEE RIVER – KENTUCKY LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF KENTUCKY LOCK AND DAM, MILE MARKER 22.4, TENNESSEE RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED A SAFETY ZONE AT KENTUCKY L/D MILE MARKER 22.4 TENNESSEE RIVER. THE KENTUCKY L/D HAS CEASED LOCKING. HIGH WATER CONDITIONS AND VESSEL WAKES HAVE CAUSED DAMAGE TO SURROUNDING STRUCTURES. VESSEL TRANSITS ARE CEASED UNTIL WATER CONDITIONS SUBSIDE AND DAMAGE CAN BE PREVENTED.

4.C. Tennessee River Action Plan

4.C.4. The Gorge High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p style="text-align: center;">THE GORGE</p> <p style="text-align: center;">TENNESSEE RIVER MILE MARKERS: 446.0 – 455.0</p> <p>OTHER USEFUL DATA: TABLE USES FLOWS THROUGH THE GORGE GIVEN IN THOUSANDS OF CUBIC FEET PER SECOND (CFS). CFS RATES CAN BE USED TO DETERMINE HAZARDOUS CONDITIONS / FLOWS. UNDER THESE CONDITIONS MARINERS SHOULD NAVIGATE AT SLOWEST SAFE SPEED. AREA MAY CONTAIN HIGH CURRENT CAUSING VESSELS TO EXPERIENCE UNEXPECTED SET RESULTING IN ADVERSE CONSEQUENCE.</p> <p>TVA GAUGE READINGS REPORT</p>	46,000 CFS	Rising	High Current	Watch	Operations normal. CG, TVA, USACE and TCIC chairman monitor CFS rates and begin holding conference calls as needed.
	75,000 CFS	Rising	High Current	Action	Lockmaster contacts the Sector Command Center. The Sector Command Center will initiate a BNM (Enc. 1), recommending commercial traffic transit through the Gorge during daylight hours only. TCIC holds conference call.
	90,000 CFS and above	Rising	Very High Current	Emergency	Lockmaster contacts the Sector Command Center. Chickamauga L&D ceases locking vessels. The Sector Command Center initiates a Safety Zone BNM (Enc. 2), ceasing navigation through the Gorge and cancels BNM (Enc. 1). TCIC holds conference call.
	below 90,000 CFS	Falling	High Current	Action	Lockmaster contacts the Sector Command Center. Chickamauga L&D resumes locking vessels. The Sector Command Center cancels Safety Zone BNM (Enc. 2) and reissues BNM (Enc. 1), recommending commercial traffic transit through the Gorge during daylight hours only. TCIC holds conference call.
	75,000 CFS	Falling	High Current	Action	Lockmaster contacts the Sector Command Center. The Sector Command Center cancels BNM (Enc. 1)
	46,000 CFS	Falling	Normal Operations	Recovery	Operations normal. CG, TVA, USACE and TCIC chairman monitor CFS rates.

TENNESSEE RIVER – THE GORGE

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcasts (BNM)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF THE TENNESSEE RIVER GORGE, MILE MARKER 446 TO MILE MARKER 455. HEAVY RAINFALL HAS CAUSED RELEASES FROM CHICKAMAUGA DAM, TNR MM 471, TO GO ABOVE 75,000CFS. IAW THE WATERWAY MANAGEMENT PLAN, IT IS RECOMMENDED THAT COMMERCIAL TRAFFIC TRANSIT THROUGH THE GORGE AREA DURING DAYLIGHT HOURS ONLY. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE WHEN NAVIGATING THIS AREA. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD. THIS ADVISORY WILL REMAIN IN EFFECT UNTIL CHICKAMAUGA DAM REDUCES FLOWS BELOW 75,000 CFS.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (BNM)

HEAVY RAINFALL HAS CAUSED RELEASES FROM CHICKAMAUGA DAM, TNR MM 471 TO GO ABOVE 90,000 CFS. IAW THE WATERWAY MANAGEMENT PLAN, THE USCG COTP OHIO VALLEY HAS ESTABLISHED A SAFETY ZONE ON THE TNR FROM MM 446 TO MM 455, EXTENDING THE ENTIRE WIDTH OF THE RIVER. NAVIGATION OF THE GORGE HAS CEASED BETWEEN THESE MILE MARKERS. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE USCG. CHICKAMAUGA LOCK IS NOW CLOSED DUE TO HIGH TURBULENCE AT MOORING CELLS. THIS SAFETY ZONE WILL REMAIN IN EFFECT UNTIL CHICKAMAUGA DAM REDUCES FLOWS BELOW 90,000 CFS.

4.D. Cumberland River Action Plan

4.D.1. Barkley Lock & Dam Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>BARKLEY LOCK & DAM</p> <p>CUMBERLAND RIVER MILE MARKER: 30.6</p> <p>OTHER USEFUL DATA: THIS CHART USES THE BARKLEY LOCK AND DAM LOWER GAUGE. THE GAUGE IS GIVEN IN FEET ABOVE SEA LEVEL.</p> <p>TO DETERMINE DEPTH OVER MITER SILL ADD THE STAFF GAUGE READING + 289 FEET. 289 FEET = THE MITER SILL ELEVATION ABOVE SEA LEVEL.</p> <p>WHEN THE STAFF GAUGE REACHES 11 FEET VESSEL MAY BE RESTRICTED FROM ENTERING LOCK CHAMBER DUE TO LOW WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	302' & above 13ft over sill	Falling	Normal Operations	Watch	Lock Ops Normal.
	301' 12ft over sill	Falling	Low Water	Watch	Lockmaster contacts MSU Paducah. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1); indicate low water, exercise caution.
	300' 11ft over sill	Falling	Low Water	Watch	Lockmaster contacts MSU Paducah. Safety Advisory in effect. Note: When the staff gauge falls to or below 11' vessels may be restricted from entering the lock chamber based on draft and water level.
	299' 10ft over sill	Falling	Extreme Low Water	Action	Safety Advisory in effect. Hold ICE Committee and TCIC conference call. Discuss draft and tow size recommendations. Limited locking ability based on vessel s draft. Note: At Barkley lock & dam one foot of clearance over the miter sill is required for vessels to enter and exit lock chambers.
	298' 9ft over sill	Falling	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. Hold ICE Committee and TCIC meeting. Limited locking ability based on vessel s draft. Consider need for Safety Zone (Enc. 2) for lower CMR.
	297' 8ft over sill	Falling	Restrict Lock Operations	Action	MSU Paducah considers implementation of Safety Zone between MM 00.0 – MM 30.6 CMR.
	297' 8ft over sill	Rising	Restrict Lock Operations	Recovery	Consider need for Safety Zone between MM 00.0 – MM 30.6 CMR. Manage vessel traffic on a case-by-case basis.
	298' 9ft over sill	Rising	Restrict Lock Operations	Recovery	Lockmaster contacts MSU Paducah. Notify ICE Committee and TCIC. Limited locking ability based on vessel s draft. Consider lifting Safety Zone for lower TNR; re-issue Safety Advisory.
	299' 10ft over sill	Rising	Extreme Low Water	Recovery	Lockmaster contacts CG MSU Paducah. Notify ICE Committee and TCIC. Limited locking ability based on vessel s draft. SCC cancels Safety Zone (Enc 2); if implemented and re-issues Safety Advisory (Enc 1); indicate low water, exercise caution, detail draft & tow size recommendations.
	300' 11ft over sill	Rising	Low Water	Recovery	Safety Advisory in effect. Notify ICE Committee and TCIC. Vessels exercise caution on lower CMR.
	301' 12ft over sill	Rising	Low Water	Recovery	Lockmaster contacts MSU Paducah. Cancel Safety Advisory (Enc. 1).
302' & above 13ft over sill	Rising	Normal Operations	Watch	Lock Ops Normal.	

CUMBERLAND RIVER – BARKLEY LOCK & DAM

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER CONDITIONS IN THE VICINITY OF BARKLEY LOCK AND DAM. VESSELS TRANSITING THE BARKLEY LOCK AND DAM VICINITY ARE EXPERIENCING GROUNDINGS. UNTIL RIVER CONDITIONS STABILIZE, DRAWDOWN CONDITIONS ARE OCCURRING IN THE BARKLEY LOCK AND DAM VICINITY. RIVER LEVELS IN THE BARKLEY LOCK AND DAM VICINITY ARE NOT FORECASTED TO RISE SIGNIFICANTLY DURING THIS PERIOD. THE ADVERTISED NAVIGABLE DRAFT IS 9'0". MARINERS ARE ADVISED TO EXERCISE CAUTION WHILE TRANSITING THESE AREAS WITH DRAFTS GREATER THAN 9'0". MARINERS ARE ALSO ADVISED TO CONSIDER RISKS OF NAVIGATING LOW WATER WHEN PUSHING CERTAIN DANGEROUS CARGOES.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE CUMBERLAND RIVER FROM MILE MARKER _____ TO MILE MARKER _____ EXTENDING THE ENTIRE WIDTH OF THE RIVER DUE TO EXTREME LOW WATER CONDITIONS. COMMERCIAL VESSELS ARE PROHIBITED FROM ENTERING OR TRANSITING IN THIS SAFETY ZONE UNLESS PERMITTED BY U.S. COAST GUARD CAPTAIN OF THE PORT. COMMERCIAL VESSELS REQUESTING TO ENTER OR TRANSIT IN THIS SAFETY ZONE MUST CONTACT THE MSU PADUCAH COMMAND DUTY OFFICER FOR PERMISSION AT 1-270-994-7385.

4.D. Cumberland River Action Plan

4.D.2. Barkley Lock & Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING LOWER GAUGE	TREND	DESCRIPTION	PHASE	ACTION
<p>BARKLEY LOCK & DAM</p> <p>CUMBERLAND RIVER MILE MARKER: 30.6</p> <p>FLOOD STAGE READING: 345'</p> <p>OTHER USEFUL DATA: THIS CHART USES THE BARKLEY LOCK AND DAM LOWER GAUGE. THE GAUGE IS GIVEN IN FEET ABOVE SEA LEVEL ADD THE ACTUAL STAFF GAUGE READING + 289 FEET TO DETERMINE THE GAUGE READING. 289 FEET = THE MITER SILL ELEVATION ABOVE SEA LEVEL. MONITOR TVA FLOW RATES. FLOWS FROM CUMBERLAND RIVER INTO THE OHIO RIVER CAN POSE HAZARDOUS CONDITIONS.</p> <p>USACE GAUGE READINGS REPORT</p>	302'	Rising & continues to rise rapidly	Normal Operations	Watch	Locking Operations Normal.
	345'	Rising	High Water	Watch	Lockmaster contacts MSU Paducah. MSU Paducah will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1); indicate high water, exercise caution.
	350'	Rising	Extreme High Water	Watch	Safety Advisory in effect. Consider ICE Committee and TCIC conference call.
	351' 1ft height of guide wall remaining.	Rising	Extreme High Water	Watch	Lockmaster contacts MSU Paducah. Safety Advisory in effect. Hold ICE Committee and TCIC conference call. Consider assist vessel on stand-by for up-bound. 1ft height of guide wall remaining.
	352' Top of guide wall submerged	Rising	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. Barkley L&D may cease locking vessels. Hold ICE Committee and TCIC meeting. Consider assist vessel on stand-by for up-bound. MSU Paducah considers implementation of Safety Zone (Enc. 2). Vessels will experience delays. Note: At 352 feet on the upper gauge Barkley L&D closes due to debris in the gate gears.
	352' & above	Rising	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. Hold ICE Committee and TCIC meeting. MSU Paducah requests SCC initiate Safety Zone (Enc. 2) and cancel Safety Advisory (Enc. 1) USACE may buoy guide wall. Note: At 352 feet on the upper gauge Barkley L&D closes due to debris in the gate gears.
	352' Top of guide wall submerged	Falling	Restrict Lock Operations	Action	Lockmaster contacts MSU Paducah. MSU Paducah considers cancellation of Safety Zone.
	351' 1ft height of guide wall remaining.	Falling	Resume Locking Ability	Recovery	Lockmaster contacts MSU Paducah. Barkley L&D resumes locking vessels. Hold ICE Committee and TCIC conference call. SCC cancels Safety Zone (Enc 2); if implemented and re-issues Safety Advisory (Enc 1); indicate high water, report hazardous conditions to Coast Guard.
	350'	Falling	Extreme High Water	Recovery	Lockmaster contacts CG MSU Paducah. Safety Advisory in effect. Consider ICE Committee and TCIC conference call.
	345'	Falling	High Water	Recovery	Lockmaster contacts MSU Paducah. Cancel Safety Advisory (Enc. 1).
302' 13ft	Falling	Normal Operations	Recovery	Locking Operations Normal.	

CUMBERLAND RIVER – BARKLEY LOCK & DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF BARKLEY LOCK AND DAM, MILE MARKER 30.6, CUMBERLAND RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAK-AWAYS TO THE U.S. COAST GUARD.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE AT BARKLEY LOCK AND DAM, MILE MARKER 30.6, CUMBERLAND RIVER. THE BARKLEY LOCK AND DAM HAS CEASED LOCKING. HIGH WATER CONDITIONS AND VESSEL WAKES HAVE CAUSED DAMAGE TO SURROUNDING STRUCTURES. VESSEL TRANSITS ARE CEASED UNTIL WATER CONDITIONS SUBSIDE AND DAMAGE CAN BE PREVENTED.

4.E. Allegheny River Action Plan

4.E.1. Lock 4 Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>LOCK 4 ALLEGHENY RIVER MILE MARKER: 24.2</p> <p>FLOOD STAGE READING: 18' UG</p> <p>OTHER USEFUL DATA: NORMAL POOL 10.1' ON UG & 9' LG</p> <p>TABLE USES LOWER GAUGE READINGS TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL GROUNDINGS INCREASES AS THE WATER FALLS.</p> <p>USACE GAUGE READINGS REPORT</p>	9.8' LG	Falling	Normal Operations/ Flow Conditions		Locking operations normal
	9.8' - LG	Falling & projected to continue falling rapidly	Low Water/ Low Flow Conditions	Watch	Consider for low water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1).
	9.8+ LG	Rising	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 2).

ALLEGHENY RIVER – LOCK 4

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER / LOW FLOW CONDITIONS AT DAM FOUR, MILE MARKER 24.2, ALLEGHENY RIVER. THE LOWER GAUGE AT DAM FOUR READS LESS THAN 9.8 FEET. PROCEED WITH CAUTION AND REMAIN IN THE NAVIGABLE CHANNEL DUE TO DECREASING WATER LEVELS. ALL VESSELS MUST MONITOR CHANNEL DEPTHS AND ENSURE THAT ADEQUATE WATER EXISTS FOR THEIR VESSEL DRAFTS. REPORT ALL GROUNDINGS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO RISING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.E. Allegheny River Action Plan
4.E.2. Lock 7 High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p align="center">LOCK 7</p> <p>ALLEGHENY RIVER MILE MARKER: 45.7</p> <p>FLOOD STAGE READING: 17' UG</p> <p>OTHER USEFUL DATA: NORMAL POOL 9' ON UG & LG</p> <p>TABLE USES UPPER GAUGE READINGS TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL ALLISIONS WITH LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENTS INCREASE.</p> <p><u>USACE GAUGE READINGS REPORT</u></p>	16' UG	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	16+ UG	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley Command Center will initiate a Safety Advisory (Enc. 1). Note: Cease locking at 17' on upper gauge.
	16' UG	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 2).

ALLEGHENY RIVER – LOCK 7

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT DAM SEVEN MILE MARKER 45.7 ALLEGHENY RIVER. THE UPPER GAUGE AT DAM SEVEN READS GREATER THAN 16 FEET. FLEETING FACILITIES ARE ADVISED TO (1) REVIEW AND ACT IN ACCORDANCE WITH THEIR WATERFRONT FLEET OPERATIONS GUIDE AND ANY COMPANY CONTINGENCY PLANS. (2) ASSIGN A PERSON TO BE IN CONTINUOUS SURVEILLANCE AND TO OBSERVE THE BARGES IN THE FLEETING FACILITY, (3) DOUBLE-UP THE LINES ON THE HEAD OF THE FLEET AND PROVIDE AN ADEQUATE NUMBER OF SPRING AND BREAST LINES BETWEEN THE DOCK AND THE BARGES IN THE FLEET, AND (4) REVIEW THEIR NEED TO SECURE TOWBOAT ASSISTANCE.

LOW WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD

4.F. Monongahela River Action Plan

4.F.1. Braddock Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>BRADDOCK LOCK AND DAM</p> <p>MONONGAHELA RIVER MILE MARKER: 11.3</p> <p>FLOOD STAGE READING: 22' UG</p> <p>OTHER USEFUL DATA: NORMAL POOL 12' ON UG & 16.8' ON LG MAX. DAM OPENING 42' CEASE LOCKING 19' UG</p> <p>TABLE USES UPPER GAUGE AND DAM OPENINGS TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL ALLISIONS WITH LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: SEVERE OUTDRAFT DURING HIGH WATER BY TURTLE CREEK ALONG UPPER GUIDE WALL</p> <p>CAUTIONARY NOTE 2: BRIDGE CLEARANCES AT FORT PERRY AROUND MM 11.6 RESTRICTED DURING HIGH WATER.</p> <p>USACE GAUGE READINGS REPORT</p>	15' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	15+ DAM	Rising &	High Water/ High Flow	Watch	Consider for high water conference calls. MSU
	OPENING	projected to continue rising rapidly	Conditions		Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	15 -' DAM OPENING	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1).
	12.5' UG	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	12.5'+ UG	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 2).
	12.5' - UG	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 2).

MONONGAHELA RIVER – BRADDOCK LOCK AND DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT BRADDOCK DAM, MILE MARKER 11.3, MONONGAHELA RIVER. THE GATE OPENING IS READING GREATER THAN 15 FEET. EXERCISE CAUTION WHILE TRANSITING UNDER THE MCKEESPORT-DUQUESNE HIGHWAY BRIDGE MILE MARKER 14.0 AND THE UNION RAILROAD BRIDGE MILE MARKER 14.2 DUE TO THE NARROW CHANNEL IN THAT AREA AND THE SHORT DISTANCE BETWEEN THESE TWO BRIDGES.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT BRADDOCK DAM MILE MARKER 11.3 MONONGAHELA RIVER. THE UPPER GAUGE AT BRADDOCK DAM READS GREATER THAN 12.5 FEET. EXERCISE CAUTION AND ENSURE VERTICAL CLEARANCE IS SUFFICIENT WHILE TRANSITING UNDER THE NORFOLK AND SOUTHERN BRIDGE MILE MARKER 11.7. WHEN THE UPPER GAUGE AT BRADDOCK DAM IS 12.5 FEET, THE VERTICAL CLEARANCE UNDER THIS BRIDGE IS 42.5 FEET.

HIGH WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.F. Monongahela River Action Plan

4.F.2. Lock and Dam 4 High/Low Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>LOCK AND DAM 4</p> <p>MONONGAHELA RIVER MILE MARKER: 41.5</p> <p>FLOOD STAGE READING: 28' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 10.5' ON UG & 10' ON LG MAX. DAM OPENING 80' CEASE LOCKING 12.5' UG</p> <p>TABLE USES UPPER AND LOWER GAUGE READINGS AND DAM OPENINGS TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL ALLISIONS WITH LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>USACE GAUGE READINGS REPORT</p>	8' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	8'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	35'+ DAM OPENING	Rising & projected to continue rising rapidly	Extreme High Water/Extreme High Flow Conditions	Action	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1). Issue Safety Advisory (Enc. 2).
	35'- DAM OPENING	Falling	High Water/ High Flow Conditions	Watch	Continue monitoring river conditions and consider canceling Safety Advisories.
	8'- DAM OPENING	Falling	Normal Operations/ Flow Conditions	Recovery	Locking operations normal.
	9.5' LG	Falling	Normal Operations/ Flow Conditions		Locking operations normal.
	9.5' - LG	Falling & projected to continue falling rapidly	Low Water/ Low Flow Conditions	Watch	Consider for low water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 4).
	9.5' + LG	Rising	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 4).

MONONGAHELA RIVER – LOCK 4

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT LOCK AND DAM 4, MILE MARKER 41.5 MONONGAHELA RIVER. THE GATE OPENING IS READING GREATER THAN 8 FEET. EXERCISE CAUTION WHILE DOUBLE LOCKING THROUGH LOCK 4.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT LOCK AND DAM 4 MILE MARKER 41.5 MONONGAHELA RIVER. THE GATE OPENING IS READING GREATER THAN 35 FEET. EXERCISE CAUTION WHILE TRANSITING THROUGH LOCK 4. EXERCISE CAUTION WHILE TRANSITING THROUGH THE AREA BETWEEN GREENFIELD BEND MILE MARKER 50 AND MAXWELL DAM MILE MARKER 61.2.

HIGH WATER Enclosure 3 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 4 (example)

Safety Marine Information Broadcast (Local Safety)

(NOTE: This BNM can be changed to reflect actual conditions and draft limitations)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER / LOW FLOW CONDITIONS AT LOCK AND DAM 4, MILE MARKER 41.5, MONONGAHELA RIVER. THE LOWER GAUGE READS LESS THAN 9.5 FEET (NOTE: The lower gauge reading may change to reflect actual conditions). PROCEED WITH CAUTION AND REMAIN IN THE NAVIGABLE CHANNEL DUE TO DECREASING WATER LEVELS. ALL VESSELS MUST MONITOR CHANNEL DEPTHS AND ENSURE ADEQUATE WATER EXISTS FOR THEIR VESSEL DRAFTS. VESSEL DRAFTS SHOULD NOT EXCEED ____ FEET (NOTE: Draft limitations will depend on the conditions). REPORT ALL GROUNDINGS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 5 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO RISING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.F. Monongahela River Action Plan

4.F.3. Maxwell Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>MAXWELL LOCK AND DAM</p> <p>MONONGAHELA RIVER MILE MARKER: 61.0</p> <p>FLOOD STAGE READING: 12' UG 31' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 9' ON UG & LG CEASE LOCKING 31' LG MAX. DAM OPENING 110'</p> <p>TABLE USES UPPER GAUGE TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL COLLISIONS WITH LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>USACE GAUGE READINGS REPORT</p>	15' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	15'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	15' - DAM OPENING	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1).

MONONGAHELA RIVER – MAXWELL LOCK AND DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT MAXWELL DAM, MILE MARKER 61.2, MONONGAHELA RIVER. THE GATE OPENING IS GREATER THAN 15 FEET. EXERCISE CAUTION WHILE TRANSITING THROUGH THE AREA BETWEEN GATES LIGHT MILE MARKER 76.1 AND GRAYS LANDING DAM MILE MARKER 82.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.F. Monongahela River Action Plan

4.F.4. Grays Landing Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>GRAYS LANDING LOCK AND DAM MONONGAHELA RIVER MILE MARKER: 82</p> <p>FLOOD STAGE READING: 17' UG</p> <p>OTHER USEFUL DATA: NORMAL POOL 9' ON UG & LG CEASE LOCKING 17' UG</p> <p>TABLE USES UPPER GAUGE TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL ALLISIONS WITH LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>CAUTIONARY NOTE 1: WHEN WATER LEVELS ARE EXPECTED TO REACH OR EXCEED 21' UG, ALL GATES ARE TIED BACK SO THAT WATER CAN FLOW FREELY</p> <p>USACE GAUGE READINGS REPORT</p>	15' UG	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	15' + UG	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	15' - UG	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1).

MONONGAHELA RIVER – GRAYS LANDING

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT GRAYS LANDING DAM MILE MARKER 82.0 MONONGAHELA RIVER. THE UPPER GAUGE AT GRAYS LANDING DAM READS GREATER THAN 15 FEET. FLEETING FACILITIES ARE ADVISED TO (1) REVIEW AND ACT IN ACCORDANCE WITH THEIR WATERFRONT FLEET OPERATIONS GUIDE AND ANY COMPANY CONTINGENCY PLANS, (2) ASSIGN A PERSON TO BE IN CONTINUOUS SURVEILLANCE AND TO OBSERVE THE BARGES IN THE FLEETING FACILITY, (3) DOUBLE-UP LINES ON THE HEAD OF THE FLEET AND PROVIDE AN ADEQUATE NUMBER OF SPRING AND BREAST LINES BETWEEN THE DOCK AND THE BARGES IN THE FLEET, AND (4) REVIEW THEIR NEED TO SECURE TOWBOAT ASSISTANCE.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.F. Monongahela River Action Plan

4.F.5. Point Marion Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>POINT MARION LOCK AND DAM MONONGAHELA RIVER MILE MARKER: 90.8</p> <p>FLOOD STAGE READING: 29' LG</p> <p>OTHER USEFUL DATA: NORMAL POOL 9' ON UG & LG CEASE LOCKING 11' UG MAX. DAM OPENING 33'</p> <p>TABLE USES UPPER GAUGE TO MONITOR RIVER CONDITIONS. THE POTENTIAL FOR VESSEL ALLISIONS WITH LOCK AND DAM TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES.</p> <p>USACE GAUGE READINGS REPORT</p>	20' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	20'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for high water conference calls. MSU Pittsburgh and/or WAPI will initiate a phone conference between CG, USACE and WAPI. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Pittsburgh will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	20' - DAM OPENING	Falling	Normal Operations/ Normal Flow Conditions	Recovery	Continue monitoring river conditions and consider canceling Safety Advisory (Enc. 1).

MONONGAHELA RIVER – GRAYS LANDING

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER / HIGH FLOW CONDITIONS AT POINT MARION DAM, MILE MARKER 90.8, MONONGAHELA RIVER. THE GATE OPENING AT POINT MARION DAM READS GREATER THAN 20 FEET. EXERCISE CAUTION WHEN TRANSITING THROUGH COBURN BEND BETWEEN MILE MARKERS 93 TO 95.

HIGH WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

CANCEL BNM _____ DUE TO FALLING WATER CONDITIONS. REPORT ANY HAZARDOUS CONDITIONS TO THE U.S. COAST GUARD.

4.G. Kanawha River Action Plan

4.G.1. Winfield Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>WINFIELD LOCK & DAM</p> <p>KANAWHA RIVER MILE MARKER: 31.1</p> <p>FLOOD STAGE READING: 46' LG Reference: WINFIELD DAM</p> <p>OTHER USEFUL DATA: MAX OPENING 110' GATES ALL OUT 35.5' LG CEASE LOCKING 39.8' LG</p> <p>TABLE USES DAM OPENING. THE POTENTIAL FOR VESSEL ALLISIONS WITH WINFIELD L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 30' OF GATE OPENING.</p> <p>USACE GAUGE READINGS REPORT</p>	<25'	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	25'+	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	40'	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, presence of ice, and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	40'-	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	25'-	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

KANAWHA RIVER – WINFIELD LOCK AND DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF WINFIELD LOCK AND DAM, MILE MARKER 31.1, KANAWHA RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF WINFIELD LOCK AND DAM, MILE MARKER 31.1, KANAWHA RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GUAGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.G. Kanawha River Action Plan

4.G.2. Marmet Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>MARMET LOCK & DAM KANAWHA RIVER MILE MARKER: 67.7</p> <p>FLOOD STAGE READING: 43' LG Reference: MARMET DAM</p> <p>OTHER USEFUL DATA: MAX OPENING 85' GATES ALL OUT 31' LG CEASE LOCKING 34' LG</p> <p>TABLE USES DAM OPENING. THE POTENTIAL FOR VESSEL ALLISIONS WITH MARMET L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 20' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 3: NEW LOCK CHAMBER UNDER CONSTRUCTION LANDWARD OF PRESENT CHAMBERS.</p> <p>USACE GAUGE READINGS REPORT</p>	<15.'	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	15.'+	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Consider for up river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	30.'	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, presence of ice, and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	30.'-	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	15.'-	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

KANAWHA RIVER – MARMET LOCK AND DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF MARMET LOCK AND DAM, MILE MARKER 67.7, KANAWHA RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF MARMET LOCK AND DAM, MILE MARKER 67.7, KANAWHA RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GUAGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.G. Kanawha River Action Plan

4.G.3. London Lock and Dam High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>LONDON LOCK & DAM KANAWHA RIVER MILE MARKER: 82.8</p> <p>FLOOD STAGE READING: 43' LG Reference: LONDON DAM</p> <p>OTHER USEFUL DATA: MAX OPENING 85' GATES ALL OUT 33' LG CEASE LOCKING 33' LG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH LONDON L&D TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBERS AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: DRIFT TENDS TO ACCUMULATE IN THE UPPER APPROACH.</p> <p>CAUTIONARY NOTE 2: OUTDRAFT IS SEVERE AT APPROXIMATELY 10' OF GATE OPENING.</p> <p>CAUTIONARY NOTE 3: DUE TO TOPOGRAPY, POOL LEVELS CAN RISE RAPIDLY.</p> <p>USACE GAUGE READINGS REPORT</p>	<15' DAM OPENING	Rising	Normal Operations/ Flow Conditions		Locking operations normal.
	15'+ DAM OPENING	Rising & projected to continue rising rapidly	High Water/ High Flow Conditions	Watch	Participate in river high water conference calls. MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. MSU Huntington will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	30' DAM OPENING	Rising	Extreme High Water/ Extreme High Flow Conditions	Action	MSU Huntington and/or HDWA will initiate a phone conference between CG, USACE and HDWA. Factors to evaluate include rate of rise, amount of drift, presence of ice, and weather conditions. In extreme ice conditions consider providing local Pilot knowledge of river characteristics.
	30'- DAM OPENING	Falling	High Water/ High Flow Conditions	Action	Continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	15'- DAM OPENING	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

KANAWHA RIVER – LONDON LOCK AND DAM

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF LONDON LOCK AND DAM, MILE MARKER 82.8, KANAWHA RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

LOW WATER Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT OHIO VALLEY HAS ISSUED THIS SAFETY ADVISORY DUE TO LOW WATER THAT EXISTS IN THE VICINITY OF LONDON LOCK AND DAM, MILE MARKER 82.8, KANAWHA RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH OBSTRUCTIONS THAT MAY IMPEDE SAFE PASSAGE IN THIS AREA DUE TO WATER DEPTHS OF LESS THAN NINE FEET. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. OPERATORS SHOULD REGULARLY CHECK RIVER DEPTHS TO GUAGE SAFE DRAFTS AND IMMEDIATELY REPORT GROUNDINGS TO THE U.S. COAST GUARD.

4.H. Green River Action Plan

4.H.1. Spottsville RR Bridge High Current Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>Spottsville RR Bridge GREEN RIVER MILE MARKER: 8.3</p> <p>Reference: Lock 1 LG & Newburgh L&D LG (Ohio River)</p> <p>OTHER USEFUL DATA:</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH SPOTTSVILLE RAILROAD BRIDGE ABUTMENTS TENDS TO INCREASE AS CURRENT INCREASES, SPECIFICALLY WHEN LOCK 1 LG (GREEN RIVER) IS TWO FEET OR HIGHER THAN NEWBURGH L&D LG (OHIO RIVER). VESSELS EXPERIENCE OUTDRAFT WHILE TRANSITING THE BRIDGE DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, PASS THE BRIDGE AT SLOWEST SAFE SPEED AND PREPARE FOR POTENTIAL OUTDRAFTS.</p>	Lock 1 LG is < 1' higher than Newburgh L&D LG	Green River rising	Normal Operations / Flow Conditions		Navigation operations normal.
	Lock 1 LG is > 1' higher than Newburgh L&D LG	Rising & difference between Green & Ohio River levels increasing	High Flow Conditions	Watch	Participate in high flow conference calls. Sector Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Encl. 1).
	Lock 1 LG is > 2' higher than Newburgh L&D LG	Green River levels 2' or higher than Ohio River levels.	High Flow Conditions	Action	Sector Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Factors to evaluate include rates of rise on Green and Ohio Rivers and weather conditions. Consider vessel restrictions including minimum horsepower per loaded barge, tow size limits or daylight operations. Consider establishing safety zone. Update safety advisory to reflect controls.
	Lock 1 LG is < 2' but >1' higher than Newburgh L&D LG	Difference between Green and Ohio River levels decreasing	High Flow Conditions	Watch	USACE, CG and/or CORMIG will initiate a phone conference. Factors to evaluate include river heights and weather conditions. Consider removing safety zone. Update safety advisory as appropriate.
	Lock 1 LG is < 1' higher than Newburgh L&D LG	Difference between Green and Ohio River levels decreasing	Normal Operations / Flow Conditions		Cancel safety zone if applicable. Cancel safety advisory. Navigation operations normal.

GREEN RIVER – Spottsville RR Bridge

High Current Conditions

Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH CURRENT THAT EXISTS IN THE VICINITY OF SPOTTSVILLE RAILROAD BRIDGE, MILE MARKER 8.3, GREEN RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING THE SPOTTSVILLE BRIDGE ABUTMENTS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE.

4.H. Green River Action Plan

4.H.2. Lock & Dam 1 High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>Lock 1 GREEN RIVER MILE MARKER: 9.1</p> <p>Reference: Lock 1 UG & LG</p> <p>OTHER USEFUL DATA: CEASE LOCKING 25.9' UG</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH L&D 1 TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES, SPECIFICALLY BETWEEN 16' AND 19' ON THE UPPER GAUGE. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION, ENTER CHAMBER AT SLOWEST SAFE SPEED, AND PREPARE FOR POTENTIAL OUTDRAFTS.</p>	<13' Upper Gauge	Rising	Normal Operations / Flow Conditions		Locking operations normal.
	13'+ Upper Gauge	Rising & projected to continue rising rapidly	High Water / High Flow Conditions	Watch	Participate in river high water conference calls. Sector Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Topics to discuss: water conditions, concerns, future actions, weather forecasts and river stages. Sector Ohio Valley will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	25.9' Upper Gauge	Rising	Max Locking Ability	Action	Sector Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Factors to evaluate include rate of rise and weather conditions. Lock ceases operations and vessels will experience delays. Consider river closure and identifying lay-up locations.
	> 33' Lower Gauge	Rising	Potential Weir Navigation	Action	USACE, CG and/or CORMIG will initiate a phone conference. Factors to evaluate include rate of rise and weather conditions. Consider implementing safety zone and one-way traffic. Consider tow size limitations and/or horsepower per tow limitations. Modify Safety Advisory (encl. 2) as appropriate.
	> 33' Lower Gauge	Falling	Potential Weir Navigation	Action	USACE, CG and/or CORMIG will initiate a phone conference to discuss factors for ceasing weir navigation, considering current, rate of fall, and weather conditions.
	25.9' Upper Gauge	Falling	High Water / High Flow Conditions	Action	Resume locking, continue conference calls, monitor conditions, and adjust restrictions as appropriate.
	<13' Upper Gauge	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

GREEN RIVER – Lock 1

Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF LOCK 1, MILE MARKER 9.1, GREEN RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE GREEN RIVER FROM MILE MARKER 8 TO MILE MARKER 10 IN THE VICINITY OF LOCK 1. THIS SAFETY ZONE INCLUDES THE CLOSURE OF LOCK AND DAM ONE DUE TO HIGH WATER WITH THE UPPER GAUGE READING 25.9 FEET. [Optional text for weir navigation: VESSELS WITH 9'0" DRAFT AND ADEQUATE HORSEPOWER ARE AUTHORIZED NAVIGATION OVER THE WEIR.]

4.H. Green River Action Plan

4.H.3. Lock & Dam 2 High Water Operations

CRITICAL AREA DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
<p>Lock 2 GREEN RIVER MILE MARKER: 63.1</p> <p>Reference: Lock 2</p> <p>OTHER USEFUL DATA:</p> <p>CEASE LOCKING ANYWHERE BETWEEN 21.3 AND 22.5 UG DEPENDING ON CONDITIONS.</p> <p>THE POTENTIAL FOR VESSEL ALLISIONS WITH L&D 2 TENDS TO INCREASE AS WATER RISES AND CURRENT INCREASES, SPECIFICALLY BETWEEN 16' AND 19' ON THE UPPER GAUGE. VESSELS EXPERIENCE OUTDRAFT WHILE APPROACHING LOCK DOWNBOUND. MARINERS ARE ADVISED TO EXERCISE EXTREME CAUTION AND PREPARE FOR POTENTIAL OUTDRAFTS.</p> <p>CAUTIONARY NOTE 1: Mariners are advised to hug the right descending bank when approaching downbound.</p> <p>CAUTIONARY NOTE 2: Outdrafts are particularly strong beginning at 18' UG. Downbound mariners may need to push hard to get into the gate and then back off upon reaching the gate to prevent being overcome by outdrafts.</p>	<13' Upper Gauge	Rising	Normal Operations / Flow Conditions		Locking operations normal.
	13'+ Upper Gauge	Rising & projected to continue rising	High Water / High Flow Conditions – Outdraft starts	Watch	Sector Ohio Valley and/or CORMIG will initiate a phone conference. Topics to discuss: water conditions, concerns, future actions, weather and river stage forecasts. Sector Ohio Valley will submit a Safety Advisory request to the Sector Command Center (SCC). The SCC will initiate a Safety Advisory (Enc. 1).
	18'+ Upper gauge	Rising	High water / High Flow - Severe Outdrafts	Action	Sector Ohio Valley and/or CORMIG will initiate a phone conference between CG, USACE and CORMIG. Factors to evaluate include rate of rise, weather conditions, number of barges in tow, configuration of boxed vs. raked barges. Consider tow size limitations and/or horsepower per tow limitations.
	21.3' – 22.5' Upper Gauge	Rising	Max Locking Ability	Action	USACE, CG and/or CORMIG will initiate a phone conference. Factors to evaluate: rate of rise/weather conditions. Lock ceases operations and vessels will experience delays. Consider river closure and identifying lay-up locations.
	> 25' Lower gauge	Rising	Potential Weir Navigation	Action	USACE, CG and/or CORMIG will initiate a phone conference. Factors to evaluate include rate of rise and weather conditions. Consider implementing safety zone and one-way traffic. Consider tow size limitations and/or horsepower per tow limitations.
	> 25' Lower Gauge	Falling	Potential Weir Navigation	Action	USACE, CG and/or CORMIG will initiate a phone conference to discuss factors for ceasing weir navigation, considering current, rate of fall, and weather conditions.
	21.5' - 23' Upper Gauge	Falling	High Water / High Flow Conditions	Action	Resume locking, continue conference calls, monitor conditions, and adjust restrictions.

	< 18' Upper gauge	Falling	High water / High Flow - Outdrafts	Recovery	Continue conference calls, monitor conditions, and adjust restrictions.
	<13' Upper Gauge	Falling	Normal Operations / Normal Flow Conditions	Recovery	Continue monitoring river conditions and cancel Safety Advisory (Enc. 1).

GREEN RIVER – Lock 2

HIGH WATER Enclosure 1 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ISSUED THIS SAFETY ADVISORY DUE TO HIGH WATER THAT EXISTS IN THE VICINITY OF LOCK 2, MILE MARKER 63.1, GREEN RIVER. MARINERS ARE ADVISED TO EXERCISE CAUTION DUE TO THE HAZARDOUS CONDITIONS ASSOCIATED WITH STRONG CURRENTS, INCREASED DRIFT, AND SEVERE OUTDRAFTS. WHEN NAVIGATING LOCK CHAMBERS, MARINERS ARE ADVISED TO CONSIDER HORSEPOWER CAPABILITY AND TOW SIZE. FLEET OPERATORS SHOULD REGULARLY CHECK THEIR FLEETS AND IMMEDIATELY REPORT BARGE BREAKAWAYS TO THE U.S. COAST GUARD.

Enclosure 2 (example)

Safety Marine Information Broadcast (Local Safety)

THE U.S. COAST GUARD CAPTAIN OF THE PORT HAS ESTABLISHED A SAFETY ZONE ON THE GREEN RIVER FROM MILE MARKER 62 TO MILE MARKER 64 IN THE VICINITY OF LOCK 2. THIS SAFETY ZONE INCLUDES THE CLOSURE OF LOCK AND DAM 2 DUE TO HIGH WATER WITH THE UPPER GAUGE READING XX FEET. [Optional text for weir navigation: VESSELS WITH 9'0" DRAFT AND ADEQUATE HORSEPOWER ARE AUTHORIZED NAVIGATION OVER THE WEIR.]

4.I. Ice Conditions: ALL ZONES

CRITICAL REACH DESCRIPTION	TRIGGER READING	TREND	DESCRIPTION	PHASE	ACTION
ALL OHIO VALLEY ZONES	No Ice		Normal Operations		Corps distributes informational navigation notice in early winter, prior to ice season.
	Ice Build-Up in Channel and Sheet Ice Formation	Predicted weather forecast indicates extreme temperatures. Ice buildup begins in the creeks and tributaries.	Mariners consulting with lock masters for indications of ice buildup. Ice Interferes with Normal Navigation. Sheet ice will at times prevent opening of the upper and lower lock gates. When the lock gates cannot be fully opened into recesses, they are highly vulnerable to extensive damage from tows entering or departing the lock chamber.	Watch	Consider advisories on missing buoys and safety zone restriction for tow width and length. Ice couplings for entering locks. Single-file traffic in ice-narrowed channels. Navigators are cautioned to exercise extreme care when entering or departing the lock chamber to avoid damage to the lock gates. When ice builds up to the extent that full usage of the lock chamber is prohibited, length and/or width restrictions may be imposed on lockages.
	Heavy Ice Gorges	Prolonged extreme temp.	Channel blocked in some locations. Gorged ice becomes a particular hazard when attempts are made to drive barges through the formation. Barges forced through or over gorged ice may be damaged.	Action	Consider river closure, restriction of types of traffic, or allow single lane traffic in open areas only. Navigators are advised to exercise due caution to avoid damaging barges and unusual currents and high localized flow or out draft conditions due to water bypassing the temporary dam formed by the gorge. Navigators approaching an ice gorge should make certain that the towboat has sufficient power to properly control the number of barges in tow under such unusual conditions of flow.
	Rotting ice, increased flow softening ice	Rising temperatures and rain flushing ice out.	Ice softening, water noticeable on top of the ice flow, channel conditions improving, and ice receding from channel.	Recovery	ATON checks, locks and dams flush ice; lock personnel will notify USCG to release a broadcast prior to prolonged flushing at the locks.

5. Drift Removal Procedures

5.A. Huntington District Drift Removal Procedures

During high river flow conditions both the USACE and navigation industry are challenged with drift and debris accumulation at locks on the Ohio River. In addition to river topography, variables such as pool stage, wind direction and wind velocity largely influence the accumulation and removal of drift from the approaches, fore bays and chambers of the locks. The primary methods of drift removal are by locking and flushing it through the lock chamber(s) but this is dependent upon the design and capabilities of each individual lock. The following guidance was prepared to communicate the expected drift removal practices and expectations for each lock within the Huntington District. They are guidelines only.

The characterization of drift accumulation at locks as “light”, “moderate” and “heavy” is not an absolute determination. It is rather a qualitative comparison of drift accumulation observations over the years by a number of experienced navigation industry representatives.

5.A.1. Willow Island Locks and Dam

(Light Drift Accumulation)

Light drift accumulates in the upper approach with a lower gage of less than 16.0’ and little wind. Drift will be passed using the valves in the auxiliary chamber.

Heavy drift accumulates in the upper approach with a lower gage of at least 20.0’ and little wind. Drift will be flushed with the auxiliary chamber emergency gate. It may be necessary to use the main chamber emergency gates to flush drift through the lock. Drift has a tendency to hang at the edge of the lower river wall at the line between the river’s flow and the slack water. When the wind is blowing upriver, it may not be possible to move the drift through the lock. Heavy drift does not accumulate typically until the dam openings are fully open in a rising river.

5.A.2. Belleville Locks and Dam

(Heavy Drift Accumulation)

Light drift accumulates in the upper approach with a lower gage of 12.0’ to 26.0’ and little wind. Drift will be passed using the valves in the auxiliary chamber.

When there is not sufficient lift to move the drift or the volume of the drift gets too great, two bulkheads are set in the auxiliary chamber using the bulkhead crane. Both upper and lower gates are then latched in the open position. Drift is flushed by leaving the bottom bulkhead on the sill and raising the top bulkhead to clear the upper pool elevation. If the upper pool exceeds 14.0’ or 584 feet above sea level another bulkhead is added.

Drift has a tendency to hang at the edge of the lower river wall at the line between the river’s flow and the slack water. If you have an upriver wind and it is working against you, it may be impossible to get rid of the drift. Heavy drift does not accumulate typically until the dam openings are fully open in a rising river.

5.A.3. Racine Locks and Dam

(Heavy Drift Accumulation)

Light drift accumulates in the upper approach with a lower gage of less than 14.0’ and little wind. Drift will be passed using the valves in the auxiliary chamber.

Heavy drift accumulates in the upper approach with a lower gage of at least 33.0’ and little wind. Drift will be flushed with the auxiliary chamber emergency gate. It may be necessary to use the main chamber emergency gates to flush drift through the lock. Drift has a tendency to hang at the edge of the lower river wall at the line between the river’s flow and the slack water. When the wind is blowing upriver, it may not be possible to move the drift through the lock. Heavy drift does not accumulate typically until the dam openings are fully open in a rising river.

5.A.4. Robert C. Byrd Locks and Dam

(Light Drift Accumulation)

Due to the design and layout of the upper lock approach with regard to the dam and location of the filling intake system, this lock rarely has drift and debris accumulation within the lock approach.

Light drift can accumulate in the upper approach with a lower gage of less than 15.0' and little wind. Drift will be passed utilizing the valves in the auxiliary chamber.

The project is also equipped with emergency gates on both chambers to pass debris if needed.

5.A.5. Greenup Locks and Dam

(Heavy Drift Accumulation)

Light drift accumulates in the upper approach with a lower gage of less than 25.7' and little wind. Drift will be passed using the valves in the auxiliary chamber.

Heavy drift accumulates in the upper approach with a lower gage of at least 25.7' and little wind. Drift will be flushed with the auxiliary chamber emergency gate. It may be necessary to use the main chamber emergency gates to flush drift through the lock. Drift has a tendency to hang at the edge of the lower river wall at the line between the river's flow and the slack water. When the wind is blowing upriver, it may not be possible to move the drift through the lock. Heavy drift does not accumulate typically until the dam openings are fully open in a rising river.

5.A.6. Meldahl Locks and Dam

(Light Drift Accumulation)

Light drift accumulates in the upper approach with a lower gage of less than 35.0' and little wind. Drift will be passed using the valves in the auxiliary chamber.

Heavy drift accumulates in the upper approach with a lower gage of at least 40.6' and little wind. Drift will be flushed with the auxiliary chamber emergency gate. It may be necessary to use the main chamber emergency gates to flush drift through the lock. Drift has a tendency to hang at the edge of the lower river wall at the line between the river's flow and the slack water. When the wind is blowing upriver, it may not be possible to move the drift through the lock. Heavy drift does not accumulate typically until the dam openings are fully open in a rising river.

5.A.7. London Locks and Dam - (Kanawha River)

(Light Drift Accumulation)

Drift has to be dealt with promptly when it accumulates on the guard wall otherwise the barges will not lay flat on the wall. This complicates recoupling of tows and inhibits deck crew movement between barges.

Typically drift is pushed into the chamber by down bound tows and locked through with the tow. This clears the majority of the drift from the upper lock approach.

Drift can also be locked through the chamber by by-passing the valve-to-gate interlocks. The lock's emptying valves are utilized to draw the debris into the chamber. The filling valves are then opened to push the drift out of the chamber.

Under certain conditions, the roller dam gates can be utilized to draw the drift onto the dam. This does not clear any drift in the lock approach but may prevent additional drift from accumulating.

5.A.8. Marmet Locks and Dam - (Kanawha River)

(Light Drift Accumulation)

Marmet does not have a history with drift and debris accumulation. Should significant drift accumulation occur the lock's emptying valves could be used to draw the drift into the chamber followed by the filling valves

use to flush the drift out of the chamber. Given the lock's through-the-sill intake system, this procedure has not been proven.

5.A.9. Winfield Locks and Dam - (Kanawha River) *(Moderate Drift Accumulation)*

Usually drift and debris is pushed into the chamber by down bound tows and locked through with the tow. This will clear the majority of the drift from the upper approach.

Lock personnel utilize the subsurface air system to move the drift out of the miter gate recess to permit their full opening.

The emergency gate can also be used to pass drift through the 800' main chamber. Under most conditions, once the drift has passed through the lock chamber, the debris may linger in the lower approach.

5.B. Louisville District Drift Removal Procedures

During high river flow conditions both the USACE and navigation industry are challenged with drift and debris accumulation at locks on the Ohio River. In addition to river topography, variables such as pool stage, wind direction and wind velocity largely influence the accumulation and removal of drift from the approaches, fore bays and chambers of the locks. The primary methods of drift removal are by locking and flushing it through the lock chamber(s) but this is dependent upon the design and capabilities of each individual lock. The following guidance was prepared to communicate the expected drift removal practices and expectations for each lock within the Louisville District. They are guidelines only.

The characterization of drift accumulation at locks as "light", "moderate" and "heavy" is not an absolute determination. It is rather a qualitative comparison of drift accumulation observations over the years by a number of experienced navigation industry representatives.

5.B.1. Markland Lock *(Heavy Drift Accumulation)*

Light drift accumulates in the upper approach with a lower gage of 20.0' with little. Drift will be passed using the valves in auxiliary chamber.

Heavy drift accumulates in the upper approach with a lower gage of at least 43.0' and little wind. Drift will be flushed with the auxiliary chamber emergency gate. It may be necessary to use the main chamber emergency gates to flush drift through the lock. Drift has a tendency to hang at the edge of the lower river wall at the line between the river's flow and the slack water. When the wind is blowing upriver, it may not be possible to move the drift through the lock.

5.B.2. McAlpine Lock *(Light Drift Accumulation)*

McAlpine does not have a history with drift and debris accumulation. The dam gates do not sit closed for long periods of time as at other dams and the canal approach does not attract significant drift.

5.B.3. Cannelton Lock *(Heavy Drift Accumulation)*

Flushing drift at Cannelton is an infrequent occurrence - usually 2-3 times in an average year. It takes approximately 2-3 hours to flush drift out of the fore bay.

Flushing of drift is not triggered by any specific pool level but rather when there is sufficient accumulation to hazard northbound navigation traffic departing the lock. After 1600 and on weekends lock operators are

required to contact the lockmaster if drift is becoming a hazard to navigation. Flushing is accomplished by maintenance personnel through the auxiliary chamber.

5.B.4. Newburgh Lock

(Moderate Drift Accumulation)

Flushing drift at Newburgh occurs infrequently. When present in the approach lock personnel manage the drift as follows:

1. Advantageously utilize the wind, current, and cycling of the lock chambers to discharge drift.
2. Communicate with approaching tow boats advising them of the presence of drift.
3. Utilize the project's work boat to push drift through the chamber when feasible and safe to do so.
4. With a normal upper pool, place two emergency bulkheads in the auxiliary chamber.

5.B.5. John T. Myers Lock

(Light Drift Accumulation)

Drift is not a significant problem at JT Myers because the river bend at Highland Rocks just above the project directs most of it to the dam. Substantial drift is observed when the dam is in the all-out stage at 12.0' upper gage and 30.0' lower but it typically passes through the open dam gates.

Drift does not build up on the dam during higher flows from 100' to 270' dam opening because it gets sucked under and passes unassisted once the dam opening reaches 70'.

Drift can be flushed from the upper approach by setting the bulkheads above the auxiliary chamber but this is infrequently necessary.

5.B.6. Smithland Lock

(Light Drift Accumulation)

When drift accumulates in the upper approach, lock personnel open the upper gates and pin the top latch of the gate in the recess. With the filling valves closed and the interlock system bypassed, the emptying valves can be opened to draw the drift into the chamber. Once there, with the emptying valves closed and the upper gates unpinned and closed, the lower gates can be opened and pinned and the filling valves opened to flush the drift from the chamber.

The project's work boat can be used to work the drift into the chamber for locking through. The work boat can also be used to pull out large pieces of drift from the approach.

The river chamber is usually where most of the drift collects. Northbound towboats push it upstream as they leave and it flows around the end of the guard wall onto the dam.

Drift is flushed off the dam when running more than 15 feet of opening on a gate. One gate is opened with the adjacent two adjusted to draw the drift through the opened gate.

6. Risk Assessment

6.A. Casualty History by Location

FY 2003-2010 CAG Data				
River	Pool	# of Collisions	# of Allisions	# of Groundings
Monongahela River	MM0- Lock 2	0	10	13
	Lock 2	1	3	0
	Lock 3	0	2	3
	Lock 4	2	0	0
	Maxwell	1	6	2
Allegheny River	MM 0.0-6.7	0	0	1
	MM 6.7-14.5 Lock 2 Pool	0	1	0
	MM14.5 - 24.2 Lock 3 Pool	0	0	1
	MM24.2-30.4 Lock 4 Pool	0	0	0
	MM30.4-36.3 Lock 5 Pool	0	0	0
	MM36.3-45.7 Lock 6 Pool	0	0	0
	MM45.7-52.6 Lock 7 Pool	0	0	0
	MM52.6-62.2 Lock 8 Pool	0	0	0
	MM62.2 - 69 Lock 9 Pool	0	0	0
Ohio River	Emsworth	0	1	7
	Dashields	0	1	1
	Montgomery	0	12	6
	New Cumberland	1	2	5
	Pike Island	1	4	2
	Hannibal	0	6	3
	Willow	4	8	7
	Belleville	5	22	4
	Racine	3	19	12
	R.C.Byrd	0	5	21
	Greenup	1	4	7
	Meldahl	0	15	35
	Markland	0	5	24
	McAlpine	8	16	45
	Cannelton	2	21	34
	Newburgh	1	13	3
	J.T. Myers	0	2	2
	Smithland	0	8	3
	Lock 52	0	3	1
	Lock 53	2	5	1
Lock 53 to Cairo	1	4	4	
Upper Mississippi River	MM0.3 Cairo Point to Route 60	0	3	6
	MM1.3 Route 60 / 62 Bridge to Thebes	1	5	25
	MM43.2 Thebes Rail Road Bridge to Grays Point	2	3	5
	MM44.0-52.0 Grays Point to Chester	2	5	29

6. Risk Assessment

6.A. Casualty History by Location

FY 2003-2010 CAG Data				
River	Pool	# of Collisions	# of Allisions	# of Groundings
Lower Mississippi River	LMR Cairo to 109	4	4	17
Tennessee River	MM17.0-21.1 I-24 Bridge & Vicinity	0	2	3
	MM22.4-25.2 Kentucky Lock to Barkley Canal	1	2	6
	MM25.2-32 Barkley Canal to Smith Bay	0	0	0
	MM32-66.2 Smith Bay to RT 79 Bridge	0	5	2
	MM66.2-100.5 RT 79 Bridge to Johnsonville	0	1	3
	MM100.5-135 Johnsonville to Pickwick L & D	0	0	2
	MM135-180 Perryville to Cerro Gorde	0	1	1
	MM180-204.5 Cerro Gorde to Big Bend	0	1	5
	MM204.5-206.7 Big Bend to Pickwick L & D	0	7	14
	MM206.7-239 Pickwick to Krogers Island	0	0	2
	MM239-259 Krogers Island to Wilson	0	2	3
	MM259-275 Wilson to Wheeler	1	4	2
	MM275-305 Wheeler to Decatur	0	3	3
	MM305-349 Decatur to Guntersville	2	1	0
	MM349-386 Guntersville to B.B.Coomer Hwy	0	1	0
	MM386-424.5 B.B Coomer Hwy to Nickajack	1	2	0
	Nickajack to Chick including "The Gorge"	0	0	4
Cumberland River	Cumberland River canal	0	0	9
	Barkley Lock & Dam MM30.6-55	0	3	8
	Barkley Lock & Dam MM55-81.5	0	3	8
	Barkley Lock & Dam MM81.5-115	0	1	1
	Barkley Lock & Dam MM115 to Cheatham	1	2	5
	Cheatham to Old Hickory	0	14	5

6.B. Waterway Analysis

6.B.1. Tool Legend

Need for Precise Control	Navigational Complexity			Congestion	Casualty History (7 yr period)
	Obstructions to Nav	Channel Width (Full Banks)	Bend Radius		
High	Multiple Obstructions	Narrow (single passage)	sharp bend(>180 deg)	Traffic always present	>10
Medium	Single Obstruction	Medium (dual passage possible/likely)	gradual bend (btn 90 and 180 or	Traffic sometimes present	6<<10
Low	No Obstructions	Wide (more than 2 vsl passage possible)	no bend (>90 deg) or no river crossing	Traffic rarely present	<6

6.B.2. Risk Factors

6.B.2.a. Monongahela River

Location	Factors to Increase Likelihood of Casualty				Casualty History	Risk Score
	Obs to Nav	Channel Width	Bend Radius	Congestion		
MM0-Lock 2 Pool	High	High	High	High	High	600
Lock 2 Pool	Medium	High	Medium	High	Low	222
Lock 3 Pool	Low	High	Low	High	Low	204
Lock 4 Pool	High	Medium	Low	High	Low	213
Maxwell Pool	Low	High	High	High	Low	303

6.B.2. Risk Factors

6.B.2.b. Allegheny River

Location	Factors to Increase Likelihood of Casualty				Casualty History	Risk Score
	Obs to Nav	Channel Width	Bend Radius	Congestion		
MM 0.0-6.7	Low	Medium	Low	High	Low	114
MM 6.7-14.5 Lock 2 Pool	Low	Medium	Medium	High	Low	123
MM14.5 - 24.2 Lock 3 Pool	Low	Low	Medium	High	Low	114
MM24.2-30.4 Lock 4 Pool	Low	Medium	Medium	High	Low	123
MM30.4-36.3 Lock 5 Pool	Low	Low	Low	Medium	Low	15
MM36.3-45.7 Lock 6 Pool	Low	High	Medium	Low	Low	114
MM45.7-52.6 Lock 7 Pool	Low	Medium	Medium	Low	Low	24
MM52.6-62.2 Lock 8 Pool	Low	Medium	High	Medium	Low	123
MM62.2 - 69 Lock 9 Pool	Low	High	High	Low	Low	204

6.B.2. Risk Factors

6.B.2.c. Ohio River

Location	Factors to Increase Likelihood of Casualty				Casualty History	Risk Score
	Obs to Nav	Channel Width	Bend Radius	Congestion		
EMSWORTH POOL	Medium	Low	Medium	High	Low	123
DASHIELDS POOL	High	Medium	Medium	High	High	420
MONTGOMERY POOL	High	Medium	Medium	High	Low	222
NEW CUMBERLAND POOL	Medium	High	Medium	High	Medium	240
PIKE ISL POOL	Medium	High	Medium	High	Medium	240
HANNIBAL POOL	High	High	Medium	High	Medium	330
WILLOW POOL	High	High	Medium	High	Low	312
BELLEVILLE POOL	High	High	Medium	High	High	510
RACINE POOL	High	High	High	High	Medium	420
R.C.BYRD POOL	High	Medium	Medium	High	Medium	240
GREENUP POOL	Low	Low	Low	High	Medium	123
MELDAHL POOL	Low	Low	Medium	High	High	312
MARKLAND POOL	High	Low	High	High	High	501
MCALPINE POOL	Medium	Low	Medium	High	High	321
CANNELTON POOL	Low	Medium	Medium	High	High	321
NEWBURGH POOL	Low	Medium	Low	High	High	312
J. T. MYERS POOL	Medium	Medium	Medium	High	High	330
SMITHLAND POOL	Low	Low	Medium	High	High	312
LOCK52 POOL	High	High	Low	High	High	501
LOCK 53 POOL	High	High	Low	High	High	501
LOCK 53 TO CAIRO	High	High	Low	High	High	501

6.B.2. Risk Factors

6.B.2.d. Mississippi River

Location	Factors to Increase Likelihood of Casualty				Casualty History	Risk Score
	Obs to Nav	Channel Width	Bend Radius	Congestion		
MM52.0-44.0 CHESTER TO GRAYS POINT	Medium	Medium	Medium	High	High	330
MM44.0-43.2 GRAYS POINT TO THEBES RAIL BRIDGE	Medium	Medium	Low	High	High	321
MM43.2-1.3 THEBES TO ROUTE 60 / 62 BRIDGE	High	Medium	Medium	High	High	420
MM1.3-0.3 ROUTE 60 / 62 BRIDGE TO CAIRO POINT	High	Medium	Low	High	Medium	231
MM0.3-109 CAIRO TO MM 109	Medium	Medium	High	High	High	420

6.B.2. Risk Factors

6.B.2.e. Tennessee River

Location	Factors to Increase Likelihood of Casualty				Casualty History	Risk Score
	Obs to Nav	Channel Width	Bend Radius	Congestion		
MM17.0-21.1 (I-24 BRIDGE & VICINITY)	Low	High	Low	High	Low	204
MM22.4-25.2 (KENTUCKY LOCK TO BARKLEY CANAL)	Low	Low	Low	High	Medium	123
MM25.2-32 (BARKLEY CANAL TO SMITH BAY)	Low	Low	Low	Medium	Low	15
MM32-66.2 (SMITH BAY TO RT 79 BRIDGE)	Low	Medium	Low	Medium	Medium	42
MM66.2-100.5 (RT 79 BRIDGE TO JOHNSONVILLE)	Low	Medium	Low	Medium	Low	24
MM100.5-135 (JOHNSONVILLE TO PICKWICK L & D)	Low	Medium	Medium	Medium	Low	33
MM135-180 (PERRYVILLE TO CERRO GORDE)	Low	High	High	Medium	Low	213
MM180-204.5 (CERRO GORDE TO BIG BEND)	Low	High	High	Medium	Medium	231
MM204.5-206.7 (BIG BEND TO PICKWICK L & D)	Low	High	High	Medium	High	411
MM206.7-239 PICKWICK TO KROGERS ISLAND	Low	Low	Low	Medium	Low	15
MM239-259 KROGERS ISLAND TO WILSON	Low	High	Low	Medium	Low	114
MM259-275 WILSON TO WHEELER	Low	Low	Low	Medium	Medium	33
MM275-305 WHEELER TO DECATUR	Low	Medium	Low	Medium	Medium	42
MM305-349 DECATUR TO GUNTERSVILLE	Low	Medium	Medium	Low	Low	24
MM349-386 GUNTERSVILLE TO B.B COOMER HWY	Low	Medium	Low	Low	Low	15
MM386-424.5 B.B COOMER HWY TO NICKAJACK	Low	High	Medium	Low	Low	114
MM424.5-471 NICKAJACK TO CHICKAMAUGA	Low	High	High	High	Low	303

6.B.2. Risk Factors

6.B.2.f. Cumberland River

Location	Factors to Increase Likelihood of Casualty				Casualty History	Risk Score
	Obs to Nav	Channel Width	Bend Radius	Congestion		
MM0.0-30.6	Medium	High	Medium	Medium	Medium	150
MM30.6-55 BARKLEY LOCK TO ROCK CASTLE POINT	Low	High	Medium	Medium	High	321
MM55-81.5 ROCKCASTLE TO BEAR CREEK LT	Low	High	Medium	Medium	High	321
MM81.5-115 BEAR CREEK LT TO PALMYRA	Low	High	High	Medium	Low	213
MM115-148.7 PALMYRA TO CHEATHAM	Low	High	High	Medium	Medium	231
CHEATHAM TO OLD HICKORY	Medium	High	High	Medium	High	420