



Positive Pressure Test of Casing

Pumped in 5 bbl,
Pressure increased to
2500 psi



Bled off 5 bbl, Pressure
decreased to 0 psi




Negative Pressure Test of Casing

Plan: Partially replace mud with seawater, leaving seawater in choke & kill lines & drillpipe. Bleed off pressure on seawater to 0 psi.


Success – Bleed 5 bbl & stops, SI & no pressure

Failure – Bled 15 bbl & Built pressure when SI



Kick Detection

NO KICK



KICK

