

MSC Guidelines for Review of Suppression in galley ducts

Plan Review Guidance #: SOLAS-11

Effective Date	11/15/02
Regulations	<ul style="list-style-type: none"><input type="checkbox"/> SOLAS 2001 Cite: II-2/9.7.5.1.3<input type="checkbox"/> SOLAS 1974 Cite: II-2/32.1.9.3
Disclaimer	<p>These guidelines were developed by the Marine Safety Center staff as an aid in the preparation and review of vessel plans and submissions. They were developed to supplement existing guidance. They are not intended to substitute or replace laws, regulations, or other official policy by the Coast Guard or the International Maritime Organization. The responsibility to demonstrate compliance with all applicable laws and regulations still rests with the plan submitter. The Coast Guard and the U.S. Department of Transportation expressly disclaim liability resulting from the use of this document.</p>
Contact Information	<p>If you have any questions or comments concerning this document, please contact the Marine Safety Center by e-mail or phone. Please refer to the Plan Review Guidance #: SOLAS-11.</p> <p>E-Mail: Customerservicemsc@uscg.msc.mil Phone: (202) 366-6480</p>
Regulation Text	“...a fixed means for extinguishing a fire within the duct.”
Guidance	Fixed extinguishing systems should be sized to provide protection for the entire volume of ducting between the dampers required by 9.7.5.1.2.
Background	Given the large length of typical main galley ventilation ducts, it is necessary to clarify the extent of fixed extinguishing protection within the duct.