

MSC Guidelines for Review of Refrigerators

Plan Review Guidance #: SOLAS-37

Effective Date	11/15/2002
Regulations	<ul style="list-style-type: none">❑ SOLAS 2001 Cite: II-2/9.2.2.3.2.11❑ SOLAS 1974 Cite: II-2/26.2.2(11)
Disclaimer	<p>These guidelines were developed by the Marine Safety Center staff as an aid in the preparation and review of vessel plans and submissions. They were developed to supplement existing guidance. They are not intended to substitute or replace laws, regulations, or other official policy by the Coast Guard or the International Maritime Organization. The responsibility to demonstrate compliance with all applicable laws and regulations still rests with the plan submitter. The Coast Guard and the U.S. Department of Transportation expressly disclaim liability resulting from the use of this document.</p>
Contact Information	<p>If you have any questions or comments concerning this document, please contact the Marine Safety Center by e-mail or phone. Please refer to the Plan Review Guidance #: SOLAS-37.</p> <p>E-Mail: CustomerserviceMSC@uscg.msc.mil Phone: (202) 366-6480</p>
Regulation Text	<p>"(11) Auxiliary machinery spaces, cargo spaces, cargo and other oil tanks and other similar spaces of moderate fire risk: Refrigerated chambers."</p>
Guidance	<p>We expect detection and suppression to be installed within the type-11 refrigerator boundaries. If the type-11 refrigerated space is fully enclosed within a galley boundary then the additional door requirements normally required for galley boundaries are not expected. Otherwise, the type-11 boundary may enclose multiple refrigerated chambers with the exception of areas that will be normally manned or used for non-refrigerated storage. In which case, the non-refrigerated space should be categorized as a type-13. In cases where groups of spaces are enclosed within one category 11 boundary and an area falls into the above non-refrigerated category, the category 11 designation may be maintained so long as A-class boundaries are provided between the area in question and any refrigerated chamber and adequate escape is available for manned spaces (workshops, food prep areas, etc). Drawing #1 gives generic examples of acceptable arrangements.</p>
Background	<p>Walk-in, or non-portable, refrigerated spaces are essentially store-rooms, or, if used to process food stuffs, a work space. Portable refrigerated units such as a freestanding or built-into-the-wall appliance (refrigerators in cabins, type-9 pantries, etc) do not fall under this broad category. While SOLAS allows refrigerated spaces to be treated as type-11 spaces, it is unclear how to address fire suppression and detection for these spaces. Because a refrigerator is used to store combustibles, fire detection and suppression should be provided. Two arrangements in particular are of concern. The first is the SOLAS requirements for doors in galley boundaries (i.e., walk-in refrigerators located adjacent to or</p>

MSC Guidelines for Review of Refrigerators

Plan Review Guidance #: SOLAS-37

within a galley). In this case, walk-in refrigerators located entirely within the SFP boundary of the galley should not be required to meet the additional galley boundary door requirements. The second concern involves the arrangement of multiple walk-in refrigerators in a common type-11 boundary. While this arrangement would typically be acceptable because the spaces are adjacent and common-use, sometimes these refrigerators open into a common space or other area that could be used as non-refrigerated storage or a workshop. Because escape is generally not an issue from grouped or multiple walk-in refrigerators these common/other spaces should be protected as individual type-13 spaces.