

MSC Guidelines for Review of Navigation Bridge Visibility

Procedure Number: H2-25

Revision Date: 05/05/00

References

- a. 46 CFR Subchapter H Subpart 72.04 – Navigation Bridge Visibility
 - b. 46 CFR Subchapter I Subpart 92.03 – Navigation Bridge Visibility
 - c. SOLAS Regulation V/22
-

Disclaimer

These guidelines were developed by the Marine Safety Center staff as an aid in the preparation and review of vessel plans and submissions. They were developed to supplement existing guidance. They are not intended to substitute or replace laws, regulations, or other official Coast Guard policy guidance. The responsibility to demonstrate compliance with all applicable laws and regulations still rests with the plan submitter. The Coast Guard and the U. S. Department of Transportation expressly disclaim liability resulting from the use of this document.

Contact Information

If you have any questions or comments concerning this document, please contact the Marine Safety Center by e-mail or phone. Please refer to the Procedure Number: H2-25

E-mail: customerservicemsc@msc.uscg.mil

Phone: 202-366-6480.

General Review Guidance

Refer to references (a), (b) and (c) above.