


1. Crew had recovered drag and suspended above sorting table.

2. Drag contents were dropped and club bar resecured.

3. Crew was preparing to reset drag when 3/4" nylon line failed where eye had chafed on becket of tail block.

4. Drag fell, striking crewman on head.



 **U.S. Coast Guard**
Marine Safety Office,
Portland, Maine

This diagram was prepared as part of case number MC97003192, injury onboard a scallop dragger, March 4, 1997 off Stonington, Maine