



LINDA E Intact Profile




This sketch illustrates significant features on the LINDA E as the vessel appeared on December 11, 1998.

LINDA E Damage Profile




This sketch illustrates the most significant damage observed during the June 21, 2000 ROV Dive. No significant damage noted to port side of vessel.

LINDA E Damage Profile Close-Up



This sketch illustrates the most significant damage observed during the June 21, 2000 ROV Dive. No significant damage noted to port side of vessel.

LINDA E Damage Profile Dimensions



This sketch displays a few of the relevant dimensions of markings and damage observed during the June 21, 2000 ROV Dive.