

Ship Name: **ANTARES**
IMO Number: **7508532**
Date of Action: **09/02/2004**
Action Taken: **Detention**

Ship Type: **Bulk Carrier**
Flag: **Panama**
Class Society: **Bureau Veritas**
Recognized Security

Port: **Norfolk, Virginia**

Ship Management: Owners, Operators, or Managers
Cometa United Corp.
Rina Tradewood Shipping Company S.A.S
Charterers:
Blue Marine

<u>Code - Category</u>	<u>Description</u>
2550 - Maintenance of ship and equipment	Approximately 2 inches standing water located on deck in emergency fire pump room.
2550 - Maintenance of ship and equipment	Examined 7 fire hose with 3 failures.
0672 - EPIRB's for survival craft	EPIRB not mounted in location where able to float free.
1720 - Control of discharge of oil	No containment on fuel oil and libe oil vent piping.
2550 - Maintenance of ship and equipment	Several flame screens were cracked and bulked with residue.
1499 - Other (Prop. & Aux. Machinery)	Ground on 220 V feeder panel.
2550 - Maintenance of ship and equipment	Discovered 3 leaks on fire main piping and 2 leaks from valve stem (port and Stbd) aft of #1 hold.
1299 - Other (Load Lines)	Ladder leading up to anchor windlass STBD side needs repair approx. 2 feet from bottom both welds cracked/coming apart..
0117 - Continuous Synopsis Record	Provide original continuous synopsis record.
0610 - Lifeboats	Replace entire supply of ships liferings with approved life rings to satisfaction of class.
0710 - Fire prevention	Have class attest to replacement of fire suits prior to departure
0630 - Launch arrangt. for survival craft	Have class attest to replacement of hydrostatic release on STBD side liferaft.
0695 - Training/instruction manual	Have class attest to adequate supply and placement of SOLAS Training Manuals onboard prior to departure.
2550 - Maintenance of ship and equipment	Vessel required to have ISM audit from Recognized Organization approved by Flag State within 72 hours.

Ship Name: **ARGOLA** Ship Type: **Bulk Carrier**
IMO Number: **7343231** Flag: **Croatia**
Date of Action: **09/22/2004** Class Society: **Croatian Register of Shipping**
Action Taken: **Detention** Recognized Security

Port: **Corpus Christi, Texas** Ship Management: Owners, Operators or Managers
Argola Ltd.
Sartija Nautika D.O.O.
Charterers:
Trans Sea Transport Inc.

Deficiencies: Code - Category Description
2020 - Fire drills **Crew unable to demonstrate proficiency in a satisfactory fire drill.**

Ship Name: **HAMBURG CARRIER** Ship Type: **Bulk Carrier**
IMO Number: **8313336** Flag: **Antigua and Barbuda**
Date of Action: **09/16/2004** Class Society: **Det Norske Veritas**
Action Taken: **Detention** Recognized Security

Port: **Redwood City, California** Ship Management: Owners, Operators or Managers
Leo Shipping Co. Ltd
DT-Bereederungs BMGH & Co KG
Charterers
Pan Ocean Shipping Co. Ltd

Deficiencies: Code - Category Description
0699 - Other (Life Saving Appliances) **Portside lifeboat sheaves wasted.**
0610 - Lifeboats **Port lifeboat painter lines wasted.**
0650 - Lifebuoys **Lifebuoy grab lines wasted**
0615 - Rescue boats **Rescue boat will inoperable.**
0710 - Fire prevention **Fire hazard in forward boatswain's stores caused from spilled oil covering deck.**
0610 - Lifeboats **Bowsing blocks for port lifeboat wasted.**
0710 - Fire prevention **Fire hazard in fwd bos'n stores cause from spilled oil covering deck.**
0715 - Detection **Fire alarms (two) in engine room are covered /disabled.**

Ship Name: **KATERINA** Ship Type: **Bulk Carrier**
IMO Number: **8203361** Flag: **Malta**
Date of Action: **09/15/2004** Class Society: **Bureau Veritas**
Action Taken: **Detention** Recognized Security **Bureau Veritas**

Port: **Long Beach, California** Ship Management: Owners, Operators, Managers

machinery spaces has created a fire and slip hazard.

Ship Name: **MAGPIE** Ship Type: **Chemical Tankship**
IMO Number: **9192753** Flag: **Liberia**
Date of Action: **09/24/2004** Class Society: **American Bureau of Shipping**
Action Taken: **Detention** Recognized Security

Port: **Jacksonville, Florida**

Ship Management: Owners, Operators, or Managers
FHH Fonds NO. 5 Mt. Lutetia
Christian F. Ahrenkiel Gmbh & Co. KG.
Charterers
Maersk Tankers

Deficiencies: Code - Category Description
0615 - Rescue boats **STBD lifeboat inoperative, releasing mechanism inoperative.**

Ship Name: **STAR ALABAMA** Ship Type: **Bulk Carrier**
IMO Number: **8221777** Flag: **Norway**
Date of Action: **09/22/2004** Class Society: **Det Norske Veritas**
Action Taken: **Detention** Recognized Security

Port: **Houston, Texas**

Ship Management: Owners, Operators, or Managers
Grieg Shipping AS
Grieg Billabong AS
Charterers
Star Shipping

Deficiencies: Code - Category Description
0725 - Fixed fire extinguishing installation **Piping to stern fire hydrant is severely wasted. While testing main fire pump, stern fire hydrant completely broke off at the pipe**

Ship Name: **THOR KIRSTEN** Ship Type: **Containership**
IMO Number: **8702422** Flag: **Denmark**
Date of Action: **09/20/2004** Class Society: **Lloyd's Register of Shipping**
Action Taken: **Detention** Recognized Security

Port: **Ponce, Puerto Rico**

Ship Management: Owners, Operators, or Managers
CEC Ship Management A/S, Svendborg
Thor Rederi, A/S Svendborg
Charterers

Denmark

Deficiencies: Code - Category Description
0740 - Pumps **Emergency fire pump locate on the forecastle was inoperative.**
1730 - Oily-water separating **Oily Water Separator was inoperative.**

equipment

0750 - Fire prevention

Provide bolts and gasket for international shore connection.